

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21000835/UPA3Q2**Date:** 03/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993682
<b>Claimant Vehicle No :</b>	GBE9977Y	<b>Insured Vehicle No :</b>	GBK6187Z
Date of Loss:	13/01/2021	Nature of Claim:	TP
		Claim No:	9089616690SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBE9977Y</b>		
Make & Model:	FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT GLAZE (M)	Engine No:	263A50007509877
Reg. Date:	12/05/2016 (Man. Year: 2015)	Chassis No:	ZFA26300006B94717
Colour:	White	Odometer:	66008 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,810.80	1,438.92	371.88	20.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	150.00	250.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,210.80</b>	<b>1,588.92</b>	<b>621.88</b>	<b>28.13</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,250.00</b>		
<b>Nett Amount (\$\$)</b>	<b>2,210.80</b>	<b>1,250.00</b>	<b>960.80</b>	<b>43.46</b>
<b>+ Loss of Use (2.0 x S\$60.00/day) (\$\$)</b>		120.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>1,377.45</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>1,370.00</b>		

INSPECTION

Date of Assignment:	18/01/2021	
Date Inspected:	18/01/2021 Inspected At:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	2.0 days	

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR VIEW MIRROR LH	Cracked	1,142.80 F	*1,142.80 FL
2	1		*FRONT SIDE MIRROR COVER LH	Repair	212.00 F	*- FL
3	1		*FRONT DOOR GLASS LH	Pitted	456.00 F	*456.00 FL
					<b>Sub Total (\$\$)</b>	<b>1,810.80 1,598.80</b>
					<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00 159.88</b>
					<b>Total Parts (\$\$)</b>	<b>1,810.80 1,438.92</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	250.00	100.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	150.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>400.00</b>	<b>150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >