

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/AIG21000836/UGS3Q2

Date:

06/07/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700029672

Claimant Vehicle No : SLV3374T**Insured Vehicle No :**

GBG3073J

Date of Loss: 15/01/2021

Nature of Claim:

TP

Claim No:

3027238355SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLV3374T**

Make & Model: KIA CARENS, 1.7 D DCT 5DR FWD (A)

Engine No:

D4FDHH109488

Reg. Date: 28/12/2017 (Man. Year: 2017)

Chassis No:

KNAHU815VJ7193716

Colour: Brown

Odometer:

246579 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Grenlander 6 mm

Rear Left Side:

Grenlander 6 mm

Front Right Side: Grenlander 6 mm

Rear Right Side:

Grenlander 6 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,674.50	8,058.30	7,616.20	48.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,340.00	2,470.00	2,870.00	53.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,014.50	10,528.30	10,486.20	49.90
Approved Total (Overridden) (S\$)		8,400.00		

(S\$)	21,014.50	8,400.00	12,614.50	60.03
+ GST 7.00/7.00% (S\$)	1,471.02	588.00	883.02	60.03
Nett Amount (S\$)	22,485.52	8,988.00	13,497.52	60.03
+ Car Rental (8.0 x S\$83.00/day) (S\$)		664.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,654.00		

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 18/01/2021

Estimated Period of Repair: 6.0 days

Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	627.00 FL	*627.00 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
3	1		*FRONT BUMPER SIDE RETAINER N/S	Not Necessary	11.00 FL	*- FL
4	1		*N/S HEADLAMP	Scratched	1,559.00 FL	*1,558.00 FL
5	1		*N/S HEADLAMP BRACKET	Not Necessary	45.00 FL	*- FL
6	1		*N/S FRONT FENDER	Badly Dented	384.00 FL	*384.00 FL
7	1		*N/S FRONT FENDER INNER COWLING	Torn	67.00 FL	*67.00 FL
8	1		*SET N/S FRONT FENDER INNER COWLING CLIPS	Necessary	44.00 FL	*44.00 FL
9	1		*N/S FRONT FENDER WIND DEFLECTOR	Not Necessary	65.00 FL	*- FL
10	1		*N/S FRONT DOOR	Badly Dented	1,098.00 FL	*1,098.00 FL
11	1		*N/S FRONT DOOR OUTER CHROME MOULDING	Scratched	43.00 FL	*43.00 FL
12	1		*N/S FRONT DOOR OUTER HANDLE	Scratched	176.00 FL	*176.00 FL
13	1		*N/S FRONT DOOR OUTER HANDLE EXTENSION	Not Necessary	24.00 FL	*- FL
14	1		*N/S FRONT DOOR OUTER AUTO KEY LOCK	Not Necessary	358.00 FL	*- FL
15	1		*N/S FRONT DOOR OUTER KEY LOCK BUTTON	Scratched	55.00 FL	*55.00 FL
16	1		*N/S FRONT DOOR LOCK WITH ACTUATOR	Jammed / Shorted	239.00 FL	*239.00 FL
17	1		*N/S FRONT DOOR HINGE -TOP	Twisted	30.00 FL	*30.00 FL
18	1		*N/S FRONT DOOR HINGE -BOTTOM	Twisted	30.00 FL	*30.00 FL
19	1		*N/S FRONT DOOR CHECKER	Twisted	45.00 FL	*45.00 FL
20	1		*N/S FRONT DOOR POWER WINDOW MOTOR ASSY WITH BASE	Shorted	280.00 FL	*280.00 FL
21	1		*N/S FRONT DOOR REGULATOR	Jammed	210.00 FL	*210.00 FL
22	1		*N/S FRONT DOOR INNER TRIMBOARD	Not Necessary	875.00 FL	*- FL
23	1		*N/S FRONT DOOR FRONT PILLAR	Repair	1,788.00 FL	*- FL
24	1		*N/S FRONT DOOR WEATHERSTRIP	Twisted / Necessary	95.00 FL	*95.00 FL
25	1		*N/S FRONT DOOR FRAME STICKER -TOP	Necessary	11.00 FL	*11.00 FL
26	1		*N/S FRONT DOOR FRAME STICKER -BOTTOM	Necessary	12.00 FL	*12.00 FL
27	1		*N/S SIDE MIRROR ASSY	Cracked	589.00 FL	*589.00 FL
28	1		*N/S REAR DOOR	Bent / Warped	978.00 FL	*978.00 FL
29	1		*N/S REAR DOOR OUTER CHROME MOULDING	Not Necessary	53.00 FL	*- FL
30	1		*N/S REAR DOOR LOCK	Not Necessary	207.00 FL	*- FL
31	1		*N/S REAR DOOR HINGE -TOP	Not Necessary	30.00 FL	*- FL
32	1		*N/S REAR DOOR HINGE -LOWER	Not Necessary	30.00 FL	*- FL
33	1		*N/S REAR DOOR CHECKER	Not Necessary	34.00 FL	*- FL
34	1		*N/S ROCKER PANEL	Repair	1,729.00 FL	*- FL
35	1		*N/S REAR FENDER	Badly Dented	1,349.00 FL	*1,349.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*N/S REAR FENDER INNER COWLING	Not Necessary	202.00 FL	*- FL
37	8		*N/S REAR FENDER INNER COWLING CLIPS	Not Necessary	44.00 FL	*- FL
38	1		*REAR BUMPER	Repair	452.00 FL	*- FL
39	1		*N/S FRONT LOWER ARM	Bent	387.00 FL	*387.00 FL
40	1		*N/S FRONT SHOCK ABSORBER	Not Necessary	302.00 FL	*- FL
41	1		*N/S FRONT KNUCKLE ARM	Bent	311.00 FL	*311.00 FL
42	1		*N/S FRONT WHEEL BEARING	Necessary	214.00 FL	*214.00 FL
43	1		*N/S A PILLAR	Repair	1,786.00 FL	*- FL
44	1		*FRONT WINDSCREEN GLASS MOULDING	Not Necessary	82.00 FL	*- FL
45	1		*N/S FRONT 1/4 GLASS SEAL	Not Necessary	80.00 FS	*- FS
46	1		*N/S FRONT 1/4 GLASS SEALANT	Not Necessary	40.00 FS	*- FS
47	1		*N/S REAR 1/4 GLASS SEAL	Necessary	50.00 FS	*20.00 FS
48	1		*N/S REAR 1/4 GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
49	1		*FRONT WINDSCREEN GLASS SEALANT	Not Necessary	60.00 FS	*- FS
50	1		*FRONT WINDSCREEN GLASS INNER SPONGE SEAL	Not Necessary	40.00 FS	*- FS
51	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,375.00	8,947.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,700.50	888.70
Total Parts (S\$)	15,674.50	8,058.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	350.00	90.00
2	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS ,REMOVE AND RENEWAL OF THE NECESSARY PARTS ,TO PERFORM FINAL CHECKING AND TESTING	New	200.00	120.00
3	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	120.00	0.00
4	TO REMOVE AND REFIT LEFT FRONT FENDER QUARTER GLASS	New	100.00	60.00
5	TO TRANSFER OF LEFT BOTH DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	240.00	120.00
6	TO REMOVE AND REFIT LEFT REAR FENDER QUARTER GLASS	New	120.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	150.00	20.00
8	TO CHECK CENTRAL LOCKING FUNCTION	New	140.00	0.00
9	TO RENEW BOTH DOOR FRAME STICKER	New	100.00	0.00
10	TO UPHOLSTERY AND MAKE GOOD REPAIR TO CUSHION SEAT AND SEAT FRAME AND RECLINING MECHANISM }	New	120.00	80.00
11	TO DISMANTLE AND REFIT REAR SEAT ,BACKREST ,TRIMMING ,GARNISH ,ROOF-LINING ,SPEAKER SHELFBOARD ,CARPETING AND OTHER TO ENABLE BODY WORK REPAIR }	New	150.00	0.00
12	TO DISMANTLE AND REFIT INSTRUMENT DASHBOARD ,CHECK ELECTRICAL LIGHTINGS AND RE-RUN ,RE-ROUTE WIRE HARNESS	New	250.00	0.00
13	TO TRANSFER OF TYRE ,RIM AND ON WHEEL BALANCING	New	30.00	0.00
14	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	100.00	80.00
15	USING ONBOARD SCAN TOOL (OBD) PERFORM FULL ENGINE DIAGNOSTIC CHECK ,TO CONFIGURE AND CLEAR ,RESET SRS SERVICE LIGHT	New	250.00	0.00
16	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	0.00
17	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	900.00
18	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			5,340.00	2,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >