

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/III21000839/UPS3Q2

Date:

12/05/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MFL0005568_01

Claimant Vehicle No : SLA876S**Insured Vehicle No :**

YM8173S

Date of Loss: 18/01/2021

Nature of Claim:

TP

Claim No:

MFL2021D0000240

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLA876S**

Make & Model: HONDA VEZEL, 1.5 X HYBRID CVT (A)

Engine No: LEB5065143

Reg. Date: 22/02/2016 (Man. Year: 2015)

Chassis No: RU31115129

Colour: White

Odometer: 151228 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,582.40	3,737.04	4,845.36	56.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,670.00	1,420.00	45.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,672.40	5,407.04	6,265.36	53.68
Approved Total (Overridden) (S\$)		4,300.00		

Nett Amount (S\$)	11,672.40	4,300.00	7,372.40	63.16
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 18/01/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
Singapore 417883

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 May 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA876S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR O/S	Dented / Bent	966.20 F	*912.30 FL
2	1		*REAR DOOR FRAME BLACK STICKER O/S	Necessary	80.00 F	*80.00 FL
3	1		*REAR DOOR LOWER STICKER O/S	Necessary	68.00 F	*62.00 FL
4	1		*REAR DOOR INNER LOCK O/S	Shorted	399.50 F	*315.20 FL
5	1		*REAR DOOR INNER TRIM BOARD O/S	Not Necessary	681.00 F	*- FL
6	1		*REAR DOOR INNER RUBBER O/S	Necessary	211.30 F	*145.30 FL
7	1		*REAR FENDER O/S	Repair	1,049.20 F	*- FL
8	1		*REAR FENDER OUTER PROTECTOR O/S	Distorted	280.50 F	*180.20 FL
9	1		*REAR FENDER UNDER COVER O/S	Torn	265.10 F	*266.30 FL
10	1		*REAR BUMPER	Torn	845.20 F	*745.20 FL
11	1		*REAR BUMPER SIDE O/S	Torn	299.50 F	*299.50 FL
12	1		*ROCKER PANEL GARNISH O/S	Deformed	845.20 F	*645.30 FL
13	1		*REAR WHEEL HUB BEARING O/S	Damaged	650.50 F	*320.00 FL
14	1		*REAR SHOCK ABSORBER O/S	Not Necessary	311.20 F	*- FL
15	1		*SET REAR DOOR INNER TRIM BOARD CLIPS O/S	Not Necessary	50.00 FS	*- FS
16	1		*SET REAR FENDER UNDER COVER CLIPS O/S	Necessary	50.00 FS	*30.00 FS
17	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
18	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
19	1		*REAR SPORT RIM O/S	Cut / Bent	1,200.00 FS	*480.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,582.40	4,531.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	794.26
Total Parts (\$\$)	8,582.40	3,737.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
4	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	180.00	120.00
5	TO TRANSFER REAR DOOR MECHANISM	New	80.00	60.00
6	TO SPRAY RUST PROOFING	New	80.00	30.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	500.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	750.00
Gross Labour Cost (\$\$)			3,090.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >