

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000848/AGS3Q2

Date: 29/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070107511

Claimant
Vehicle No : SKA5864E **Insured Vehicle No :** SDE8380B

Date of Loss: 15/01/2021 Nature of Claim: TP Claim No: 5309215420SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA5864E	Engine No:	06336395N52B25AE
Make & Model:	BMW 523I, 2.5 (A)	Chassis No:	WBANE32080CM76109
Reg. Date:	26/01/2007 (Man. Year: 2006)	Odometer:	180726 km
Colour:	Blue		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,217.48	2,183.02	1,034.46	32.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	550.00	600.00	52.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,367.48	2,733.02	1,634.46	37.42
Approved Total (Overridden) (\$\$)		2,200.00		
(\$\$)	4,367.48	2,200.00	2,167.48	49.63
+ GST 7.00/7.00% (\$\$)	305.72	154.00	151.72	49.63
Nett Amount (\$\$)	4,673.20	2,354.00	2,319.20	49.63
+ Car Rental (4.0 x S\$120.00/day) (\$\$)		480.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		2,836.00		

INSPECTION

Date of Assignment: 25/01/2021

Date Inspected: 25/01/2021 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,592.00 FL	*1,592.00 FL
2	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	206.40 FL	*206.40 FL
3	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	106.00 FL	*- FL
4	1		*REAR BUMPER UNDERCOVER	Not Necessary	158.40 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	685.00 FL	*- FL
6	1		*REAR BUMPER CENTRE GUIDE	Deformed	149.40 FL	*149.40 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
8	1		*SET REAR BUMPER UNDER CLIPS	Not Necessary	30.00 FS	*- FS
9	2		*REVERSE SENSOR	Damaged	530.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,507.20	2,377.80
- List Item Discount on L Items 10.00/10.00% (S\$)	289.72	194.78
Total Parts (S\$)	3,217.48	2,183.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	500.00	250.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	500.00	250.00
3	TO CHECK WIRING	New	50.00	0.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			1,150.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >