

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000850/EPA3Q2
Date: 08/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070006576
Claimant Vehicle No :	SMK6309J	Insured Vehicle No :	SMR7553B
Date of Loss:	11/01/2021	Nature of Claim:	TP
		Claim No:	9466123543SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK6309J		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UHN8829
Reg. Date:	17/04/2019 (Man. Year: 2018)	Chassis No:	MMBSTA13AKH001161
Colour:	Red	Odometer:	23383 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,223.41	2,956.02	1,267.39	30.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,320.00	3,100.00	2,220.00	41.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,543.41	6,056.02	3,487.39	36.54
+ GST 7.00/7.00% (S\$)	668.04	423.92	244.12	36.54

Nett Amount (S\$)	10,211.45	6,479.94	3,731.51	36.54
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,337.94		

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 26/01/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY ,COMB ,RR RH	Not Necessary	257.95 FS	*- FS
3	1		*FACE ,RR BUMPER	Broken	575.96 FS	*575.96 FS
4	1		*BRACKET ,RR BUMPER ,RH	Broken	21.56 FS	*21.56 FS
5	1		*PANEL ,RR END	Dented	327.25 FS	*327.25 FS
6	1		*WEATHERSTRIP ,TRUNK LID	Not Necessary	120.89 FS	*- FS
7	1		*PANEL ,TRUNK LID	Dented	609.07 FS	*609.07 FS
8	1		*HINGE ,TRUNK LID ,RH	Not Necessary	156.31 FS	*- FS
9	1		*HINGE ,TRUNK LID ,LH	Not Necessary	156.31 FS	*- FS
10	1		*LATCH ,TRUNK LID	Not Necessary	167.86 FS	*- FS
11	1		*MARK ,THREE-DIA	Necessary	53.13 FS	*53.13 FS
12	1		*MARK ,ATTRAGE	Necessary	16.17 FS	*16.17 FS
13	1		*TRIM ,RR END	Not Necessary	50.82 FS	*- FS
14	1		*UNPAINTED BODYKITS	Broken	1,314.40 FS	*1,314.40 FS
15	1		*PANEL ,RR END	Repeated	327.25 FS	*- FS
16	4		*GROMMET ,RR END TRIM	Necessary	9.24 FS	*9.24 FS
17	4		*CLIP ,RR END TRIM	Necessary	9.24 FS	*9.24 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	4,223.41	2,956.02
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RELACE END PANEL	New	450.00	450.00
2	SPRAY PAINT WORK ON END PANEL	New	350.00	350.00
3	REPLACE REAR BUMPER ,BOOT ,END PANEL & AFFECTED AREA REPAIR ON REAR RH FENDER	New	2,250.00	900.00
4	PAINT WORK ON REAR BUMPER ,BOOT ,REAR RH FENDER ,END PANEL & BODY KIT	New	1,750.00	1,050.00
5	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	120.00
6	TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	0.00
7	TO APPLY BODY SEALANT	New	40.00	40.00
8	PERFORM RUST PREVENTION	New	40.00	0.00
9	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
11	TO SUPPLY C&C EMBLEM	New	50.00	40.00
Gross Labour Cost (S\$)			5,320.00	3,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >