

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD INV No. AC2103219

300 BEACH ROAD INV Date 10/05/2021

#17-04/07 THE CONCOURSE Reference CC4/LPC21000852/Kga3q2

SINGAPORE 199555 Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMW 5632T

Insured Veh. GBA 9238T

Claim No. 20/21/21/VC00/024147

Policy No. Z/20/VC00/106596

Accident Date 15/01/2021

Inspection Date 19/01/2021

| Description | Total |
|--------------------------------|--------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|-----|-------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|---------------------|------------------------|--|--|--|
| | LONPAC INSURAI | NCE BHD | Ref: | CC4/LPC21000852/Kga3q2 | | | |
| | 300 BEACH ROAD #17-04/07 THE CC |) NCOURSESINGAPORE 199555 | Date: | 10/05/2021 | | | |
| | | | Code | LPC2 | | | |
| 1. | | Policy Particulars | :- THIRD PARTY CLAI | M | | | |
| | Insured Veh. | GBA 9238T | Veh. Inspected | SMW 5632T | | | |
| | Policy No. | Z/20/VC00/106596 | Coverage (\$) | 0.00 | | | |
| | Claim No. | 20/21/21/VC00/024147 | Excess (\$) | 0.00 | | | |
| | Assign From | GERALD | Assign Date | 18/01/2021 | | | |
| 2. | | Vehicle Partic | culars & Condition | | | | |
| | Make & Model | B.M.W. 730li (A) | c.c | 2996 | | | |
| | Engine No. | HIDDEN | Year of Reg. | 2011 | | | |
| | Chassis No. | WBAKB22020CN74901 | Colour | METALLIC SILVER | | | |
| | Odometer | 57032 KM | Steering | IN ORDER | | | |
| | Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | | | |
| | General | GOOD | | | | | |
| 3. | | Conditi | ons of Tyres | | | | |
| | | Size | Make | Balance | | | |
| | R/H Front Tyre | 245/50 R18 | BRIDGESTONE | 7 mm | | | |
| | L/H Front Tyre | 245/50 R18 | BRIDGESTONE | 7 mm | | | |
| | R/H Rear Tyre | 245/50 R18 | BRIDGESTONE | 7 mm | | | |
| | L/H Rear Tyre | 245/50 R18 | BRIDGESTONE | 7 mm | | | |
| 4. | | Description | on of Damages | | | | |
| | THE VEHICLE SU | STAINED DAMAGES AT THE RE | AR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | | | |
| 5. | | Genera | I Information | | | | |
| | Accident Date | 15/01/2021 | Inspection Date | 19/01/2021 | | | |
| | Survey held at | WEGA ENGINEERING PTE LTD |) | | | | |
| | | BLK 176 SIN MING DRIVE #04-16 SIN MING AUTOCARE . SINGAPORE 575721 | | | | | |
| 5a. | | Ro | emarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | | |
| 5b. | Estimate Days of Repair | | | | | | |
| | ESTIMATED NOR | MAL PERIOD FOR REPAIR: | 3 Wor | king Days | | | |
| | | | | | | | |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMW 5632T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | BUCKLED | 2,376.00 | 1,876.00 |
| 1 | REAR BUMPER ABSORBER GARNISH NO:13 | SERVICEABLE | 786.84 | - |
| 1 | REAR BUMPER LOWER LIP NO.3 | BUCKLED / DENTED | 638.00 | 638.00 |
| 1 | REAR BUMPER RENTANNAL LH NO.11 | SERVICEABLE | 52.80 | - |
| 1 | REAR BUMPER REFLECTOR LH | SERVICEABLE | 93.50 | - |
| 1 | REAR BUMPER REVERSE SENSOR | SHORTED | 424.60 | 381.60 |
| 1 | REAR FENDER LAMP LH | SERVICEABLE | 825.00 | - |
| 2 | REAR END PANEL @\$1358.50 | TO REPAIR SEE LABOUR | 1,358.50 | - |
| 5 | REAR EXHAUST PIPE COULER | SERVICEABLE | 198.00 | - |
| 1 | REAR EXHAUST PIPE MOUNTING BRACKET | TO REPAIR SEE LABOUR | 27.50 | - |
| 1 | EXHAUST PIPE MOUNTING | SERVICEABLE | 71.50 | - |
| 1 | REAR BUMPER REINFORCEMENT | BENT | 886.64 | 782.00 |
| | LESS 5% DISCOUNT | | - | -183.88 |
| | | | 7,738.88 | 3,493.72 |
| | <u>LABOUR</u> | | | |
| | TO CHECK WIRING & SYSTEM FUNCTION . | | 100.00 | 15.00 |
| | TO REMOVE & REFIX REAR REVERSE SENSOR . | | 120.00 | 60.00 |
| | TO CHECK & RESET REVERSE SENSOR SYSTEM FUNCTION . | NOT NECESSARY | 80.00 | - |
| | TO CONDUCT RE-PROGRAMME AND SETTING OF ECU SYSTEMTO FAULT CODE. | NOT NECESSARY | 180.00 | - |
| | TO REPLACE ,REPAIR & KNOCKING ACCIDENT REAR PORTION REAR BUMPER ,CHASSIS LH REAR TAILGATE ,REAR TYRE PANEL AND REAR END PANEL.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR EXHAUST PIPE MOUNTING BRACKET . | | 1,000.00 | 300.00 |
| | TO RESPRAY REAR BUMPER ,REAR TAIL GATE ,REAR END PANEL ,TYRE PANEL N CHASSIS LH . | | 1,000.00 | 300.00 |
| | | | 2,480.00 | 675.00 |
| | GRAND TOTAL | | 10,218.88 | 4,168.72 |

Report Ref No. CC4/LPC21000852/Kga3q2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 3,300.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CC4/LPC21000852/Kga3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMW 5632T

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMW 5632T

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMW 5632T

RE-INSPECTION





