

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000861/T1PA3Q2
Date: 18/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900153570
Claimant Vehicle No :	SHB6655R	Insured Vehicle No :	SJA9996T
Date of Loss:	16/01/2021	Nature of Claim:	TP
		Claim No:	9200732269SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6655R		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU194604
Reg. Date:	23/04/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU141799
Colour:	Blue	Odometer:	197117 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	796.12	378.60	417.52	52.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	830.00	150.00	15.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,776.12	1,208.60	567.52	31.95
+ GST 7.00/7.00% (S\$)	124.33	84.60	39.73	31.96

Nett Amount (S\$)	1,900.45	1,293.20	607.25	31.95
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$125.19/day) (S\$)		312.98		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,733.18		
Global Sum Settlement (S\$)		1,730.00		

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 18/01/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -RR BUMPER	Repair	459.40 FL	*- FL
2	1		*MOULDING ASSY-R	Cut	451.25 FL	*451.25 FL
3	10		*BUMPER COVER CLIP R	Necessary	22.00 FL	*22.00 FL
4	1		*PROTECTOR MAT	Not Necessary	50.00 FS	*- FS
					Sub Total (\$)	473.25
					- List Item Discount on L Items 20.00/20.00% (\$)	94.65
					Total Parts (\$)	378.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
4	RENEW ADVERTISEMENT STICKER -FENDER	New	200.00	200.00
Gross Labour Cost (\$\$)			980.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >