

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21000871/EQD3E2

Date: 10/02/2021

REFERENCE

Insured/Claimant:	DHANARAJ THOMAS JEYARAJ	Policy No:	2070129638	
Date of Loss:	18/01/2021	Nature of Claim:	OD	Claim No: 9267489497SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU9407L		
Make & Model:	KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)	Engine No:	G4LEKS616335
Reg. Date:	07/09/2020 (Man. Year: 2019)	Chassis No:	KNACB81CVL5371398
Colour:	Blue	Odometer:	18601 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,261.20	5,284.00	1,977.20	27.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	2,290.00	1,240.00	35.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,791.20	7,574.00	3,217.20	29.81
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	10,491.20	7,274.00	3,217.20	30.67
+ GST 7.00/7.00% (S\$)	734.38	509.18	225.20	30.67
Nett Amount (S\$)	11,225.58	7,783.18	3,442.40	30.67

INSPECTION

Date of Assignment:	19/01/2021	
Date Inspected:	19/01/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-HEAD,RH	Not Necessary	904.00 FL	*- FL
2	1		*CARRIER ASSY-FRONT END MODULE	Crushed	675.00 FL	*675.00 FL
3	1		*BEAM COMPLETE-FR BUMPER	Dented	661.00 FL	*661.00 FL
4	1		*HINGE ASSY-HOOD,RH	Not Necessary	40.00 FL	-
5	1		*HINGE ASSY-HOOD,LH	Not Necessary	40.00 FL	*- FL
6	1		*CONDENSER ASSY-COOLER	Bent	639.00 FL	*639.00 FL
7	1		*RADIATOR ASSY-INVERTER	Bent	768.00 FL	*768.00 FL
8	1		*RADIATOR ASSY	Bent	492.00 FL	*492.00 FL
9	1		*GUARD-AIR,LH	Not Necessary	29.00 FL	*- FL
10	1		*GUARD-AIR,RH	Broken	29.00 FL	*29.00 FL
11	1		*GUARD-AIR RADIATOR,UPR	Not Necessary	15.00 FL	*- FL
12	1		*BLOWER ASSY	Broken	546.00 FL	*546.00 FL
13	1		*COVER-FR BUMPER UPR	Broken	637.00 FL	*637.00 FL
14	1		*COVER-FR BUMPER,LWR	Cut	373.00 FL	*373.00 FL
15	1		*LIP ASSY-FRONT BUMPER	Not Necessary	38.00 FL	*- FL
16	1		*SKID PLATE-FR BUMPER	Not Necessary	60.00 FL	*- FL
17	1		*STRIP ASSY-FR BUMPER UPR	Not Necessary	28.00 FL	*- FL
18	1		*GRILLE ASSY-RADIATOR	Broken	441.00 FL	*441.00 FL
19	1		*COVER ASSY-RADIATOR GRILLE UPR	Not Necessary	40.00 FL	*- FL
20	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	68.00 FL	*68.00 FL
21	1		*COVER-DAYTIME RUNNING LIGHT,RH	Broken	46.00 FL	*46.00 FL
22	1		*BRACKET-FR BUMPER SIDE MTG,LH	Broken	3.00 FL	*3.00 FL
23	1		*BRACKET-FR BUMPER SIDE MTG,RH	Broken	3.00 FL	*3.00 FL
24	1		*LAMP ASSY-DAY RUNNING LIGHT RH	Not Necessary	619.00 FL	*- FL
25	1		*GRILLE-FRONT BUMPER	Cut	131.00 FL	*131.00 FL
26	1		*STIFFNER-FR BPR LWR	Not Necessary	116.00 FL	*- FL
27	1		*DUCT ASSY-ACTIVE AIR	Broken	64.00 FL	*64.00 FL
28	1		*FLAP ASSY-ACTIVE AIR,LWR	Not Necessary	481.00 FL	*- FL
29	1		*BRACKET-FR BUMPER SIDE,LH	Not Necessary	12.00 FL	*- FL
30	1		*BRACKET-FR BUMPER SIDE,RH	Not Necessary	12.00 FL	*- FL
31	1		*LOGO ASSY-KIA SUB	Necessary	51.00 FL	*51.00 FL
32	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
33	1		*HOSE & CLAMP ASSY (Supplementary)	Bent	83.00 FL	*83.00 FL
34	1		*DAM-AIR (Supplementary)	Crushed	27.00 FL	*27.00 FL
35	1		*HORN ASSY -HIGH PITCH (Supplementary)	Crushed	79.00 FL	*79.00 FL
36	1		*FLAP ASSY-ACTIVE AIR, LWR (Supplementary)	Broken	481.00 FL	*481.00 FL
37	1		*PIPE & TUBE ASSY (Supplementary)	Bent	227.00 FL	*227.00 FL
38	1		*NIRO HYBRID EMBLEM (Supplementary)	Necessary	30.00 FL	*30.00 FL
39	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 FL	*26.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,064.00	6,600.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,802.80	1,316.00
Total Parts (S\$)	7,261.20	5,284.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,SUPPORT PANEL & AFFECTED AREA.REPAIR ON FRT LH FENDER	New	1,600.00	400.00
2	PAINT WORK ON FRT BUMPER,BONNET & FRT LH FENDER	New	1,050.00	1,050.00
3	REMOVE & INSTALL RADIATOR,CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
4	TO TOP UP AIRCON GAS	New	80.00	80.00
5	PERFORM RUST PREVENTION	New	80.00	40.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	TO SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
9	REPLACE SUPPORT PANEL (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			3,530.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >