

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/III21000874/APS3Q2

Date:

19/05/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MPC0002286_01

Claimant Vehicle No : SMR2560M**Insured Vehicle No :**

SJF1927U

Date of Loss: 14/01/2021

Nature of Claim:

TP

Claim No:

MPC2021D0000291

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMR2560M**

Make & Model: HONDA FIT, 1.3 GF CVT (A)

Engine No:

L13B3935192

Reg. Date: 26/12/2019 (Man. Year: 2019)

Chassis No:

GK33420703

Colour: Black

Odometer:

13707 km

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size:

175/70 R14

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,100.24	7,682.32	5,417.92	41.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	3,170.00	1,290.00	28.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,560.24	10,852.32	6,707.92	38.20
Approved Total (Overridden) (S\$)		8,650.00		

Nett Amount (S\$)		17,560.24	8,650.00	8,910.24	50.74
Global Sum Settlement (S\$)			0.00		

INSPECTION

Date of Assignment:	15/01/2021		
Date Inspected:	15/01/2021	Inspected At:	Polymath Garage Pte Ltd - Kaki Bukit (HQ) 10 KAKI BUKIT ROAD 2, #01-21 FIRST EAST CENTRE Singapore 417868
Estimated Period of Repair:	9.0 days		

Adjuster:	ADRIAN LING	Manager:	CHEW HSIAO TONG
------------------	-------------	-----------------	-----------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR2560M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	584.20 FL	*584.20 FL
2	2		*FRONT BUMPER SIDE HOLDER	Necessary	51.00 FL	*51.00 FL
3	2		*FRONT FENDER	Dented	870.00 FL	*870.00 FL
4	1		*FRONT FENDER INNER SHIELD	N/S Deformed	277.20 FL	*138.60 FL
5	1		*HEADLAMP	N/S Cracked	2,341.20 FL	*1,170.60 FL
6	1		*HEADLAMP LOWER BRACKET	N/S Cracked	130.00 FL	*65.00 FL
7	1		*FRONT RH DOOR	Dented	966.20 FL	*966.20 FL
8	1		*FRONT RH DOOR WING MIRROR	Damaged	527.50 FL	*527.50 FL
9	2		*FRONT RH DOOR HINGE	Not Necessary	190.00 FL	*- FL
10	1		*FRONT RH DOOR INNER TRIM BOARD	Not Necessary	605.20 FL	*- FL
11	1		*FRONT RH DOOR GLASS REGULATOR GEAR	Not Necessary	392.00 FL	*- FL
12	1		*FRONT RH DOOR LOCK	Not Necessary	375.00 FL	*- FL
13	1		*FRONT RH DOOR WEATHERSTRIPE	Not Necessary	138.40 FL	*- FL
14	1		*REAR RH DOOR	Dented	845.40 FL	*845.40 FL
15	1		*REAR RH DOOR HINGE	Not Necessary	190.00 FL	*- FL
16	1		*REAR RH DOOR WEATHERSTRIPE	Not Necessary	122.30 FL	*- FL
17	2		*FRONT LOWER ARM	Bent	790.00 FL	*790.00 FL
18	2		*FRONT KNUCKLE ARM	Damaged	1,010.40 FL	*1,010.40 FL
19	2		*FRONT WHEEL HUB C/W BEARING	Damaged	376.60 FL	*376.60 FL
20	2		*FRONT SHOCK ABSORBER	Bent	732.40 FL	*732.40 FL
21	1		*STEERING RACK & PINION	Not Necessary	1,885.30 FL	*- FL
22	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	2		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
24	1		*SET FRONT RH DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
25	1		*SET FRONT RH DOOR BLACK TAPE	Necessary	60.00 FS	*60.00 FS
26	1		*SET REAR RH DOOR BLACK TAPE	Necessary	60.00 FS	*60.00 FS
27	2		*FRONT WHEEL RIM	Cut	1,600.00 FS	*1,000.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*FRONT TYRE	Not Necessary	500.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					15,780.30	9,307.90
- List Item Discount on L Items 20.00/20.00% (\$)					2,680.06	1,625.58
Total Parts (\$)					13,100.24	7,682.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	1,100.00
2	SPRAY PAINTING	New	1,600.00	1,300.00
3	WIRING	New	50.00	30.00
4	TO TRANSFER FRONT RH DOOR FITTINGS	New	150.00	80.00
5	TO TRANSFER REAR RH DOOR FITTINGS	New	150.00	80.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
7	TO REMOVE FRONT LH & RH UNDERCARRIAGE	New	700.00	440.00
8	TOWING FEES	New	60.00	60.00
Gross Labour Cost (S\$)			4,460.00	3,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >