Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG21000875/UQF3Q2

Date: 25/02/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001623868

Claimant Vehicle No: SMK6587Y Insured Vehicle No: SLG5264T

Date of Loss: 15/01/2021 Nature of Claim: TP Claim No: 252225

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK6587Y

 Make & Model:
 HONDA SHUTTLE, 1.5 G CVT (A)
 Engine No:
 L15B6002442

 Reg. Date:
 18/04/2019 (Man. Year: 2019)
 Chassis No:
 GK82002068

 Colour:
 Blue
 Odometer:
 22164 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm
Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,592.60	2,664.16	3,928.44	59.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	620.00	640.00	50.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,852.60	3,284.16	4,568.44	58.18
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	7,852.60	2,950.00	4,902.60	62.43
+ GST 7.00/7.00% (S\$)	549.68	206.50	343.18	62.43
Nett Amount (S\$)	8,402.28	3,156.50	5,245.78	62.43

INSPECTION

Date of Assignment: 28/01/2021

Date Inspected: 19/01/2021 Inspected At: Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 5

Adjuster Report Page 3 of 5

Note: New parts replacement

Adjuster Report Page 4 of 5

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 25 Feb 2021)

Parts: N/A HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMK6587Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

C = = = 1:4: = =

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	1,550.00 F	*1,020.20 FL
2	1		*FRONT BUMPER SIDE RETAINER O/S	Serviceable	52.50 F	*-FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	450.80 F	*- FL
4	1		*FRONT BUMPER FOG LAMP O/S	Not Necessary	422.10 F	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
6	1		*HEADLAMP LED O/S	Cracked	3,230.10 F	*2,271.00 FL
7	1		*FRONT GRILLE	Not Necessary	355.80 F	*- FL
8	1		*FRONT FENDER O/S	Repair	492.30 F	*- FL
F=Fra	nchise	part. L=ListIt	emDisc.	_		
				Sub Total (S\$)	6,592.60	3,330.20
	- List Item Discount on L Items 0.00/20.00% (S\$)			0.00	666.04	
				Total Parts (S\$)	6,592.60	2,664.16

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO CHECK WIRING	New	50.00	20.00				
2	TO SPRAY RUST PROOFING	New	50.00	0.00				
3	TO CONDUCT WHEEL ALIGNMENT	New	80.00	0.00				
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	500.00	200.00				
5	TO PUTTY & SPRAY PAINTING	New	580.00	400.00				
	Gross Labo	our Cost (S\$)	1,260.00	620.00				

Report was unsubmitted during this print-out.

< END OF ESTIMATES >