

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG21000877/ETF3E2

Date: 23/02/2021

REFERENCE

Insured/Claimant:	GOH TZE YUEN GILBERT	Policy No:	2070088930		
Date of Loss:	18/01/2021	Nature of Claim:	OD	Claim No:	4043093316SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD3322L	Engine No:	G4FGKH756317
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF5416ML5069940
Reg. Date:	11/06/2020 (Man. Year: 2019)	Odometer:	8586 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$89,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,989.20	616.00	2,373.20	79.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	670.00	670.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,659.20	1,286.00	2,373.20	64.86
+ GST 7.00/7.00% (S\$)	256.14	90.02	166.12	64.86
Nett Amount (S\$)	3,915.34	1,376.02	2,539.32	64.86

INSPECTION

Date of Assignment:	19/01/2021		
Date Inspected:	19/01/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	1.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$2,075.20 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*- FS
2	1		*GEAR ASSY-STEERING	Bent	770.00 FL	*770.00 FL
3	1		*KNUCKLE-FRNT AXLE, LH	* Check	350.00 FL	*- FL
4	1		*HUB ASSY-FR WHEEL LHF	* Check	436.00 FL	*- FL
5	1		*BAR ASSY-FR STABILIZER	Not Necessary	238.00 FL	*- FL
6	1		*LINK-STABILIZER LHF	Not Necessary	72.00 FL	*- FL
7	1		*STRUT ASSY-FR, LH	* Check	280.00 FL	*- FL
8	1		*BEARING-STRUT	* Check	86.00 FL	*- FL
9	1		*ARM COMPLETE-FR LWR, LH	* Check	286.00 FL	*- FL
10	1		*CROSSMEMBER COMPL	* Check	1,156.00 FL	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					3,724.00	770.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					734.80	154.00
Total Parts (\$\$)					2,989.20	616.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
2	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
3	RENEW FRT U/CARRIAGE LH INCLUDING STEERING RACK & PINION	New	400.00	400.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
Gross Labour Cost (\$\$)			670.00	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >