



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 6647S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT DOOR RH	BENT	1,036.80	792.40
1	FRONT DOOR HANDLE RH	DISTORTED	195.00	195.00
1	FRONT DOOR LOCK COMPL	DENTED	388.80	388.80
1	FRONT DOOR INNER TRIM BOARD RH	MTG DISTORTED	430.00	430.00
1	FRONT DOOR REGULATOR RH	BENT	490.00	490.00
1	FRONT DOOR GLASS RH	SHATTERED	680.00	508.20
1	SET FRONT DOOR HINGE RH	BENT	100.00	100.00
1	FRONT DOOR CHECKER RH	BENT	65.00	65.00
1	FRONT DOOR WEATHERSTRIP	CUT	195.00	195.00
1	FRONT DOOR WINDOW TRIM	BENT	110.00	110.00
1	SET FRONT DOOR STICKER	NECESSARY	75.00	75.00
1	ROCKER PANEL RH	BENT	378.00	378.00
1	ROCKER PANEL SIDE COVER RH	DENTED	175.00	175.00
1	REAR DOOR RH	BENT	1,036.80	736.20
1	SET REAR DOOR HINGE RH	BENT	100.00	100.00
1	SET REAR DOOR STICKER RH	NECESSARY	75.00	75.00
1	FRONT FENDER RH	BENT	280.80	280.80
1	FRONT FENDER "HYBRID" EMBLEM	NECESSARY	55.00	55.00
1	FRONT FENDER SIGNAL LAMP RH	MISSING	21.60	21.60
1	FRONT FENDER QUARTER GLASS	SERVICEABLE	240.00	-
1	SIDE MIRROR COMPL RH	DENTED / CRACKED	324.00	324.00
1	FRONT WHEEL COVER RH	DENTED	453.60	175.00
1	FRONT ABSORBER RH	BENT	423.00	423.00
1	FRONT LOWER ARM RH	SERVICEABLE	248.40	-
1	FRONT KNUCKLE ARM RH	BENT	388.80	388.80
1	FRONT STABILIZER LINK RH	DISTORTED	64.80	64.80
1	FRONT STABILIZER BAR RH	SERVICEABLE	223.50	-
1	FRONT STEERING RACK	TO REPAIR SEE LABOUR	750.00	-
1	FRONT DRIVER SHAFT	TO REPAIR SEE LABOUR	226.70	-

Report Ref No. CS/TP21000878/Kqd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WHEEL BEARING RH	NECESSARY	176.30	176.30
1	FRONT FENDER INNER SHIELD RH	DISTORTED	75.00	75.00
	LESS 20% DISCOUNT		-	-1,359.58
			9,481.90	5,438.32
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT STEEL RIM (LOCAL PURCHASE) (SN)	DENTED	403.20	60.00
1	FRONT FENDER INNER SHIELD CLIPS RH (SN)	NECESSARY	30.00	30.00
1	SET FRONT DOOR HANDLE CARBON FIBER FITTINGS (SN)	NECESSARY	170.00	170.00
1	SET FRONT DOOR SUN VISOR (SN)	NECESSARY	150.00	150.00
1	SET FRONT / REAR DOOR CARBON FIBER TRIMMING (SN)	NECESSARY	150.00	150.00
			903.20	560.00
	<b><u>LABOUR</u></b>			
	LABOUR CHARGE TO REMOVE, REFIX, REPAIR & READJUST ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF FRONT STEERING RACK AND FRONT DRIVER SHAFT.		1,400.00	1,100.00
	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.		1,200.00	1,000.00
	LABOUR CHARGES TO DISMANTLE & RE-INSTALL FRONT DOOR MECHANISM / GLASS.		180.00	60.00
	LABOUR CHARGES TO DISMANTLE & RE-INSTALL REAR DOOR MECHANISM / GLASS.		180.00	60.00
	LABOUR CHARGES TO DISMANTLE AND RE-INSTALL UNDERCARRIAGE.		200.00	180.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO TUFF KOTE & UNDERSEAL MATERIALS.		150.00	120.00
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		150.00	40.00
	TO DIAGNOSIS FAULT CODE & RESET MEMORY.		150.00	120.00
			3,760.00	2,740.00
	<b>GRAND TOTAL</b>		<b>14,145.10</b>	<b>8,738.32</b>

Report Ref No. CS/TP21000878/Kqd3e2



RECOMMENDED COST OF REPAIRS			8,738.32
-----------------------------	--	--	----------

Report Ref No. CS/TP21000878/Kqd3e2

A handwritten signature in black ink, consisting of the letters 'KSC' in a cursive, stylized font.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.