

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000880/EQD3Q2
Date: 05/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00125192000
Claimant Vehicle No :	SML4845K	Insured Vehicle No :	SMH3493U
Date of Loss:	15/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200269/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML4845K	Engine No:	G4FGJH721702
Make & Model:	KIA CERATO, 1.6 SX (A)	Chassis No:	KNAF3416MK5040936
Reg. Date:	23/05/2019 (Man. Year: 2018)	Odometer:	22686 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,202.00	694.00	508.00	42.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,420.00	2,760.00	2,660.00	49.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,622.00	3,454.00	3,168.00	47.84
+ GST 7.00/7.00% (S\$)	463.54	241.78	221.76	47.84
Nett Amount (S\$)	7,085.54	3,695.78	3,389.76	47.84

INSPECTION

Date of Assignment:	19/01/2021	
Date Inspected:	05/02/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2021)
Parts:	143	KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML4845K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRACKET ASSY-RR BPR SIDE UPR,L	Not Necessary	25.00 FS	*- FS
2	1		*BRACKET ASSY-RR BPR SIDE UPR,R	Not Necessary	31.00 FS	*- FS
3	1		*LAMP ASSY-SIDE T/SIGNAL,RH	Not Necessary	181.00 FS	*- FS
4	1		*COVER-RR BUMPER FOG LAMP,RH	Cut	19.00 FS	*19.00 FS
5	2		*GROMMET ASSY-SCREW	Necessary	4.00 FS	*4.00 FS
6	1		*COVER-RR BUMPER	Broken	651.00 FS	*651.00 FS
7	1		*COVER-RR BUMPER LWR	Not Necessary	241.00 FS	*- FS
8	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	1,202.00	694.00
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE,REPAIR RH REAR FENDER DAMAGES	New	1,920.00	640.00
2	REMOVE AND INSTALL PARKING ASSIST TO FACILITATE REPAIR WORK	New	100.00	100.00
3	PAINT WORK SPRAY RH REAR FENDER,REAR BUMPER AND AFFECTED PORTION	New	1,650.00	550.00
4	PERFORM RUST PREVENTION	New	80.00	0.00
5	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	200.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI SCAN PRO TEST USING HI SCAN PRO TEST	New	280.00	280.00
7	REPAIR RH REAR FENDER	New	640.00	640.00
8	RESPRAY RH REAR FENDER	New	550.00	550.00
Gross Labour Cost (\$\$)			5,420.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >