

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	Re	ef:	CS3/ASM21000888/R1qf3e2	
	8 SHENTON WAY TOWERSINGAPOR	-	Da	ite:	04/02/2021	
	ATTN : TAN WANG	CONG	Co	de:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	EQ 38T	Veh. Inspected		FBR 2305P	
	Policy No.	GA502556/1	Coverage (\$)		0.00	
	Claim No.	S0M02ZPC	Excess (\$)		0.00	
	Assign From	TAN WANCONG	Assign Date		19/01/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA NC700XA	c.c		670	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	JH2RC63B2CK500949	Colour		MULTI COLOUR	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	120/70Z R17	MICHELIN		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	160/60Z R17	MICHELIN		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.					
5.	5. General Information					
	Accident Date	29/12/2020	Inspect Date / Tim	ne	19/01/2021 (04:54 PM)	
	Survey held at	20 BUKIT BATOK CRESCENT	#01-19 ENTERPRISE (CENT	TRE	
	Repairer	Repairer PRIMERO RACING				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$500-\$1,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days					

Report Ref No. CS3/ASM21000888/R1qf3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

DECD And Consider OF Liverage Association

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$