

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21000891/DQD3Q2  
**Date:** 05/03/2021

### REFERENCE

|                                                                 |                               |                                   |
|-----------------------------------------------------------------|-------------------------------|-----------------------------------|
| Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: DMPCSNW00193252000 |                                   |
| Claimant Vehicle No : SJE7117G                                  | Insured Vehicle No : SJV4574A |                                   |
| Date of Loss: 17/01/2021                                        | Nature of Claim: TP           | Claim No: SNM21D200305/C02/THAMYL |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | SJE7117G                          |             |                   |
| Make & Model:               | HONDA CR-V, 1.5 (A)               | Engine No:  | K24Z98501662      |
| Reg. Date:                  | 24/06/2015 (Man. Year: 2015)      | Chassis No: | MRHRM3850GP000013 |
| Colour:                     | White                             | Odometer:   | 117788 km         |
| Engine Capacity:            | 2354 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 225/60 R18    | Rear Tyre Size:  | 225/60 R18    |
| Front Left Side:  | Yokohama 5 mm | Rear Left Side:  | Yokohama 5 mm |
| Front Right Side: | Yokohama 5 mm | Rear Right Side: | Yokohama 5 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                    | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts                             | 32,987.60  | 2,914.18   | 30,073.42  | 91.17  |
| Miscellaneous Items               | 0.00       | 0.00       | 0.00       |        |
| Labour                            | 7,700.00   | 1,560.00   | 6,140.00   | 79.74  |
| Paintwork Labour                  | 0.00       | 0.00       | 0.00       |        |
| Towing                            | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 40,687.60  | 4,474.18   | 36,213.42  | 89.00  |
| Approved Total (Overridden) (S\$) |            | 3,550.00   |            |        |
| (S\$)                             | 40,687.60  | 3,550.00   | 37,137.60  | 91.27  |
| + GST 7.00/7.00% (S\$)            | 2,848.13   | 248.50     | 2,599.63   | 91.27  |
| Nett Amount (S\$)                 | 43,535.73  | 3,798.50   | 39,737.23  | 91.27  |

### INSPECTION

|                             |                          |                                                                                                                |
|-----------------------------|--------------------------|----------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 21/01/2021               |                                                                                                                |
| Date Inspected:             | 19/01/2021 Inspected At: | JWG International Pte Ltd (HQ)<br>Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK<br>AutoPoint<br>Singapore 568047 |
| Estimated Period of Repair: | 4.0 days                 |                                                                                                                |

3/5/2021

Adjuster Report

**Adjuster:** BRYAN TANI

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                      |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 02 Mar 2021)                                                                                                                                             |                                                      |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | HONDA CR-V 1.5 (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                    |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SJE7117G)                                                                                                                                    |                                                      |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                      |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                      |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                      | Condition         | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------------------|-------------------|-------------|--------------|
| 1   | 1   |          | <b>*TAILGATE</b>                                 | Dented            | 2,980.00 FL | *1,255.90 FL |
| 2   | 1   |          | <b>*TAILGATE CENTER CHROME</b>                   | Not Necessary     | 410.00 FL   | *- FL        |
| 3   | 1   |          | <b>*TAILGATE LOGO</b>                            | Not Necessary     | 101.40 FL   | *- FL        |
| 4   | 1   |          | <b>*TAILGATE LOWER GARNISH</b>                   | Mounting Broken   | 1,410.00 FL | *339.72 FL   |
| 5   | 1   |          | <b>*TAILGATE CRV EMBLEM</b>                      | Necessary         | 92.00 FL    | *92.00 FL    |
| 6   | 1   |          | <b>*TAILGATE LOCK</b>                            | Not Necessary     | 398.00 FL   | *- FL        |
| 7   | 1   |          | <b>*TAILGATE WEATHER STRIP</b>                   | Not Necessary     | 402.20 FL   | *- FL        |
| 8   | 1   |          | <b>*TAILGATE SWITCH</b>                          | Not Necessary     | 372.90 FL   | *- FL        |
| 9   | 1   |          | <b>*TAILGATE INNER TRIM BOARD</b>                | Not Necessary     | 1,142.00 FL | *- FL        |
| 10  | 1   |          | <b>*TAILGATE WINDSCREEN MOULDING</b>             | Necessary         | 421.00 FL   | *188.30 FL   |
| 11  | 2   |          | <b>*TAIL LAMP LH/RH</b>                          | Not Necessary     | 2,004.80 FL | *- FL        |
| 12  | 2   |          | <b>*TAIL LAMP LOWER BRACKET LH/RH</b>            | Not Necessary     | 403.80 FL   | *- FL        |
| 13  | 1   |          | <b>*REAR BUMPER</b>                              | Distorted/Cracked | 1,980.20 FL | *695.30 FL   |
| 14  | 2   |          | <b>*REAR BUMPER SIDE RETAINER LH/RH</b>          | Serviceable       | 229.60 FL   | *- FL        |
| 15  | 2   |          | <b>*REAR BUMPER REFLECTOR LH/RH</b>              | Not Necessary     | 248.00 FL   | *- FL        |
| 16  | 1   |          | <b>*REAR BUMPER LOWER LID CENTER</b>             | Mounting Broken   | 1,004.80 FL | *281.60 FL   |
| 17  | 2   |          | <b>*REAR BUMPER LOWER LID SIDE LH/RH</b>         | Not Necessary     | 1,580.00 FL | *- FL        |
| 18  | 4   |          | <b>*REAR BUMPER SENSOR HOLDER</b>                | Not fitted        | 80.00 FL    | *- FL        |
| 19  | 1   |          | <b>*REAR BUMPER SENSOR WIRE HARNESS</b>          | Not Necessary     | 1,221.90 FL | *- FL        |
| 20  | 1   |          | <b>*REAR BUMPER UNDER COVER</b>                  | Not Necessary     | 349.80 FL   | *- FL        |
| 21  | 1   |          | <b>*REAR BUMPER SPONGE</b>                       | Not fitted        | 348.70 FL   | *- FL        |
| 22  | 1   |          | <b>*REAR REINFORCEMENT BAR</b>                   | Not fitted        | 1,450.00 FL | *- FL        |
| 23  | 1   |          | <b>*REAR END PANEL</b>                           | Repair            | 2,149.10 FL | *- FL        |
| 24  | 1   |          | <b>*REAR END PANEL TOP GARNISH</b>               | Not Necessary     | 389.20 FL   | *- FL        |
| 25  | 1   |          | <b>*SPARE WHEEL PANEL</b>                        | Not Necessary     | 2,680.20 FL | *- FL        |
| 26  | 1   |          | <b>*SPARE WHEEL PANEL TOP BOARD</b>              | Not Necessary     | 490.80 FL   | *- FL        |
| 27  | 2   |          | <b>*SPARE WHEEL QUARTER PANEL LH/RH</b>          | Not Necessary     | 1,960.00 FL | *- FL        |
| 28  | 1   |          | <b>*SPARE WHEEL PANEL TOOL BOX</b>               | Not Necessary     | 499.80 FL   | *- FL        |
| 29  | 2   |          | <b>*REAR FENDER LH/RH</b>                        | Not Necessary     | 6,038.00 FL | *- FL        |
| 30  | 2   |          | <b>*REAR FENDER INNER TRIM BOARD LH/RH</b>       | Not Necessary     | 2,480.00 FL | *- FL        |
| 31  | 2   |          | <b>*REAR FENDER QUARTER GLASS MOULDING LH/RH</b> | Not Necessary     | 596.00 FL   | *- FL        |
| 32  | 1   |          | <b>*REAR EXHAUST PIPE</b>                        | Not Necessary     | 2,119.40 FL | *- FL        |
| 33  | 1   |          | <b>*REAR EXHAUST MOUNTING</b>                    | Not Necessary     | 98.00 FL    | *- FL        |
| 34  | 1   |          | <b>*REAR EXHAUST HEAT SHIELD</b>                 | Not Necessary     | 249.00 FL   | *- FL        |
| 35  | 1   |          | <b>*REAR KEYLESS SENSOR</b>                      | Mounting Broken   | 197.00 FL   | *197.00 FL   |
| 36  | 1   |          | <b>*REAR KEYLESS BUZZER</b>                      | Mounting Broken   | 217.90 FL   | *217.90 FL   |
| 37  | 1   |          | <b>*TAILGATE WINDSCREEN SEALANT</b>              | Necessary         | 80.00 FS    | *40.00 FS    |
| 38  | 1   |          | <b>*TAILGATE WINDSCREEN DAMPING SEAL</b>         | Not Necessary     | 30.00 FS    | *- FS        |
| 39  | 1   |          | <b>*TAILGATE LOWER GARNISH CLIPS</b>             | Necessary         | 50.00 FS    | *20.00 FS    |
| 40  | 1   |          | <b>*TAILGATE CHROME GARNISH CLIPS</b>            | Not Necessary     | 50.00 FS    | *- FS        |
| 41  | 1   |          | <b>*TAILGATE INNER TRIM BOARD CLIPS</b>          | Not Necessary     | 50.00 FS    | *- FS        |
| 42  | 1   |          | <b>*REAR BUMPER CLIPS</b>                        | Necessary         | 50.00 FS    | *20.00 FS    |

Report was unsubmitted during this print-out.

| No.                                                 | Qty | Part No. | Particulars                             | Condition     | Repairer's       | Amount          |
|-----------------------------------------------------|-----|----------|-----------------------------------------|---------------|------------------|-----------------|
| 43                                                  | 1   |          | *REAR END PANEL SEALANT                 | Not Necessary | 80.00 FS         | *- FS           |
| 44                                                  | 1   |          | *REAR END PANEL TOP GARNISH CLIPS       | Not Necessary | 50.00 FS         | *- FS           |
| 45                                                  | 1   |          | *SPARE WHEEL PANEL SEALANT              | Not Necessary | 80.00 FS         | *- FS           |
| 46                                                  | 1   |          | *REAR FENDER SEALANT                    | Not Necessary | 80.00 FS         | *- FS           |
| 47                                                  | 1   |          | *REAR FENDER INNER TRIM CLIPS           | Not Necessary | 50.00 FS         | *- FS           |
| 48                                                  | 1   |          | *REAR FENDER QUARTER GLASS SEALANT      | Not Necessary | 80.00 FS         | *- FS           |
| 49                                                  | 1   |          | *REAR FENDER QUARTER GLASS DAMPING SEAL | Not Necessary | 30.00 FS         | *- FS           |
| 50                                                  | 1   |          | *REAR NO PLATE & CASING                 | Not Necessary | 100.00 FS        | *- FS           |
| 51                                                  | 4   |          | *REAR BUMPER SENSOR                     | Damaged       | 1,091.20 FS      | *220.00 FS      |
|                                                     |     |          |                                         |               |                  |                 |
| Sub Total (\$\$)                                    |     |          |                                         |               | <b>40,746.70</b> | <b>3,567.72</b> |
| - List Item Discount on L Items 20.00/20.00% (\$\$) |     |          |                                         |               | 7,759.10         | 653.54          |
|                                                     |     |          |                                         |               |                  |                 |
| Total Parts (\$\$)                                  |     |          |                                         |               | <b>32,987.60</b> | <b>2,914.18</b> |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                                                        | Lab.Type | Repairer's      | Amount          |
|-------------------------|----------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>     |                                                                                                    |          |                 |                 |
| 1                       | TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS                                      | New      | 500.00          | 80.00           |
| 2                       | TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS                                            | New      | 2,600.00        | 600.00          |
| 3                       | TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS                                                     | New      | 2,600.00        | 600.00          |
| 4                       | TO TUFF COAT DAMAGED AREAS                                                                         | New      | 300.00          | 30.00           |
| 5                       | TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS                                                    | New      | 200.00          | 60.00           |
| 6                       | TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS                                                    | New      | 150.00          | 40.00           |
| 7                       | TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS                                                   | New      | 400.00          | 120.00          |
| 8                       | TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS                                             | New      | 200.00          | 0.00            |
| 9                       | TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS                                                 | New      | 100.00          | 0.00            |
| 10                      | TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS                                            | New      | 150.00          | 0.00            |
| 11                      | TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS                                                           | New      | 200.00          | 30.00           |
| 12                      | TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS | New      | 300.00          | 0.00            |
| Gross Labour Cost (S\$) |                                                                                                    |          | <b>7,700.00</b> | <b>1,560.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >