

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 604S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | BUMPER COVER REAR | TO REPAIR SEE LABOUR | 561.70 | - |
| 1 | FENDER PANEL REAR RH | TO REPAIR SEE LABOUR | 1,933.20 | - |
| 1 | FENDER BRACKET LOWER RH | SERVICEABLE | 11.80 | - |
| 1 | WHEELARCH REAR RH | SERVICEABLE | 275.40 | - |
| | LESS 10% DISCOUNT | | -278.21 | - |
| | | | 2,503.89 | - |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR BUMPER CLIP (SN) | NOT NECESSARY | 65.00 | - |
| 1 | SET FENDER SCREW (SN) | NOT NECESSARY | 60.00 | - |
| 1 | SET CLIP,FRONT FENDER LINER (SN) | NOT NECESSARY | 65.00 | - |
| 2 | WINDSCREEN SEALANT (SN) | NOT NECESSARY | 150.00 | - |
| 1 | WINDSCREEN MOULDING (SN) | NOT NECESSARY | 200.00 | - |
| 1 | WINDSCREEN INNER SPONGE SEAL (SN) | NOT NECESSARY | 130.00 | - |
| | | | 670.00 | - |
| | <u>LABOUR</u> | | | |
| | TOWING FEES. | NOT NECESSARY | 170.00 | - |
| | TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 300.00 | - |
| | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT. | NOT NECESSARY | 220.00 | - |
| | TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR. | NOT NECESSARY | 300.00 | - |
| | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR. | NOT NECESSARY | 380.00 | - |
| | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER COVER REAR AND FENDER PANEL REAR RH. | | 1,400.00 | 150.00 |
| | TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS. | NOT NECESSARY | 240.00 | - |

Report Ref No. CS/GAI21000895/Ktf3e2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

590.00

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|-------------------|
| | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. | | 1,400.00 | 440.00 |
| | TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING. | NOT NECESSARY | 170.00 | - |
| | TO CHECK ELECTRICAL LIGHTING CONCERNED. | NOT NECESSARY | 170.00 | - |
| | | | 4,750.00 | 590.00 |
| | GRAND TOTAL | | 7,923.89 | 590.00 |

Report Ref No. CS/GAI21000895/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser