

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No: 199607198R GST Reg. No. 19-9607198-R | | | | |
|---|---|--|-----------------|--------------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | Re | f: CS/AGI21000898/Atf3n2 | |
| | (BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924 | INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE | Da | ite: 11/06/2021 | |
| | | | Co | ode: AGI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SLC 591C | Veh. Inspected | SJJ 9932E | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | C10008714/ST | Excess (\$) | 0.00 | |
| | Assign From | IVY RATILLA | Assign Date | 19/01/2021 | |
| 2. | 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | MERCEDES BENZ GLC300 | c.c | 1991 | |
| | Engine No. | HIDDEN | Year of Reg. | 2020 | |
| | Chassis No. | WDC2533842F716053 | Colour | SILVER | |
| | Odometer | 25303 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. | 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 235/55 R19 | PIRELLI | 6 mm | |
| | L/H Front Tyre | 235/55 R19 | PIRELLI | 6 mm | |
| | R/H Rear Tyre | 235/55 R19 | PIRELLI | 6 mm | |
| | L/H Rear Tyre | 235/55 R19 | PIRELLI | 6 mm | |
| 4. Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | | |
| | Accident Date | 15/01/2021 | Inspection Date | 21/01/2021 | |
| | Survey held at | STK AUTO (S) PTE LTD | | | |
| | | 8 KAKI BUKIT AVE 4 #03-21 PREMIER@KAKI BUKIT SSINGAPORE 415875 | | | |
| 5a. | . Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: