LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000906/GQD3E2

Date: 29/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No: SKW4107Z Insured Vehicle No: SDH8113R

Date of Loss: 13/01/2021 Nature of Claim: TP Claim No: 8854121754SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW4107Z

 Make & Model:
 HONDA VEZEL, 1.5 X CVT (A)
 Engine No:
 L15B4023256

 Reg. Date:
 28/10/2015 (Man. Year: 2015)
 Chassis No:
 RU11103256

 Colour:
 White
 Odometer:
 96898 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Estimated Period of Repair:

Date of Assignment: 19/01/2021

Date Inspected: 19/01/2021 Inspected At: BLK 3022A Ubi Road 1, #01-51

Singapore 408716

Evergum Auto Services (HQ)

Singapore 4087

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

2.0 days

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	0.00 F	*-F
2	1	*REAR BUMPER SIDE	Repair	0.00 F	*-F
3	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*-F
4	1	*REAR LH FENDER PROTECTOR	Necessary	0.00 F	*-F
5	1	*REAR RH FENDER PROTECTOR	Necessary	0.00 F	*-F
F=Fra	anchise part.		_		
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted d	uring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >