

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000907/GQF3E2

Date: 29/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBK4356R

Insured Vehicle No : GBH5676B

Date of Loss: 18/01/2021

Nature of Claim: TP

Claim No: 3318895468SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK4356R**

Make & Model: TOYOTA HIACE, 3.0 (A)

Engine No: 1KDB039307

Reg. Date: 29/07/2020 (Man. Year: 2020)

Chassis No: JTFHT02P109990003

Colour: Silver

Odometer: 25716 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/01/2021

Date Inspected: 20/01/2021 Inspected At:

Tk Car Repairs (HQ)
176 SIN MING DRIVE, 01-12 SIN MING
AUTOCARE
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
3	1		*REAR END PANEL	Buckled	0.00 F	*- F
4	1		*TAILGATE	Buckled	0.00 F	*- F
5	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
6	1		*TAILGATE OUTER HANDLE	Scratched	0.00 F	*- F
7	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
8	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
9	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F
10	1		*REAR WIPER MOTOR COVER	Cut	0.00 F	*- F
11	3		*STICKER	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >