




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | |
|---|------------------------------|---------------------|---|--|
| SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623 | | | Ref: CS3/SMO21000908/QKtd3e2 Date: 08/02/2021 Code: SMO | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| Insured Veh. | SMF 953P | Veh. Inspected | SMW 1313R | |
| Policy No. | D20MTPV01013212 | Coverage (\$) | 0.00 | |
| Claim No. | CMTD2100207/GPL | Excess (\$) | 0.00 | |
| Assign From | GRACE TEO | Assign Date | 19/01/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | MERCEDES BENZ E200 | c.c | 1991 | |
| Engine No. | HIDDEN | Year of Reg. | 2017 | |
| Chassis No. | WDD2130422A043271 | Colour | BLACK | |
| Odometer | 222706 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 245/45 R18 | GOODYEAR | 6 mm | |
| L/H Front Tyre | 245/45 R18 | GOODYEAR | 6 mm | |
| R/H Rear Tyre | 245/45 R18 | GOODYEAR | 6 mm | |
| L/H Rear Tyre | 245/45 R18 | GOODYEAR | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. | | |  | |
| 5. General Information | | | | |
| Accident Date | 19/01/2021 | Inspect Date / Time | 19/01/2021 (04:37 PM) | |
| Survey held at | 60 JALAN LAM HUAT, #07-35/36 | | | |
| Repairer | WELLTAC AUTO SPRAY CENTRE | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,000 | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 5 Working Days | | |

Report Ref No. CS3/SMO21000908/QKtd3e2

Inspected By

KSC

KONG SENG CHEONG

Licensed Appraiser

KK

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.