

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21000916/AQF3E2

Date: 11/08/2021

REFERENCE

Insured/Claimant: TONG SENG FATT DAVID Policy No: 2070051671
Date of Loss: 18/01/2021 Nature of Claim: OD Claim No: 5142689142SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV1006D**
Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CHZC35246
Reg. Date: 25/02/2020 (Man. Year: 2019) Chassis No: WAUZZZ8V9LA002732
Colour: Grey Odometer: 14905 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$105,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	69,282.00	47,904.80	21,377.20	30.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	25,064.00	15,854.00	9,210.00	36.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	94,346.00	63,758.80	30,587.20	32.42
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	94,046.00	63,458.80	30,587.20	32.52
+ GST 7.00/7.00% (S\$)	6,583.22	4,442.12	2,141.10	32.52
Nett Amount (S\$)	100,629.22	67,900.92	32,728.30	32.52

INSPECTION

Date of Assignment: 19/01/2021
Date Inspected: 19/01/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 23.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Damaged	78.00 FS	*60.96 FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Cracked	160.00 FS	*128.00 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	536.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Cracked	594.00 FS	*474.40 FS
7	2		*FRONT BUMPER COVER TRIM - LH / RH	Not Necessary	326.00 FS	*- FS
8	2		*WHEEL HOUSING LINER ADAPTER - LH / RH	Not Necessary	76.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	191.00 FS	*152.40 FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Cut	376.00 FS	*300.00 FS
12	1		*FRONT REINFORCEMENT BEAM	Bent	795.00 FS	*636.00 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	189.00 FS	*151.20 FS
14	1		*FOAM FILLER PIECE COVER	Deformed	122.00 FS	*97.20 FS
15	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
16	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.88 FS
17	1		*SIGNAL HORN - LH HIGH TONE	Not Necessary	200.00 FS	*- FS
18	1		*SIGNAL HORN - RH LOW TONE	Not Necessary	200.00 FS	*- FS
19	2		*FRONT FENDER - LH / RH	Distorted	1,702.00 FS	*1,360.80 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
21	2		*FRONT FENDER CENTRE BRACKET - LH / RH	Damaged	78.00 FS	*61.44 FS
22	2		*FRONT FENDER BRACKET - LH / RH	Damaged	56.00 FS	*43.68 FS
23	2		*FRONT FENDER BRACE - LH / RH	Bent	192.00 FS	*152.96 FS
24	2		*WHEEL HOUSING LINER - LH / RH	Not Necessary	338.00 FS	*- FS
25	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
26	1		*BONNET	Distorted	3,134.00 FS	*2,507.20 FS
27	1		*BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
28	2		*BONNET LID HINGE - LH / RH	Bent	124.00 FS	*97.76 FS
29	1		*BONNET GAS FILLED STRUT	Not Necessary	104.00 FS	*- FS
30	1		*BONNET CATCH HOOK	Bent	90.00 FS	*71.28 FS
31	2		*BONNET STRIKER - LH / RH	Bent	220.00 FS	*175.20 FS
32	1		*BONNET EDGE PROTECTION	Deformed	28.00 FS	*22.00 FS
33	2		*TOP FENDER LEDGE COVER - LH / RH	Not Necessary	82.00 FS	*- FS
34	1		*BONNET CATCH HOOK	Bent	63.00 FS	*50.32 FS
35	2		*BONNET LID LOCK	Damaged	427.00 FS	*341.60 FS
36	1		*BONNET BOWDEN CABLE - CENTRE	Damaged	58.00 FS	*46.00 FS
37	1		*BONNET LID LOCK CABLE	Not Necessary	74.00 FS	*- FS
38	1		*BONNET SOUND ABSORBER	Crumpled	219.00 FS	*175.20 FS
39	1		*PLENUM CHAMBER COVER	Not Necessary	179.00 FS	*- FS
40	2		*LED HEADLIGHT - LH / RH	Cracked	10,910.00 FS	*8,728.00 FS
41	2		*LIFT CYLINDER - LH / RH	Not Necessary	284.00 FS	*- FS
42	1		*HEADLIGHT WASHER PUMP	Not Necessary	155.00 FS	*- FS
43	1		*WINDSCREEN WASHER PUMP	Not Necessary	125.00 FS	*- FS
44	1		*WASH WATER RESERVOIR	Deformed	206.00 FS	*164.40 FS
45	1		*FRONT FENDER TOP SUPPORT - LH	Not Necessary	72.00 FS	*- FS
46	1		*FRONT FENDER TOP SUPPORT -RH	Not Necessary	74.00 FS	*- FS
47	1		*A-PILLAR CONNECTING PLATE - LH INNER	Buckled	227.00 FS	*181.60 FS
48	1		*A-PILLAR CONNECTING PLATE - RH INNER	Buckled	329.00 FS	*262.80 FS
49	1		*LOCK CARRIER	Cracked	727.00 FS	*581.60 FS
50	1		*AIRCON CONDENSER	Dented	529.00 FS	*422.80 FS
51	1		*REFRIGERANT LINE	Not Necessary	475.00 FS	*- FS
52	1		*REFRIGERANT LINE	Not Necessary	619.00 FS	*- FS
53	1		*REFRIGERANT LINE	Not Necessary	518.00 FS	*- FS
54	1		*EXTERNAL TEMPERATURE SENSOR BRACKET	Damaged	19.00 FS	*14.56 FS
55	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	59.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*RADIATOR	Dented	951.00 FS	*760.40 FS
57	1		*ADDITIONAL RADIATOR	Dented	859.00 FS	*686.80 FS
58	1		*READY MIX COOLANT	Necessary	179.00 FS	*143.04 FS
59	2		*RADIATOR BRACKET	Cracked	82.00 FS	*65.28 FS
60	2		*RADIATOR BUSH - LOWER	Necessary	19.00 FS	*15.04 FS
61	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	50.00 FS	*38.88 FS
62	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Deformed	12.00 FS	*9.44 FS
63	1		*AIR INTAKE AIR DUCT COVER	Cracked	29.00 FS	*22.72 FS
64	1		*AIR INTAKE AIR GUIDE	Cracked	56.00 FS	*44.48 FS
65	1		*AIR INTAKE AIR GUIDE	Deformed	66.00 FS	*52.32 FS
66	1		*INTER COOLER GASKET	Not Necessary	14.00 FS	*- FS
67	1		*AIR INTAKE AIR GUIDE	Cracked	20.00 FS	*15.36 FS
68	1		*AIR INTAKE WATER DRAINAGE HOSE	Not Necessary	33.00 FS	*- FS
69	1		*AIR INTAKE AIR FILTER	Not Necessary	272.00 FS	*- FS
70	1		*AIR INTAKE MANIFOLD - OUTER	Not Necessary	139.00 FS	*- FS
71	1		*AIR INTAKE MANIFOLD - INNER	Not Necessary	666.00 FS	*- FS
72	1		*AIR INTAKE MANIFOLD - INNER SEAL	Not Necessary	14.00 FS	*- FS
73	1		*CHARGE AIR COOLER	Not Necessary	752.00 FS	*- FS
74	1		*CHARGE AIR COOLER SEAL	Not Necessary	14.00 FS	*- FS
75	1		*CHARGE AIR COOLER SEAL	Not Necessary	14.00 FS	*- FS
76	1		*FRONT WINDSCREEN	Cracked	1,072.00 FS	*857.60 FS
77	1		*RAIN SENSOR GEL FOIL	Necessary	137.00 FS	*109.20 FS
78	1		*INTERIOR MIRROR SPRING CLIP	Not Necessary	21.00 FS	*- FS
79	1		*PRIMER	Necessary	20.00 FS	*15.76 FS
80	1		*STEERING WHEEL AIRBAG	Activated	3,421.00 FS	*2,736.80 FS
81	1		*AIRBAG UNIT	Activated	4,414.00 FS	*3,531.20 FS
82	2		*HEAD AIRBAG UNIT - LH / RH	Activated	3,726.00 FS	*2,980.80 FS
83	1		*KNEE AIRBAG UNIT	Activated	1,863.00 FS	*1,490.40 FS
84	1		*AIRBAG CONTROL UNIT	Activated	1,647.00 FS	*1,317.60 FS
85	3		*AIRBAG CRASH SENSOR	Activated	1,167.00 FS	*933.60 FS
86	1		*STEERING WHEEL	Cut	2,374.00 FS	*1,899.20 FS
87	1		*DASHBOARD	Torn	4,259.00 FS	*3,407.20 FS
88	1		*AIR VENT	Not Necessary	151.00 FS	*- FS
89	1		*LOUDSPEAKER COVER	Not Necessary	94.00 FS	*- FS
90	2		*SEAT BELT - LH / RH	Activated	2,206.00 FS	*1,764.80 FS
91	2		*SEAT BELT HEIGHT ADJUSTER	Damaged	383.00 FS	*306.40 FS
92	1		*MOULDED HEADLINER	Crumpled	1,771.00 FS	*1,416.80 FS
93	2		*FRONT FOLDING GRAB HANDLE - LH / RH	Damaged	283.00 FS	*226.40 FS
94	2		*REAR FOLDING GRAB HANDLE - LH / RH	Damaged	284.00 FS	*226.40 FS
95	2		*A-PILLAR TRIM - LH / RH	Cut	322.00 FS	*256.80 FS
96	2		*B-PILLAR TRIM - LH / RH	Not Necessary	434.00 FS	*- FS
97	2		*C-PILLAR TRIM - LH / RH	Not Necessary	302.00 FS	*- FS
98	2		*D-PILLAR TRIM - LH / RH	Cut	232.00 FS	*184.80 FS
99	2		*WATER DEFLECTOR STRIP - LH / RH	Not Necessary	186.00 FS	*- FS
100	2		*TRIM STRIP - LH / RH	Not Necessary	514.00 FS	*- FS
101	2		*WINDOW SLOT SEAL - LH / RH FRONT	Not Necessary	618.00 FS	*- FS
102	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
103	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
104	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
105	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
106	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
107	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
108	1		*SUNDRIES	Necessary	500.00 FS	*144.96 FS
109	1		*LIFT CYLINDER HOSE	Not Necessary	68.00 FS	*- FS
110	1		*RADIATOR FAN WITH FAN RING	Cracked	1,265.00 FS	*1,012.00 FS
			(Supplementary)			

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **69,282.00** **47,904.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
4	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS AND KNEE AIRBAG	New	3,600.00	3,600.00
5	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
6	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	400.00
7	TO RENEW FRONT WINDSCREEN FOIL AND RESET SYSTEM	New	300.00	0.00
8	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	New	200.00	150.00
9	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS	New	560.00	280.00
10	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS. CUT OUT AND REWELD BOTH FRONT FENDER TOP SUPPORTS. TO REPAIR BOTH FRONT DOORS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	9,100.00	5,500.00
11	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH FRONT FENDER TOP SUPPORTS, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT	New	8,200.00	3,500.00
12	TO CARRY OUT PRE AND POST REPAIR DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			25,064.00	15,854.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >