

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21000917/R1QD3E2

**Date:** 12/03/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001623764		
<b>Claimant Vehicle No :</b>	SLT1755B	<b>Insured Vehicle No :</b>	SLH5270U		
Date of Loss:	18/01/2021	Nature of Claim:	TP	Claim No:	252285

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLT1755B</b>	Engine No:	HR12266464B
Make & Model:	NISSAN NOTE, 1.2 CVT (A)	Chassis No:	JN1TAAE12Z0980028
Reg. Date:	20/10/2017 (Man. Year: 2017)	Odometer:	42975 km
Colour:	Grey		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,667.30	5,147.80	14,519.50	73.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,350.00	2,470.00	2,880.00	53.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,017.30</b>	<b>7,617.80</b>	<b>17,399.50</b>	<b>69.55</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>25,017.30</b>	<b>6,100.00</b>	<b>18,917.30</b>	<b>75.62</b>

### INSPECTION

Date of Assignment:	19/01/2021	Xin Yun Auto Pte Ltd (kaki Bukit) (HQ) 8 Kaki Bukit Avenue 4, #05-23 Premier @ Kaki Bukit Singapore 415875
Date Inspected:	20/01/2021 Inspected At:	
Estimated Period of Repair:	9.0 days	

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2021)
<b>Parts:</b>	144	NISSAN NOTE 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLT1755B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	685.00 F	*685.00 FL
2	1		*REAR BUMPER LEFT BRACKET	Bent	78.00 F	*78.00 FL
3	1		*REAR BUMPER RIGHT BRACKET	Bent	78.00 F	*78.00 FL
4	1		*REAR BUMPER LEFT RETAINER	Necessary	65.00 F	*65.00 FL
5	1		*REAR BUMPER RIGHT RETAINER	Necessary	65.00 F	*65.00 FL
6	1		*REAR BUMPER TOW COVER	Serviceable	85.00 F	*- FL
7	1		*BUMPER SPONGE WHITE	Cracked	285.00 F	*190.00 FL
8	1		*WHEEL COWLING LEFT	Serviceable	110.00 F	*- FL
9	2		*WHEEL COWLING RIGHT	Serviceable	110.00 F	*- FL
10	1		*REAR BOOT - TAILGATE	Bent	1,500.00 F	*1,500.00 FL
11	1		*REAR TAILGATE RUBBER GARNISH	Cracked	372.20 F	*338.00 FL
12	1		*TAILGATE INTERNAL TRIM COVER	Cracked	385.00 F	*319.00 FL
13	1		*TAILGATE LOGO NISSAN	Necessary	95.00 F	*65.00 FL
14	1		*TAILGATE HOLDER / PULL POCKET	Serviceable	85.00 F	*- FL
15	1		*REAR TAILGATE EMBLEM / MODEL	Necessary	105.00 F	*73.00 FL
16	1		*REAR TAILGATE WEATHERSTRIP	Necessary	275.00 F	*147.00 FL
17	1		*REAR BOOT LOCK MECHANISM	Bent	280.00 F	*280.00 FL
18	1		*WIPPER MOTOR	Serviceable	450.00 F	*- FL
19	1		*REAR END TOP COVER	Deformed	375.00 F	*130.00 FL
20	1		*REAR FENDER TRIM LEFT (INSIDE BOOT)	Deformed	425.00 F	*296.00 FL
21	1		*REAR FENDER TRIM RIGHT (INSIDE BOOT)	Deformed	425.00 F	*296.00 FL
22	1		*FENDER LEFT	Serviceable	685.00 F	*- FL
23	1		*FENDER RIGHT	Serviceable	685.00 F	*- FL
24	1		*ANTENA, ELECTRICAL KEY	Serviceable	88.00 F	*- FL
25	2		*REAR TAILGATE NO PLATE LAMP	Serviceable	65.00 F	*- FL
26	1		*REAR LEFT TAILLAMP	Cracked	525.00 F	*435.00 FL
27	1		*REAR RIGHT TAILLAMP	Cracked	525.00 F	*435.00 FL
28	2		*REAR TAILGATE DAMPER / IMPACT BIG GOT SOUNDS	Serviceable	420.00 F	*- FL
29	1		*REAR END PANEL / BENT BADLY EDGE MOLDING / MIDDLE PANEL SIDE MOLDING	Bent	865.30 F	*530.00 FL
30	2		*COMES WITH 2 METAL MOLDING AT BOTH SIDE / BORKEN	Serviceable	360.00 F	*- FL
31	1		*GUTTER SIDE PANEL LEFT	Serviceable	685.00 F	*- FL
32	1		*GUTTER SIDE PANEL RIGHT	Serviceable	685.00 F	*- FL
33	1		*FLOOR PANEL CONTROL / SPARE TYRE PANEL	Repair	885.40 F	*- FL
34	1		*FLOOR SIDE PANEL LEFT	Repair	285.00 F	*- FL
35	1		*FLOOR SIDE PANEL RIGHT	Repair	285.00 F	*- FL
36	1		*REAR EXHAUST MUFFLER ASSY DENT	Bent	680.00 F	*552.00 FL
37	3		*REAR EXHAUST MUFFLER MOUNDING	Necessary	90.00 F	*90.00 FL
38	1		*WINDSCREEN	Not Necessary	1,500.00 F	*- FL
39	1		*WINDSCREEN MOULDING	Necessary	280.00 F	*193.00 FL
40	1		*WINDSCREEN RUBBER	Not Necessary	225.00 F	*- FL
41	1		*TOOL BOX	Deformed	480.40 F	*164.00 FL
42	1		*RR BODY MAIN METAL FRAME 1 / RIGHT SIDE DENT BADLY	Repair	985.00 F	*- FL
43	10		*REAR BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	6		*REAR END LOWER PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
45	1		*REAR END LOWER PANEL SEALANT	Necessary	120.00 FS	*40.00 FS
46	8		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
47	6		*REAR TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
48	1		*REAR FLOOR PANEL INSULATOR PAD	Not Necessary	150.00 FS	*- FS
49	1		*REAR FLOOR PANEL SEALANT	Not Necessary	120.00 FS	*- FS
50	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
51	3		*REAR WINDSCREEN MOUNDING	Necessary	320.00 FS	*- FS
52	2		*REAR BUMPER REVERSE SENSOR	Serviceable	250.00 FS	*- FS
53	1		*REAR NO PLATE WITH GARNISH	Scratched	80.00 FS	*35.00 FS
54	1		*REAR END CAMERA	Serviceable	450.00 FS	*- FS
55	1		*REVERSE SENSOR	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>19,667.30</b>	<b>7,249.00</b>
<b>- List Item Discount on L Items 0.00/30.00% (\$)</b>	<b>0.00</b>	<b>2,101.20</b>
<b>Total Parts (\$)</b>	<b>19,667.30</b>	<b>5,147.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS, MAIN BODY FRAME RR FRAME DAMAGED	New	2,500.00	900.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION, BOOT INSIDE OUT, BUMPER, RIGHT FENDER DENT, MAIN FRAME METAL, REAR END PANEL, GUTTER SIDE PANEL FOR LEFT AND RIGHT	New	1,600.00	1,000.00
3	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	40.00
4	TO REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	200.00	120.00
5	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA INCLUDING BEHIND SPARE TYRE AREA	New	250.00	80.00
6	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	60.00
7	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	250.00	80.00
8	TO REMOVE AND INTERAL SIDE FENDER TRIMS TO FACILITATE THE REPAIR	New	180.00	60.00
9	TO REMOVE AND INSTALL REAR CAMERA	New	80.00	60.00
10	TO REMOVE AND INSTALL REAR WHEEL COWLING	New	80.00	40.00
11	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,350.00</b>	<b>2,470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >