

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 23 Feb 2021

Preliminary Advice

Insured Vehicle No	: SLH5270U		
TP Vehicle No	: SLT1755B	Accident Date	: 18/01/2021
Make	: NISSAN NOTE	Assignment Date	: 19/01/2021
Date of Inspection	: 20/01/2021	Est. Duration of Repair	: 8
Inspection At	: XIN YUN AUTO PTE LTD (KAKI BUKIT) (HQ) 8 KAKI BUKIT AVENUE 4, #05-23 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,017.30
Revised Amount	:S\$	7,617.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,617.80
 Lump Sum Repair	 :S\$	 6,100.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.