

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21000918/R1VF3E2

Date: 01/06/2021

REFERENCE

Insured/Claimant: JADA MARINE TRADE & CONSULTANT
Date of Loss: 15/01/2021

Policy No: 2070137233
Nature of Claim: OD Claim No: 6953651638SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV2418X	Engine No:	DCB127910
Make & Model:	AUDI Q8, 3.0 TFSI QU TIP (A)	Chassis No:	WAUZZZF13KD043757
Reg. Date:	22/09/2020 (Man. Year: 2019)	Odometer:	7339 km
Colour:	Black		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$357,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	285/45 R21	Rear Tyre Size:	285/45 R21
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	55,148.00	24,234.80	30,913.20	56.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,822.00	10,692.00	7,130.00	40.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	72,970.00	34,926.80	38,043.20	52.14
+ GST 7.00/7.00% (S\$)	5,107.90	2,444.88	2,663.02	52.14
Nett Amount (S\$)	78,077.90	37,371.68	40,706.22	52.14

INSPECTION

Date of Assignment: 19/01/2021

Date Inspected: 19/01/2021 Inspected At:

24 Benoi Sector

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,724.00 FS	*2,179.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	378.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - RH	Cracked	120.00 FS	*95.60 FS
4	1		*FRONT BUMPER FRAME - RH	Serviceable	82.00 FS	*- FS
5	1		*FRONT BUMPER COVER - RH	Serviceable	82.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - CENTRE	Serviceable	278.00 FS	*- FS
7	1		*FRONT BUMPER TRIM - CENTRE	Serviceable	182.00 FS	*- FS
8	1		*FRONT BUMPER GRILLE	Serviceable	206.00 FS	*- FS
9	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Serviceable	210.00 FS	*- FS
10	1		*FRONT BUMPER UNDERRUN BAR	Serviceable	807.00 FS	*- FS
11	1		*FRONT SPOILER - RH	Deformed	211.00 FS	*168.80 FS
12	1		*FRONT BUMPER TRIM	Serviceable	245.00 FS	*- FS
13	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Scratched	183.00 FS	*146.40 FS
14	2		*ULTRASOUND SENSOR SUPPORT - LH / RH	Serviceable	58.00 FS	*- FS
15	1		*RADIATOR GRILLE	Serviceable	2,500.00 FS	*- FS
16	1		*RADIATOR GRILLE COVER - CENTRE	Serviceable	72.00 FS	*- FS
17	2		*RADIATOR GRILLE COVER - LH / RH	Serviceable	30.00 FS	*- FS
18	2		*FRONT BUMPER GUIDE SECTION - RH	Cracked	44.00 FS	*35.12 FS
19	1		*FRONT BUMPER FOAM FILLER PIECE	Serviceable	171.00 FS	*- FS
20	1		*FRONT BUMPER CARRIER	Serviceable	964.00 FS	*- FS
21	1		*FRONT BUMPER BRACKET - RH	Serviceable	34.00 FS	*- FS
22	1		*FRONT BUMPER COVER	Cut	131.00 FS	*104.40 FS
23	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
24	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
25	1		*FRONT PARKING AID SENSOR	Serviceable	242.00 FS	*- FS
26	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
27	1		*FRONT FENDER - RH	Bent	2,310.00 FS	*1,848.00 FS
28	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
29	1		*FRONT FENDER BRACE - RH	Bent	152.00 FS	*121.60 FS
30	1		*FRONT FENDER BRACKET - RH	Serviceable	65.00 FS	*- FS
31	1		*FRONT WHEEL HOUSING LINER - RH	Serviceable	249.00 FS	*- FS
32	1		*REAR WHEEL HOUSING LINER - RH	Deformed	249.00 FS	*198.80 FS
33	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	73.00 FS	*- FS
34	1		*FRONT SPOILER - RH	Serviceable	68.00 FS	*- FS
35	1		*HEADLAMP COVER - RH	Serviceable	102.00 FS	*- FS
36	1		*HEADLIGHT MOUNTING - RH	Cracked	118.00 FS	*94.40 FS
37	1		*LED HEADLIGHT - RH	Scratched	12,792.00 FS	*10,233.60 FS
38	1		*LIFT CYLINDER - RH	Serviceable	198.00 FS	*- FS
39	2		*FRONT WHEEL COVER - LH / RH	N/S Necessary / O/SScratched	1,150.00 FS	*920.00 FS
40	1		*S-LINE INSCRIPTION	Necessary	128.00 FS	*102.00 FS
41	1		*BONNET	Not Necessary	4,978.00 FS	*- FS
42	1		*BONNET ATTACHMENT PARTS	Not Necessary	126.00 FS	*- FS
43	2		*BONNET LID HINGE - LH / RH	Not Necessary	344.00 FS	*- FS
44	2		*BONNET IMPACT PROTECTION - LH / RH	Not Necessary	90.00 FS	*- FS
45	1		*BONNET IMPACT PROTECTION - CENTRE	Not Necessary	30.00 FS	*- FS
46	1		*BONNET STRIKER - RH	Not Necessary	120.00 FS	*- FS
47	1		*BONNET LID LOCK	Not Necessary	214.00 FS	*- FS
48	1		*LOCK CARRIER	Cracked	1,218.00 FS	*974.40 FS
49	1		*RADIATOR AIR GUIDE - RH	Serviceable	42.00 FS	*- FS
50	1		*CHARGE AIR COOLER	Bent	1,002.00 FS	*801.60 FS
51	1		*CHARGE AIR COOLER AIR GUIDE	Cracked	89.00 FS	*70.56 FS
52	1		*READY MIX COOLANT	Necessary	179.00 FS	*143.04 FS
53	1		*FRONT ALUMINIUM RIM - RH	Scratched	3,552.00 FS	*2,841.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*SUPPORT FRAME	Serviceable	3,846.00 FS	*- FS
55	1		*FRONT WISHBONE LINK	Bent	747.00 FS	*597.20 FS
56	1		*SUSPENSION GUIDE - RH FRONT	Bent	703.00 FS	*562.00 FS
57	2		*FRONT UPPER CONTROL ARM - RH UPPER / LOWER	Serviceable	720.00 FS	*- FS
58	1		*WHEEL BEARING HOUSING - RH	Bent	811.00 FS	*648.40 FS
59	1		*SWIVEL JOINT	Bent	216.00 FS	*172.80 FS
60	1		*WHEEL HUB	Bent	479.00 FS	*383.20 FS
61	1		*DOUBLE ANGLE BALL BEARING	Necessary	254.00 FS	*202.80 FS
62	1		*SUSPENSION FORKS - RH	Bent	366.00 FS	*292.40 FS
63	1		*COUPLING ROD	Serviceable	127.00 FS	*- FS
64	1		*ANTI-ROLL BAR	Serviceable	516.00 FS	*- FS
65	1		*GAS STRUT	Serviceable	3,290.00 FS	*- FS
66	1		*DRIVE SHAFT	Serviceable	2,480.00 FS	*- FS
67	1		*FRONT SPEED SENSOR	Serviceable	110.00 FS	*- FS
68	1		*TRACK ROD	Bent	134.00 FS	*106.80 FS
69	1		*TIE ROD END - RH	Bent	195.00 FS	*156.00 FS
70	1		*FRONT NO PLATE	Serviceable	60.00 FS	*- FS
71	1		*SUNDRIES	Necessary	400.00 FS	*34.08 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 55,148.00 24,234.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
3	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	450.00	300.00
4	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVEDPARTS REMOVED	New	6,300.00	3,000.00
6	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER RHS, RHS FRONT FENDER, BONNET, HINGES, BOTH FRONT WHEEL ARCH TRIMS AND RHS FRONT DOOR	New	5,800.00	2,400.00
7	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT TEST	New	520.00	520.00
8	TO TOW BACK VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			17,822.00	10,692.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >