

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Alfred Toh

Date: 02 Feb 2021

## **Preliminary Advice**

Insured Vehicle No	: SGW9599B		
TP Vehicle No	: SKM4382Y	Accident Date	: 14/01/2021
Make	: TOYOTA LEXUS GS300 AUTO	Assignment Date	: 19/01/2021
Date of Inspection	: 20/01/2021	Est. Duration of Repair	: 3
Inspection At	: KENT SENG CAR SERVICES (YISHUN) (HQ) BLK 1016 YISHUN INDUSTRIAL PARK A #01-238 SINGAPORE 768758		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,973.60
Revised Amount	:S\$	6,312.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,312.60

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : SURVEY ON WP