

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000924/APA3Q2
Date: 08/07/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070056931
Claimant Vehicle No :	SJJ8005M	Insured Vehicle No :	SMT1056Z
Date of Loss:	19/01/2021	Nature of Claim:	TP
		Claim No:	8769015323SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ8005M	Engine No:	2ZR0B53537
Make & Model:	TOYOTA VOXY HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800319870
Reg. Date:	18/06/2018 (Man. Year: 2018)	Odometer:	138151 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,655.78	7,363.32	7,292.46	49.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,320.00	2,610.00	2,710.00	50.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,975.78	9,973.32	10,002.46	50.07
Approved Total (Overridden) (S\$)		8,000.00		

Nett Amount (S\$)	19,975.78	8,000.00	11,975.78	59.95
+ Car Rental (8.0 x S\$120.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,996.45		
Global Sum Settlement (S\$)		8,900.00		

INSPECTION

Date of Assignment: 19/01/2021

Date Inspected: 20/01/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Ishare Auto Pte. Ltd. (HQ)
8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT
Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,339.31 FL	*1,025.00 FL
2	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	28.10 FL	*- FL
3	1		*REAR BUMPER REFLECTOR	O/S Cracked	251.20 FL	*125.60 FL
4	2		*REAR BUMPER SIDE RETAINER	Necessary	291.60 FL	*291.60 FL
5	1		*TAILGATE	Distorted	1,812.70 FL	*1,712.00 FL
6	1		*TAILGATE OUTER MOULDING	Cracked	767.80 FL	*687.00 FL
7	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	130.80 FL	*- FL
8	1		*TAILGATE LOGO	Necessary	67.80 FL	*67.80 FL
9	1		*TAILGATE INNER HOLDER	Deformed	74.80 FL	*74.80 FL
10	2		*TAILGATE STOPPER	Not Necessary	57.20 FL	*- FL
11	2		*TAILGATE DAMPER	Not Necessary	653.60 FL	*- FL
12	1		*TAILGATE TOP LOCK	Damaged	452.60 FL	*368.00 FL
13	1		*TAILGATE LOWER LOCK	Not Necessary	36.70 FL	*- FL
14	1		*TAILGATE INNER TRIM	Cracked	570.30 FL	*570.30 FL
15	1		*TAILGATE DETECTOR	Cracked	175.20 FL	*175.20 FL
16	1		*TAILGATE DETECTOR WIREHARNES	Not Necessary	287.10 FL	*- FL
17	2		*TAILGATE SIDE INNER TRIM	Not Necessary	259.60 FL	*- FL
18	1		*TAILGATE WEATHERSTRIP	Cut	375.10 FL	*375.10 FL
19	1		*TAILGATE WINDSCREEN GLASS C/W MOULDING	Not Necessary	1,198.10 FL	*145.00 FL
20	2		*TAIL LAMP	Not Necessary	1,706.60 FL	*- FL
21	2		*TAIL LAMP LOWER GARNISH	Cracked	344.40 FL	*344.40 FL
22	2		*TAIL LAMP LOWER PANEL	Repair	257.20 FL	*- FL
23	2		*TAIL LAMP LOWER GARNISH RETAINER	Not Necessary	321.40 FL	*- FL
24	2		*REAR FENDER INNER TRIM	Cracked	1,046.20 FL	*1,046.20 FL
25	2		*REAR FENDER COWLING	Not Necessary	230.20 FL	*- FL
26	1		*REAR END PANEL	Distorted	715.80 FL	*715.80 FL
27	1		*REAR END PANEL TOP GARNISH	Deformed	158.60 FL	*158.60 FL
28	1		*REAR FLOOR PANEL	Repair	698.70 FL	*- FL
29	1		*REAR FLOOR PANEL TOP BOARD	Cracked	1,105.50 FL	*540.00 FL
30	1		*REAR FLOOR PANEL TOP BOARD INNER SUPPORT	Not Necessary	403.20 FL	*- FL
31	1		*REAR FLOOR MAT	Not Necessary	421.60 FL	*- FL
32	1		*REAR JACK COVER GARNISH	Deformed	128.70 FL	*128.70 FL
33	1		*REAR NUMBER PLATE	Bent	80.00 FS	*50.00 FS
34	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
35	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET TAILGATE OUTER MOULDING CLIP	Necessary	30.00 FS	*30.00 FS
37	1		*SET TAILGATE INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
38	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
39	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS
40	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
41	1		*SET TAIL LAMP LOWER GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
42	2		*TAIL LAMP LOWER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
43	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*60.00 FS
44	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
45	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
46	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
47	1		*SET REAR FLOOR MAT CLIP	Not Necessary	60.00 FS	*- FS
48	1		*SET REAR FLOOR INSULATION SEAL	Not Necessary	350.00 FS	*- FS
49	1		*REAR JACK (SPECIAL TYPE)	Not Necessary	180.00 FS	*- FS
50	1		*REVERSE CAMERA	Damaged	450.00 FS	*380.00 FS
51	2		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,747.71	9,501.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,091.93	2,137.78
Total Parts (\$\$)	14,655.78	7,363.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,200.00	1,100.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	80.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	350.00	80.00
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX VIDEO RECORDER	New	80.00	50.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
9	TRANFER TAILGATE MECHANISM	New	80.00	80.00
10	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNIT ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
			Gross Labour Cost (S\$)	5,320.00
				2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >