

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21000928/R1TD3E2

Date: 02/06/2021

REFERENCE

Insured/Claimant:	LEE SHU HUA	Policy No:	1900104268		
Date of Loss:	15/01/2021	Nature of Claim:	OD	Claim No:	4003619905SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD1233A		
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK078751
Reg. Date:	31/05/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF42KA052364
Colour:	Black	Odometer:	23990 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$129,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,022.00	10,637.20	15,384.80	59.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,904.00	6,874.00	6,030.00	46.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,926.00	17,511.20	21,414.80	55.01
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	38,126.00	16,711.20	21,414.80	56.17
+ GST 7.00/7.00% (S\$)	2,668.82	1,169.78	1,499.04	56.17
Nett Amount (S\$)	40,794.82	17,880.98	22,913.84	56.17

INSPECTION

Date of Assignment: 20/01/2021

Date Inspected: 19/01/2021 Inspected At:

24 Benoi Sector

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,787.00 FS	*1,429.60 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	1	*FRONT BUMPER SECURING STRIP	N/S Bent	71.00 FS	*28.16 FS
4	1	*FRONT BUMPER GRILLE - CENTRE	Serviceable	196.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	210.00 FS	*167.60 FS
6	1	*FRONT BUMPER AIR GUIDE - LH	Cracked	63.00 FS	*50.08 FS
7	1	*RADIATOR GRILLE	Serviceable	1,332.00 FS	*- FS
8	1	*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	135.00 FS	*108.00 FS
9	1	*FRONT BUMPER CARRIER	Serviceable	845.00 FS	*- FS
10	1	*FRONT BUMPER FOAM FILLER PIECE	Serviceable	124.00 FS	*- FS
11	1	*FRONT BUMPER TOP COVER	Serviceable	127.00 FS	*- FS
12	1	*FRONT BUMPER GUIDE SECTION - LH	Cracked	36.00 FS	*28.72 FS
13	1	*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
14	1	*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
15	1	*LOCK CARRIER BRACKET	Serviceable	137.00 FS	*- FS
16	2	*LOCK CARRIER BRACKET SUPPORT - LH / RH	Serviceable	58.00 FS	*- FS
17	1	*FRONT PARKING AID SENSOR - INNER / OUTER	Not Working (1Pc Only)	484.00 FS	*195.20 FS
18	4	*FRONT PARKING AID SEAL RING	Necessary	14.00 FS	*11.20 FS
19	1	*HORN - LH HIGH TONE	Serviceable	126.00 FS	*- FS
20	1	*SPRING SHACKLE - LH	Serviceable	29.00 FS	*- FS
21	1	*FRONT FENDER - LH	Bent	767.00 FS	*613.20 FS
22	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
23	1	*FRONT FENDER CLOSING ELEMENT - LH	Necessary	72.00 FS	*57.52 FS
24	1	*FRONT FENDER BRACKET - LH	Bent	35.00 FS	*27.92 FS
25	1	*DEFORMATION ELEMENT BRACKET - LH	Serviceable	49.00 FS	*- FS
26	1	*FRONT FENDER BRACE - LH	Bent	118.00 FS	*94.40 FS
27	1	*WHEEL HOUSING LINER - LH	Deformed	240.00 FS	*191.60 FS
28	1	*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	233.00 FS	*- FS
29	1	*WHEEL SPOILER - LH	Deformed	73.00 FS	*58.40 FS
30	1	*WHEEL SPOILER TRIM - LH	Serviceable	35.00 FS	*- FS
31	1	*STONE CHIP GUARD - LH	Not Necessary	51.00 FS	*- FS
32	1	*TOP FENDER LEDGE COVER - UPPER	Cracked	31.00 FS	*24.64 FS
33	1	*TOP FENDER LEDGE COVER - LOWER	Necessary	23.00 FS	*17.92 FS
34	1	*BONNET	Serviceable	3,246.00 FS	*- FS
35	1	*BONNET ATTACHMENT PARTS	Not Necessary	412.00 FS	*- FS
36	1	*BONNET IMPACT PROTECTION - CENTRE	Not Necessary	28.00 FS	*- FS
37	1	*BONNET IMPACT PROTECTION - LH	Not Necessary	28.00 FS	*- FS
38	1	*BONNET IMPACT PROTECTION - RH	Not Necessary	28.00 FS	*- FS
39	2	*BONNET STRIKER - LH	Not Necessary	50.00 FS	*- FS
40	1	*BONNET LID LOCK	Not Necessary	214.00 FS	*- FS
41	1	*LED HEADLIGHT - LH	Broken	7,693.00 FS	*6,154.40 FS
42	1	*MAIN LIGHT ELECTRONICS POWER MODULE	Serviceable	761.00 FS	*- FS
43	1	*LIGHT CONTROL SYSTEM CONTROL UNIT	Serviceable	751.00 FS	*- FS
44	1	*HEADLIGHT HOSE - LH	Serviceable	36.00 FS	*- FS
45	1	*LIFT CYLINDER - LH	Serviceable	210.00 FS	*- FS
46	1	*LIFT CYLINDER CORRUGATED PIPE	Serviceable	93.00 FS	*- FS
47	1	*LOCK CARRIER	Cracked	1,016.00 FS	*812.80 FS
48	1	*COOLANT REGULATOR SUPPORT	Serviceable	38.00 FS	*- FS
49	1	*READY MIX COOLANT	Necessary	179.00 FS	*143.04 FS
50	1	*RADIATOR AIR GUIDE - OUTER	Serviceable	28.00 FS	*- FS
51	1	*RADIATOR AIR GUIDE - LH	Serviceable	12.00 FS	*- FS
52	1	*RADIATOR AIR GUIDE - UPPER	Serviceable	16.00 FS	*- FS
53	1	*RADIATOR AIR GUIDE - LOWER	Serviceable	22.00 FS	*- FS
54	1	*AIRCON CONDENSER	Serviceable	622.00 FS	*- FS

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
55	1	*TEMPERATURE SENSOR BRACKET	Serviceable	19.00 FS	*- FS
56	1	*PRESSURE PIPE	Serviceable	427.00 FS	*- FS
57	1	*FRONT BUMPER BRACKET - LH	Serviceable	228.00 FS	*- FS
58	1	*WINDOW GUIDE TRIM STRIP	Serviceable	257.00 FS	*- FS
59	1	*WINDOW SLOT SEAL - LH	Not Necessary	307.00 FS	*- FS
60	1	*FRONT NO PLATE	Serviceable	60.00 FS	*- FS
61	1	*SUNDRIES	Not Necessary	400.00 FS	*- FS
62	1	*HEADLIGHT WASHER CYLINDER BRACKET (Supplementary)	Necessary	6.00 FS	*4.80 FS
63	1	*REFRIGERANT PIPE (Supplementary)	Bent	523.00 FS	*418.00 FS
F=Franchise part. S=SpcNett.					
Total Parts (S\$)				26,022.00	10,637.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
4	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	280.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,250.00	2,350.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR AND LHS UPPER A-PILLAR	New	4,400.00	1,650.00
7	TO RENEW LHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT TEST	New	280.00	0.00
8	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK	New	384.00	384.00
9	TO RENEW AIRCON CONDENSER REFRIGERANT PIPE. (Supplementary)	New	280.00	280.00
Gross Labour Cost (S\$)			12,904.00	6,874.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >