

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000929/UBS3Q2
Date: 30/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800010842-03
Claimant Vehicle No :	SLW3180E	Insured Vehicle No :	SCQ1888Z
Date of Loss:	15/01/2021	Nature of Claim:	TP
		Claim No:	9162281232SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW3180E	Engine No:	LEB6541235
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71201018
Reg. Date:	07/02/2018 (Man. Year: 2017)	Odometer:	223890 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,568.12	3,205.12	6,363.00	66.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	1,800.00	1,570.00	46.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,938.12	5,005.12	7,933.00	61.31
Approved Total (Overridden) (S\$)		4,000.00		

Nett Amount (S\$)	12,938.12	4,000.00	8,938.12	69.08
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,507.45		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment: 19/01/2021

Date Inspected: 19/01/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Asia Motorsports Solution Pte Ltd (HQ)
37A Everitt
Singapore 428586

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Dented / Deformed	1,423.70 FL	*972.60 FL
2	2		*REAR BUMPER BRACKET	Not Necessary	86.40 FL	*- FL
3	2		*REAR BUMPER RETAINER	Not Necessary	88.80 FL	*- FL
4	1		*SET REAR BUMPER REFLECTOR	Not Necessary	186.60 FL	*- FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	68.80 FL	*- FL
6	1		*REAR BUMPER LEFT REFLECTOR GARNISH	Not Necessary	93.30 FL	*- FL
7	1		*REAR BUMPER RIGHT REFLECTOR GARNISH	Not Necessary	93.30 FL	*- FL
8	1		*REAR TAILGATE ASSY	Badly Dented	1,892.70 FL	*1,193.00 FL
9	1		*REAR TAILGATE LOCK MECHANISM	Twisted / Shorted	225.10 FL	*225.10 FL
10	1		*REAR TAILGATE LOCK CATCH	Not Necessary	66.70 FL	*- FL
11	1		*REAR TAILGATE CENTRE LOGO	Necessary	68.80 FL	*38.00 FL
12	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	66.40 FL	*66.40 FL
13	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	65.60 FL	*65.60 FL
14	1		*REAR TAILGATE WEATHERSTRIP	Twisted	188.20 FL	*188.20 FL
15	1		*REAR TAILGATE INNER TRIM BOARD	Deformed / Cracked	285.80 FL	*285.80 FL
16	1		*REAR TAILGATE LEFT TAILLAMP	Not Necessary	430.20 FL	*- FL
17	1		*REAR TAILGATE RIGHT TAILLAMP	Not Necessary	430.20 FL	*- FL
18	1		*REAR LEFT TAILLAMP	Not Necessary	776.90 FL	*- FL
19	1		*REAR RIGHT TAILLAMP	Not Necessary	776.90 FL	*- FL
20	1		*REAR END LOWER PANEL	Dented	1,498.60 FL	*546.70 FL
21	1		*REAR END LOWER PANEL TOP GARNISH	Not Necessary	128.80 FL	*- FL
22	1		*REAR EXHAUST MUFFLER ASSY	Not Necessary	1,020.50 FL	*- FL
23	1		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	66.60 FL	*- FL
24	1		*REAR BUMPER CLIPS (12 PCS)	Necessary	65.00 FS	*50.00 FS
25	4		*REAR END LOWER PANEL TOP GARNISH CLIPS	Not Necessary	35.00 FS	*- FS
26	1		*REAR END LOWER PANEL SEALANT	Necessary	150.00 FS	*50.00 FS
27	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
28	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	600.00 FS	*200.00 FS
29	1		*REAR VIEW CAMERA	Not Necessary	450.00 FS	*- FS
30	1		*REAR NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
31	8		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,573.90	3,921.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,005.78	716.28

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	9,568.12
						3,205.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,200.00	600.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,200.00	800.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	120.00	0.00
6	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	180.00	80.00
7	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	60.00
8	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
9	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	120.00
10	TO REMOVE AND INSTALL REAR VIEW CAMERA	New	80.00	0.00
11	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (S\$)			3,370.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >