

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121000930/DTD3N2**Date:** 31/08/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SHA8513J **Insured Vehicle No :** SKX2143B

Date of Loss: 17/01/2021 Nature of Claim: TP Claim No: CDMPG21000094

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA8513J**

Make & Model: HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A) Engine No: D4DFU564087

Reg. Date: 12/11/2015 (Man. Year: 2015) Chassis No: KMHLB41UMGU080545

Colour: Yellow Odometer: 615210 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16

Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,398.92	6,531.20	11,867.72	64.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,290.00	1,470.00	2,820.00	65.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,688.92	8,001.20	14,687.72	64.74
Approved Total (Overridden) (S\$)		6,400.00		
(S\$)	22,688.92	6,400.00	16,288.92	71.79
+ GST 7.00/7.00% (S\$)	1,588.22	448.00	1,140.22	71.79
Nett Amount (S\$)	24,277.14	6,848.00	17,429.14	71.79

INSPECTION

Date of Assignment: 19/01/2021

Date Inspected: 20/01/2021 Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2021)

Parts: 143 HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA8513J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,265.90 FL	*2,265.90 FL
2	1		*BONNET LOCK	Not Necessary	142.40 FL	*- FL
3	1		*FRONT BUMPER COVER	Torn	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SPONGE	Not Necessary	379.20 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	588.40 FL	*- FL
6	1		*FRONT BUMPER GRILLE (LH)	Cut/Deformed	149.20 FL	*149.20 FL
7	1		*FRONT BUMPER LIP	Not Necessary	152.00 FL	*- FL
8	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	44.80 FL	*- FL
9	1		*FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40)	No such part	80.00 FL	*- FL
10	1		*FRONT BUMPER BRACKET (LH)	Broken	49.20 FL	*49.20 FL
11	1		*FRONT BUMPER SIDE BRACKET (LH)	Not Necessary	28.60 FL	*- FL
12	1		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	76.20 FL	*- FL
13	1		*FRONT BUMPER GRILLE AIR DUCT (LH)	Cut	126.20 FL	*126.20 FL
14	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
15	1		*HEADLAMP (LH)	Broken/Cut	2,776.00 FL	*1,388.00 FL
16	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
17	1		*RADIATOR	Not Necessary	1,637.20 FL	*- FL
18	1		*COOLANT	Not Necessary	45.00 FL	*- FL
19	1		*FRONT FENDER (LH)	Dented	663.00 FL	*663.00 FL
20	1		*FRONT FENDER SHIELD (LH)	Torn	174.90 FL	*174.90 FL
21	1		*FRONT FENDER MUDFLAP (LH)	Not Necessary	16.20 FL	*- FL
22	1		*FRONT FENDER RETAINER	Not Necessary	24.60 FL	*- FL
23	1		*AIRCON CONDENSER	Not Necessary	947.80 FL	*- FL
24	1		*FRONT WHEEL RIM (LH)	Not Necessary	650.60 FL	*- FL
25	1		*FRONT WHEEL HUB CAP (LH)	Not Necessary	214.20 FL	*- FL
26	1		*FRONT WHEEL NUT	Not Necessary	6.80 FL	*- FL
27	1		*KNUCKLE ARM (LH)	Not Necessary	1,104.00 FL	*- FL
28	1		*FRONT WHEEL BEARING (LH)	Not Necessary	673.20 FL	*- FL
29	1		*FRONT WHEEL HUB ASSY	Not Necessary	158.60 FL	*- FL
30	1		*FRONT SUSPENSION LOWER ARM (LH)	Not Necessary	595.90 FL	*- FL
31	1		*FRONT SHOCK ABSORBER ASSY (LH)	Not Necessary	684.40 FL	*- FL
32	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	217.60 FL	*- FL
33	1		*FRONT SHOCK ABSORBER FORK (LH)	Not Necessary	212.15 FL	*- FL
34	1		*STG TIE ROD (LH)	Not Necessary	186.40 FL	*- FL
35	1		*STG TIE END (LH)	Not Necessary	125.20 FL	*- FL
36	1		*STABILIZER BAR ASSY	Not Necessary	463.70 FL	*- FL
37	1		*STABILIZER BAR LINK (LH)	Not Necessary	85.90 FL	*- FL
38	1		*ABS SENSOR	Not Necessary	217.90 FL	*- FL
39	1		*FRONT SUSPENSION UPPER ARM (LH)	Not Necessary	250.40 FL	*- FL
40	1		*INTER COOLER	Not Necessary	1,032.50 FL	*- FL
41	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*- FL
42	1		*HOSE C TO INTER COOLER INLET	Not Necessary	294.50 FL	*- FL
43	1		*HEADLAMP (RH)	Mounting Cracked	2,776.00 FL	*1,388.00 FL
44	1		*FRONT TYRE (LH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 22,944.65 8,164.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					4,545.73	1,632.80
Total Parts (S\$)					18,398.92	6,531.20
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	700.00
2	SPRAY PAINTING CHARGE	New	1,000.00	700.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	0.00
7	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	0.00
8	RE-SET FRT ABS SYSTEM	New	200.00	0.00
9	REMOVE/REFIX RADIATOR	New	90.00	0.00
10	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	0.00
11	REMOVE/REFIX FUSE BOX	New	120.00	0.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			4,290.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >