

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000945/DPS3Q2
Date: 08/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070118823
Claimant Vehicle No :	SHC3126R	Insured Vehicle No :	SMU7797Z
Date of Loss:	18/01/2021	Nature of Claim:	TP
		Claim No:	2507606411SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3126R	Engine No:	G4LEJU191233
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU141254
Reg. Date:	01/03/2019 (Man. Year: 2018)	Odometer:	299138 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,356.11	7,212.40	5,143.71	41.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,480.00	1,980.00	3,500.00	63.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,836.11	9,192.40	8,643.71	48.46
+ GST 7.00/7.00% (S\$)	1,248.53	643.47	605.06	48.46

Nett Amount (S\$)	19,084.64	9,835.87	9,248.77	48.46
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
+ Car Rental (7.0 x S\$125.19/day) (S\$)		876.33		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		11,149.65		
Global Sum Settlement (S\$)		11,000.00		

INSPECTION

Date of Assignment: 20/01/2021

Date Inspected: 20/01/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR (LH)	Dented	1,789.90 FL	*1,789.90 FL
2	1		*REAR DOOR RUBBER (LH)	Serviceable	280.00 FL	*- FL
3	1		*REAR DOOR GEAR/REGULATOR (LH)	Not Necessary	367.84 FL	*- FL
4	1		*REAR DOOR POWER MOTOR (LH)	Not Necessary	256.80 FL	*- FL
5	1		*REAR DOOR LOCK ASSY	Serviceable	306.40 FL	*- FL
6	1		*REAR DOOR TRIM BOARD (LH)	Not Necessary	613.60 FL	*- FL
7	1		*REAR DOOR PROTECTOR (LH)	Cut	166.20 FL	*166.20 FL
8	1		*ROCKER PANEL OUTER GARNISH	Cut / Mtg Broken	715.60 FL	*715.60 FL
9	1		*ROCKER PANEL OUTER	Not Necessary	1,799.60 FL	*- FL
10	1		*REAR BUMPER	Cut / Mtg Broken	459.40 FL	*459.40 FL
11	1		*REAR BUMPER SIDE RETAINER (LH)	Serviceable	85.80 FL	*- FL
12	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
13	1		*REAR FENDER (LH)	Dented	1,768.30 FL	*1,768.30 FL
14	1		*REAR TYRE RIM (LH)	Bent / Distorted	1,124.20 FL	*1,124.20 FL
15	1		*REAR WHEEL HUP-CAP (LH)	Cut	346.40 FL	*346.40 FL
16	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*554.00 FL
17	1		*REAR TRAILING ARM (LH)	Distorted	265.40 FL	*265.40 FL
18	1		*REAR ASSIST (LH)	Distorted	227.90 FL	*227.90 FL
19	1		*REAR SHOCK ABSORBER (LH)	Distorted	230.50 FL	*230.50 FL
20	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	133.10 FL	*- FL
21	1		*REAR ABSORBER STOPPER (LH)	Not Necessary	137.60 FL	*- FL
22	1		*REAR ABSORBER COVER (LH)	Not Necessary	175.60 FL	*- FL
23	1		*REAR CROSSMEMBER	Not Necessary	1,468.70 FL	*- FL
24	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
25	1		*STABILIZER LINK (LH)	Not Necessary	147.30 FL	*- FL
26	1		*REAR UPPER ARM (LH)	Distorted	239.50 FL	*239.50 FL
27	1		*REAR LOWER ARM (LH)	Distorted	393.10 FL	*393.10 FL
28	1		*REAR KNUCKLE ARM (LH)	Distorted	538.10 FL	*538.10 FL
29	1		*REAR DOOR TEL NO.STICKER (LH)	Necessary	10.00 FS	*10.00 FS
30	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
31	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
32	1		*REAR TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,356.14	8,980.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,000.03	1,768.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	12,356.11
						7,212.40
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	700.00
2	SPRAY PAINTING CHARGE	New	1,400.00	700.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	120.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
9	RE-SET REAR ABS SYSTEM	New	400.00	0.00
10	REMOVE/REFIX FUEL TANK	New	80.00	0.00
11	REMOVE/REFIX EXHAUST PIPE	New	80.00	0.00
12	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
13	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
14	FOUR WHEEL ALIGNMENT	New	120.00	60.00
15	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (S\$)			5,480.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >