

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000947/GVD3Q2

Date: 09/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900122326
Claimant
Vehicle No : SMF6649D **Insured Vehicle No :** SMN982M
Date of Loss: 16/01/2021 Nature of Claim: TP Claim No: 9095418535SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF6649D**
Make & Model: MERCEDES-BENZ C200, 1.8 (A) Engine No: 27195031184574
Reg. Date: 16/06/2009 (Man. Year: 2008) Chassis No: WDD2040412A258168
Colour: Black Odometer: 197913 km
Engine Capacity: 1796 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/01/2021
Date Inspected: 25/01/2021 Inspected At: Elite Performance (kaki Bukit) (HQ)
No. 68 Kaki Bukit Avenue 6, #01-09
ARK
Singapore 417896
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT NUMBER PLATE	Cut	0.00 F	*- F	
2	1		*FRT NUMBER PLATE BASE	Cut	0.00 F	*- F	
3	1		*FRT NUMBER PLATE GARNISH	Deformed	0.00 F	*- F	
4	1		*FRT BUMPER	Cracked	0.00 F	*- F	
5	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F	
6	1		*FRT BUMPER BRACKET	Broken	0.00 F	*- F	
7	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F	
8	2		*FRT BUMPER MOULDING	Necessary	0.00 F	*- F	
9	1		*FRT BUMPER SENSOR	Not Working	0.00 F	*- F	
10	1		*FRT GRILLE	Cracked	0.00 F	*- F	
11	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F	
12	1		*FRT LH HEADLAMP ASSY	Cut	0.00 F	*- F	
13	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F	
					Total Parts (\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >