

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000948/R1VF3E2

Date: 12/03/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00030512001
Claimant Vehicle No : SFR198Y **Insured Vehicle No :** GBJ5231R
Date of Loss: 19/01/2021 Nature of Claim: TP Claim No: SNM21D200327/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFR198Y**
Make & Model: VOLKSWAGEN TOURAN, 1.4 1.4 TSI CL 5T13NZ (A) Engine No: CZDA33059
Reg. Date: 28/06/2019 (Man. Year: 2019) Chassis No: WVGZZZ1TZKW059334
Colour: Blue Odometer: 22231 km
Engine Capacity: 1395 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,471.86	6,221.94	3,249.92	34.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,110.00	5,870.00	8,240.00	58.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,581.86	12,091.94	11,489.92	48.72
+ GST 7.00/7.00% (S\$)	1,650.73	846.44	804.29	48.72
Nett Amount (S\$)	25,232.59	12,938.38	12,294.21	48.72

INSPECTION

Date of Assignment: 20/01/2021
Date Inspected: 21/01/2021 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934
Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Mar 2021)

Parts: M1-MPV VOLKSWAGEN TOURAN 1.4 1.4 TSI CL 5T13NZ (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFR198Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID	Bent	2,207.90 FS	*2,207.90 FS
2	2		*1K WINDOW ADHESIVE	Necessary	102.22 FS	*102.22 FS
3	1		*ALL PURPOSE CLEANER	Necessary	94.03 FS	*94.03 FS
4	1		*PRIMER	Necessary	27.39 FS	*27.39 FS
5	1		*ACTIVATOR FOR PRECOATED W	Necessary	25.14 FS	*25.14 FS
6	2		*APPLICATOR	Necessary	20.24 FS	*20.24 FS
7	1		*SPOILER SATIN BLACK LHR W/SCREEN SIDE MLDG	Necessary	260.54 FS	*260.54 FS
8	1		*SPOILER SATIN BLACK RHR W/SCREEN SIDE MLDG	Necessary	272.52 FS	*272.52 FS
9	1		*PACKING ADHESIVE REAR NUMBER PLATE PACKING	Necessary	29.20 FS	*29.20 FS
10	4		*RIVETTED CAP NUT	Necessary	9.12 FS	*9.12 FS
11	1		*HOOD LATCH LOCK	Serviceable	158.42 FS	*- FS
12	1		*COVER LOCK SATIN BLACK LOCK COVER	Serviceable	19.79 FS	*- FS
13	1		*GASKET REAR WEATHERSTRIP	Serviceable	317.42 FS	*- FS
14	1		*PUSHBUTTON FOR ELECTRIC	Serviceable	1,470.77 FS	*- FS
15	2		*LED LICENCE PLACE LIGHT	Serviceable	201.34 FS	*- FS
16	1		*VW SIGN BLACK / BRIGHT CHRO	Necessary	105.72 FS	*105.72 FS
17	1		*INSCRIPTION BRIGHT CHROME EMBLEM - TOURAN	Necessary	72.44 FS	*72.44 FS
18	1		*COVER FOR BUMPER PRIMED	Deformed	1,321.12 FS	*1,321.12 FS
19	1		*SPOILER SATIN BLACK	Deformed	323.75 FS	*323.75 FS
20	4		*RIVET	Not Necessary	4.56 FS	*- FS
21	1		*BUMPER REINFORCEMENT	Bent	544.33 FS	*544.33 FS
22	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Cracked	63.48 FS	*63.48 FS
23	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Serviceable	41.17 FS	*- FS
24	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Cracked	41.17 FS	*41.17 FS
25	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Serviceable	33.60 FS	*- FS
26	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Serviceable	33.60 FS	*- FS
27	6		*SPEED NUT	Not Necessary	9.48 FS	*- FS
28	1		*END PLATE END PANEL OUTER	Serviceable	400.18 FS	*- FS
29	4		*WELD STUD	Not Necessary	3.84 FS	*- FS
30	1		*ZINC SPRAY	Not Necessary	62.88 FS	*- FS
31	1		*2K-BODY ADHESIVE	Not Necessary	428.72 FS	*- FS
32	1		*SEALANT CAB BE SPRAYED	Not Necessary	64.15 FS	*- FS
33	1		*REAR NUMBER PLATE	Scratched	80.00 FS	*80.00 FS
34	1		*REVERSE SENSOR	Not Working	400.00 FS	*400.00 FS
35	1		*ADDITIONAL BRAKE LIGHT WI 3RD BRAKE LIGHT	Necessary	221.63 FS	*221.63 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 9,471.86 6,221.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	5,880.00	1,680.00
4	SPRAY PAINT	New	4,800.00	1,600.00
5	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
6	R&R REAR W/SCREEN	New	840.00	840.00
7	R&R REAR LUGGAGE TRIM	New	840.00	420.00
8	REAR WATER LEAK TEST	New	150.00	150.00
Gross Labour Cost (\$)			14,110.00	5,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >