

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21000950/BGS3Q2**Date:** 23/09/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	SMS7223Z	Insured Vehicle No :	YP7408G
Date of Loss:	18/01/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000311

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS7223Z	Engine No:	1ZZ2711533
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100329301
Reg. Date:	07/02/2007 (Man. Year: 2006)	Odometer:	310536 km
Colour:	Red		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	TURANZA 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	TURANZA 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,330.00	1,571.70	4,758.30	75.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	1,850.00	3,150.00	63.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,330.00	3,421.70	7,908.30	69.80
Approved Total (Overridden) (S\$)		2,546.00		

Nett Amount (S\$)	11,330.00	2,546.00	8,784.00	77.53
+ Loss of Use (2.0 x S\$80.00/day) (S\$)		160.00		
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,313.45		

INSPECTION

Date of Assignment: 20/01/2021

Date Inspected: 20/01/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Auburn Auto Pte Ltd (HQ)
176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE
Singapore 575721

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2021)
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMS7223Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Not Damaged	80.00 F	*- FL
2	1		*RIGHT TAIL LIGHT BRACKET	Not Damaged	120.00 F	*- FL
3	1		*END PANEL GARNISH	Not Damaged	230.00 F	*- FL
4	1		*TAIL LAMP LOWER BRACKET	Not Necessary	120.00 F	*- FL
5	1		*REAR RIGHT BUMPER RETAINER	Necessary	180.00 F	*55.60 FL
6	1		*REAR RIGHT TAILLIGHT BRACKET	Not Damaged	120.00 F	*- FL
7	1		*REAR LEFT TAILLIGHT BRACKET	Not Damaged	120.00 F	*- FL
8	1		*REAR RIGHT WHEEL BEARING	Not Damaged	150.00 F	*- FL
9	1		*REAR LEFT WHEEL BEARING	Not Damaged	150.00 F	*- FL
10	1		*SPARE TYRE BOARD	Not Damaged	80.00 F	*- FL
11	1		*BOOTLID WEATHERSTRIP	Not Damaged	120.00 F	*- FL
12	1		*BUMPER BRACKET	Bent	150.00 F	*150.00 FL
13	1		*REAR RIGHT ABSORBER	Not Damaged	230.00 F	*- FL
14	1		*REAR LEFT ABSORBER	Not Damaged	230.00 F	*- FL
15	1		*REAR RIGHT MUDGUARD	Not Damaged	80.00 F	*- FL
16	1		*REAR LEFT MUDGUARD	Not Damaged	80.00 F	*- FL
17	1		*LEFT BOOTLID LAMP	No such part	200.00 F	*- FL
18	1		*RIGHT BOOTLID LAMP	No such part	200.00 F	*- FL
19	1		*LEFT TAIL LIGHT	Broken	200.00 F	*200.00 FL
20	1		*RIGHT TAIL LIGHT	Not Damaged	200.00 F	*- FL
21	1		*BOOT LOCK	Not Damaged	120.00 F	*- FL
22	1		*REAR UNDERCARRIAGE	Not Damaged	900.00 F	*- FL
23	1		*BOOT LID	Dented	650.00 F	*650.00 FL
24	1		*SPARE TYRE PANEL	Not Damaged	120.00 F	*- FL
25	1		*BOOT INTERIOR LINING	Not Damaged	250.00 F	*- FL
26	1		*REAR BUMPER	Dented	450.00 F	*450.00 FL
27	1		*END PANEL	Dented	800.00 F	*590.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
F=Franchise part. L=ListItemDisc.							
					Sub Total (\$\$)	6,330.00	2,095.60
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	523.90
					Total Parts (\$\$)	6,330.00	1,571.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECKING OF WIRING ,LIGHTING AND RESETTING	New	300.00	50.00
2	REMOVE AND REFIT REAR UNDERCARRIAGE	New	500.00	0.00
3	WHEEL ALIGNMENT	New	100.00	0.00
4	REMOVE AND REPLACE DAMAGED PARTS	New	800.00	200.00
5	APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	800.00	400.00
6	WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS ,REPAIRS INCLUDING CUT AND WIELD REALIGN BODY STRUCTURE	New	1,500.00	600.00
7	RESPRAY INCLUDING POLISHING AND WAXING ON THE CHANGED BODY PARTS ,REPAIRED PORTORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
Gross Labour Cost (S\$)			5,000.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >