

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000952/UVD3Q2
Date: 05/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00086812001
Claimant Vehicle No :	SMU4149P	Insured Vehicle No :	GBG564D
Date of Loss:	13/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200230C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU4149P	Engine No:	1NZX814824
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305084606
Reg. Date:	12/11/2008 (Man. Year: 2008)	Odometer:	223216 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,801.50	6,274.45	7,527.05	54.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	2,740.00	2,410.00	46.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,951.50	9,014.45	9,937.05	52.43
Approved Total (Overridden) (S\$)		7,200.00		
Nett Amount (S\$)	18,951.50	7,200.00	11,751.50	62.01

INSPECTION

Date of Assignment:	02/03/2021	
Date Inspected:	20/01/2021	Inspected At: Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	8.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU4149P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Not Necessary	720.80 FL	*- FL
2	1	*FRONT BUMPER BRACKET RH	Not Necessary	97.20 FL	*- FL
3	1	*FRONT BUMPER SIDE RETAINER RH	Not Necessary	68.10 FL	*- FL
4	1	*FRONT BUMPER CLIPS	Not Necessary	60.00 FL	*- FL
5	1	*FRONT RIGHT A-PILLAR (NPA)	Repair	0.00 FL	*- FL
6	1	*FRONT RIGHT FENDER	Badly Dented	680.70 FL	*425.10 FL
7	1	*FRONT RIGHT FENDER QUARTER GARNISH	Scratched	98.50 FL	*82.50 FL
8	1	*FRONT RIGHT FENDER INNER SHIELD	Distorted	275.40 FL	*168.10 FL
9	1	*FRONT RIGHT FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*50.00 FL
10	1	*RIGHT WING MIRROR ASSY WITH LED	Broken	386.40 FL	*386.40 FL
11	1	*FROTN RIGHT HEADLAMP ASSY	Not Necessary	591.50 FL	*- FL
12	1	*FRONT BONNET (NPA)	Not Necessary	0.00 FL	*- FL
13	1	*FRONT RIGHT DOOR	Badly Dented	786.50 FL	*786.50 FL
14	1	*FRONT RIGHT DOOR OUTER PROTECTOR GARNISH	Bent	195.20 FL	*145.50 FL
15	1	*FRONT RIGHT DOOR FRAME STICKER	Necessary	215.60 FL	*68.00 FL
16	1	*FRONT RIGHT DOOR WEATHER STRIP	Necessary	286.70 FL	*166.20 FL
17	1	*FRONT RIGHT DOOR TOP HINGE	Twisted	78.50 FL	*78.50 FL
18	1	*FRONT RIGHT DOOR LOWER HINGE	Twisted	72.60 FL	*72.60 FL
19	1	*FRONT RIGHT DOOR OUTER GLASS CHANNEL MOULDING	Grazed	195.80 FL	*145.80 FL
20	1	*FRONT RIGHT DOOR INNER LOCK	Shorted/Jammed	295.80 FL	*295.80 FL
21	1	*FRONT RIGHT DOOR ACTUATOR	Not Necessary	197.50 FL	*- FL
22	1	*FRONT RIGHT DOOR POWER WINDOW LINKAGE ASSY	Bent/Jammed	476.50 FL	*350.20 FL
23	1	*FRONT RIGHT DOOR INNER TRIMBOARD	Deformed/Torn	425.60 FL	*405.20 FL
24	1	*FRONT RIGHT DOOR INNER TRIMBOARD CLIPS	Necessary	60.00 FL	*50.00 FL
25	1	*FRONT RIGHT DOOR OUTER HANDLE GARNISH	Cut	214.90 FL	*188.20 FL
26	1	*FRONT RIGHT DOOR GLASS	Not Necessary	680.00 FL	*- FL
27	1	*REAR RIGHT DOOR	Badly Dented	720.80 FL	*720.80 FL
28	1	*REAR RIGHT DOOR OUTER PROTECTOR GARNISH	Bent	194.60 FL	*145.50 FL
29	1	*REAR RIGHT DOOR FRAME STICKER	Necessary	195.40 FL	*68.00 FL
30	1	*REAR RIGHT DOOR WEATHER STRIP	Necessary	296.20 FL	*162.50 FL
31	1	*REAR RIGHT DOOR TOP HINGE	Not Necessary	78.50 FL	*- FL
32	1	*REAR RIGHT DOOR LOWER HINGE	Not Necessary	72.60 FL	*- FL
33	1	*REAR RIGHT DOOR OUTER GLASS CHANNEL MOULDING	Not Necessary	198.40 FL	*- FL
34	1	*REAR RIGHT DOOR INNER LOCK	Not Necessary	294.50 FL	*- FL
35	1	*REAR RIGHT DOOR ACTUATOR	Not Necessary	197.50 FL	*- FL
36	1	*REAR RIGHT DOOR POWER WINDOW LINKAGE ASSY	Bent/Jammed	456.80 FL	*345.20 FL
37	1	*REAR RIGHT DOOR INNER TRIMBOARD	Deformed/Cracked	425.60 FL	*400.80 FL
38	1	*REAR RIGHT DOOR INNER TRIMBOARD CLIPS	Necessary	60.00 FL	*50.00 FL
39	1	*REAR RIGHT DOOR OUTER HANDLE GARNISH	Cut	198.70 FL	*188.20 FL
40	1	*REAR RIGHT DOOR GLASS	Not Necessary	620.00 FL	*- FL
41	1	*REAR RIGHT FENDER	Badly Dented	980.70 FL	*845.20 FL
42	1	*REAR RIGHT FENDER INNER SHIELD	Not Necessary	295.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR WINDSCREEN MOULDING	Necessary	195.80 FL	*112.30 FL
44	1		*REAR BUMPER	Repair	690.50 FL	*- FL
45	1		*REAR BUMPER BRACKET	Not Necessary	97.80 FL	*- FL
46	1		*REAR BUMPER SIDE RETAINER	Not Necessary	95.20 FL	*- FL
47	1		*REAR BUMPER CLIPS	Not Necessary	60.00 FL	*- FL
48	1		*FRONT RIGHT SUSPENSION	Not Necessary	486.50 FL	*- FL
49	1		*FRONT RIGHT LOWER ARM	Not Necessary	425.10 FL	*- FL
50	1		*FRONT RIGHT KNUCKLE ARM	Bent	586.70 FL	*544.20 FL
51	1		*FRONT RIGHT HUB BEARING	Necessary	453.20 FL	*225.30 FL
52	1		*RIGHT ROCKER	Repair	685.70 FL	*- FL
53	1		*RIGHT ROCKER CLIPS	No such part	60.00 FL	*- FL
54	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	195.00 FS	*30.00 FS
55	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
56	1		*FRONT RIGHT RIM	Bent	950.00 FS	*450.00 FS
57	1		*FRONT RIGHT TYRE	Serviceable	320.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **17,887.00** **8,192.60**
- List Item Discount on L Items 25.00/25.00% (\$\$) 4,085.50 1,918.15

Total Parts (\$\$) **13,801.50** **6,274.45**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR & RENEW ON AFFECTED ACCIDENT AREAS	New	1,600.00	1,000.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,800.00	1,200.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	150.00	120.00
5	TO CONDUCT ALL WHEEL ALIGNMENT	New	250.00	60.00
6	TO REMOVE & INSTALL FRONT RH DOOR COMPONENTS	New	200.00	50.00
7	TO REMOVE & INSTALL REAR RH DOOR COMPONENTS	New	200.00	50.00
8	TO REMOVE & INSTALL FRONT RH UNDERCARRIAGE COMPONENTS	New	250.00	120.00
9	TO CONDUCT ECU SETTING & RESET TO SPECIFICATION	New	450.00	0.00
10	TO RUST PROOF AFFECTED AREAS	New	200.00	120.00
Gross Labour Cost (\$\$)			5,150.00	2,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >