

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21000954/AEA3Q2**Date:** 28/03/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100495512
Claimant Vehicle No :	SLF5078U	Insured Vehicle No :	SLJ8314Y
Date of Loss:	18/01/2021	Nature of Claim:	TP
		Claim No:	1795758451SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF5078U	Engine No:	R18A13800176
Make & Model:	HONDA STREAM, 1.8 L SUNROOF (A)	Chassis No:	JHMRN68809S200179
Reg. Date:	11/11/2008 (Man. Year: 2008)	Odometer:	220060 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,237.76	3,750.88	2,486.88	39.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	2,610.00	600.00	18.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,447.76	6,360.88	3,086.88	32.67
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	9,447.76	5,000.00	4,447.76	47.08
+ GST 7.00/7.00% (S\$)	661.34	350.00	311.34	47.08
Nett Amount (S\$)	10,109.10	5,350.00	4,759.10	47.08
+ Car Rental (10.0 x S\$120.00/day) (S\$)		1,200.00		
Nett Liability (S\$)		6,550.00		

INSPECTION

Date of Assignment:	20/01/2021	Ms Car Auto Pte Ltd (HQ)
Date Inspected:	20/01/2021 Inspected At:	8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
Estimated Period of Repair:	8.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	832.90 FL	*688.00 FL
2	1		*REAR BUMPER BRACKET LH	Not Necessary	38.20 FL	*- FL
3	1		*REAR BUMPER RETAINER L+R H	Necessary	36.80 FL	*36.80 FL
4	6		*REAR BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
5	1		*REAR FENDER LH	Distorted	664.60 FL	*664.60 FL
6	1		*REAR FENDER INNER TRIM L+R H	Cracked	352.20 FL	*352.20 FL
7	6		*REAR FENDER INNER TRIM CLIP P LH	Necessary	30.00 FL	*30.00 FL
8	1		*TAIL LAMP LH	Cracked	851.80 FL	*358.00 FL
9	1		*TAIL LAMP PANEL LH	Dented	161.80 FL	*161.80 FL
10	4		*TAIL LAMP CLIP L+H	Not Necessary	20.00 FL	*- FL
11	1		*REAR END PANEL	Dented	426.70 FL	*426.70 FL
12	1		*REAR END PANEL TOP GARNISH	Not Necessary	136.70 FL	*- FL
13	1		*REAR END PANEL BOTTOM GARNISH	Not Necessary	82.90 FL	*- FL
14	1		*REAR END PANEL TOOLS GARNISH	Not Necessary	188.20 FL	*- FL
15	1		*ABSORBER -LH	Bent	385.00 FL	*385.00 FL
16	1		*KNUCKLE BEARING	Damaged	268.60 FL	*268.60 FL
17	1		*LOWER ARM	Not Necessary	284.00 FL	*- FL
18	1		*TAILGATE	Repair	938.90 FL	*- FL
19	1		*TAILGATE HINGE	Not Necessary	76.20 FL	*- FL
20	1		*REAR BOOT W/STRIP	Cut	162.20 FL	*162.20 FL
21	1		*REAR BOOT W/S G SS MOULDING	Not Necessary	65.80 FL	*- FL
22	1		*REAR BOOT EMBLEM -STREAM	Necessary	52.70 FL	*52.70 FL
23	1		*REAR BOOT LOCK	Not Necessary	56.50 FL	*- FL
24	1		*REAR KNUCKLE ARM LH	Damaged	397.00 FL	*397.00 FL
25	1		*REAR TYRE	Not Necessary	156.00 FS	*- FS
26	1		*REAR RIM	Cut	280.00 FS	*280.00 FS
27	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
28	1		*TAIL GATE GLASS SEALANT	Not Necessary	140.00 FS	*- FS
29	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,545.70	4,553.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,307.94	802.72
Total Parts (\$\$)	6,237.76	3,750.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT DAMAGE PARTS ,TO CUT/WELD ,KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	1,200.00	1,100.00
2	TO RESPRAY ACCIDENT AFFECTED AREA	New	1,200.00	1,000.00
3	TO RUST PROOF AFFECTED AREA	New	180.00	60.00
4	TO R&R TAIL GATE GLASS	New	150.00	120.00
5	TO R&R TAIL GATE MECHANISM	New	140.00	80.00
6	UNDERCAMAGE SYSTEM	New	120.00	120.00
7	TO R&R REVERSE SENSOR ,REVERSE CAMERA AND CHECK FUNCTION	New	120.00	50.00
8	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
Gross Labour Cost (\$\$)			3,210.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >