



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 1608S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SET HEADLAMP ASSEMBLY (XENON) O/S	SERVICEABLE	2,501.00	-
1	SET FRONT BUMPER	CUT / DISTORTED	1,250.00	1,250.00
1	SET FRONT BUMPER NOOZLE COVER O/S	SERVICEABLE	86.00	-
1	SET FRONT BUMPER PARKING SENSOR O/S	SERVICEABLE	220.00	-
1	SET FRONT BUMPER FOG LAMP GARNISH O/S	SERVICEABLE	135.00	-
1	SET FRONT BUMPER SIDE BEAN O/S	SERVICEABLE	27.00	-
1	SET FRONT BUMPER SIDE RELEASER O/S	SERVICEABLE	21.00	-
1	SET FRONT FENDER O/S	TO REPAIR SEE LABOUR	650.00	-
1	SET FRONT FENDER INNER SHIELD O/S	SERVICEABLE	195.00	-
	LESS 10% DISCOUNT		-	-125.00
			5,085.00	1,125.00
<b>SPECIAL NETT ITEMS</b>				
1	SET FRONT ALLOY RIM O/S (SN)	DEEP CUT	1,015.00	750.00
1	SET FRONT BUMPER CLIP / FASTENER (SN)	ESSENTIAL	50.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP / FASTENER O/S (SN)	SERVICEABLE	30.00	-
1	SET FRONT TYRE (NEXUS : 205/55R16) O/S (SN)	SERVICEABLE	230.00	-
			1,325.00	780.00
<b>LABOUR</b>				
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTIONS INCLUDING TO FOCUS HEADLAMPS.	NOT NECESSARY	50.00	-
	TO DISMANTLE / INSTALL AIRCONDITIONER CONDENSER & RADIATOR ASSEMBLY PIPES & HOSES ETC TO FACILITATE REPAIRS & REFILL WITH REFRIGERANT & COOLANT RESPECTIVELY.	NOT NECESSARY	150.00	-
	TO CORRECT FRONT / WHEEL GEOMETRY INCLUDING TO OSCILLATE EQUIPOISE O/S FRONT / ALLOY RIM / TYPE TO SPECIFICATIONS.		150.00	80.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANagements / CONTROL UNITS, RESET MEMORIES TO SPECIFICATIONS ETC.	NOT NECESSARY	120.00	-

Report Ref No. CS3/AIG20012051/Gvf3e2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE / RENEW THE FRONT ACCIDENT DAMAGED PORTIONS. TO HEAT, KNOCK-OUT, RESHAPE, STRAIGHTENED, ORIENTATE & ALIGN BONNET INNER LOCK FRONT BUMPER BEAM FRONT FENDER INNER PANEL O/S. INCLUSIVE OF THE REPAIR OF SET FRONT FENDER O/S.		850.00	400.00
	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT.		850.00	400.00
	TO RUSTPROOFING & CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS.	NOT NECESSARY	850.00	-
			3,020.00	880.00
GRAND TOTAL			9,430.00	2,785.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00
--	--	--	--	----------

Report Ref No. CS3/AIG20012051/Gvf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.