



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile: +65 9673 0595 / +65 9788 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No: 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

VEHICLE INSPECTION REPORT

To: Mr Stanley Soo Wei Lun
c/o 160 Sin Ming Drive
Autocity @ Sin Ming
#07-11/07
Singapore 575722

Insured :
Policy Number :
Claim Number :
Our Reference : PP/ET/IT.1608.TP.11-20
Own Damage/Sum Insured :
Excess :
Third Party/Insuree Company :
Date : 23 November 2020

Instructed By : Mr Stanley Soo
Date of Assignment : 4 November 2020
Date of Accident : 3 November 2020
Date of Inspection : 5 November 2020
Name of Workshop : Jp Concept Pte Ltd
Place of Inspection : 160 Sin Ming Drive, Autocity
#07-11/07
Singapore 575722

PARTICULARS OF DAMAGED VEHICLE

Registration Number	: SMR1608S	Odometer Reading	: 86520 Km
Make/Model	: Mercedes Benz B180	Radio/Cassette/CD	: Fitted
Year of Manuf/Reg	: 2019	Air Conditioner	: Fitted
Engine Number	: Hidden from view	View Mirrors	: Fitted-o/s & n/s
Chassis Frame Number	: WDD2462462422J261505	Seat Belts	: Fitted-front & rear only
Class/Type	: Passenger [SUV]	Other Accessories	: Fitted
Colour	: White	(Specify)	: Fitted

PRE-ACCIDENT CONDITION OF VEHICLE

General Condition	: Good	Any Apparent Engine	:
Paintwork	: Good	Modification/s	:
Footbrakes	: Serviceable	Market Value	:
Steering	: Serviceable	Scrap Value (PARF/OMV)	:
Undercarriage(Front)	: Serviceable		
Undercarriage(Rear)	: Serviceable		

TYRE CONDITION ON VEHICLE

		NEAR SIDE	OFF SIDE
Front (Size)	: Nexus	60%	60%
MAKE	: 205/5516		
Rear(Size)	: 205/5516	60%	60%
MAKE	: Nexus		

SPARE (Size)
MAKE

Type of Road Wheels : Alloy


NOTE: The above percentages represent the estimated remaining life of the tyre threads
* Denotes damaged component/s

IMPACT OF VEHICLE

Direction of Impact (→)

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered onto the o/s front of vehicle. Apparently, the o/s front wheel was struck upon, thus misaligning its wheel camber/geometry.

PRO PLUS AUTOMOBILE ENGINEERS



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT



☐ Damage Area/s

Damages sustained were the front bumper assembly, o/s front fender & its inner panel dented/buckled/headlamp panel o/s thrust inwards / buckled etc.

Note: Further reinspected vehicle/after completion of repairs on 09/11/2020 after spray painting & noted that damaged components were replaced and repaired accordingly.

ESTIMATE

The estimate submitted by JP Conceptz Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairer have agreed to undertake the repairs to the owner's satisfaction of our revision. As instructed, we have not authorised the repairs.

	Repairer's Estimate	Our Recommendation	
Spare Parts	6410.00	4943.30	Estimated number of days for repairs: 4
Labour Charges	1320.00	610.00	
Paint Work	1700.00	1100.00	Number of photographs taken at time of static inspection: 12
Towing Charges			
Others			
TOTAL	9430.00	6653.30	

Remarks: The repairer has agreed to undertake the repairs on a contract lump sum of S\$5400.00 NETT corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

NOTE: The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified with the company within 7 (seven) days from the date thereof. Otherwise, revised amount should be deemed to be valid.

PRO PLUS AUTOMOBILE ENGINEERS

Continuation Sheet No: 1

APPRAISEMENT SCHEDULE

Registration No: SMR1608S

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate	Revised Amount
		<u>PARTS REPLACEMENT-LIST ITEMS</u>	B/F		
1	1 set	Headlamp assembly [Xenon] o/s <i>X SVC</i>	displaced/servicable	2501.00	2501.00 X
2	1 set	Front bumper	cut/distorted	1250.00	1250.00 ✓
3	1 set	Front bumper noozle cover o/s	serviceable	86.00	Rejected
4	1 set	Front bumper parking sensor o/s	intact/serviceable	220.00	Rejected
5	1 set	Front bumper fog lamp garnish o/s	serviceable	135.00	Rejected
6	1 set	Front bumper side bean o/s	serviceable	27.00	Rejected
7	1 set	Front bumper side releaser o/s <i>X SVC</i>	cracked	21.00	21.00 X
8	1 set	Front fender o/s <i>X Repair</i>	dented/buckled	650.00	650.00 X
9	1 set	Front fender inner shield o/s	serviceable	195.00	Rejected
10	1 set	Front alloy rim o/s	deep cut	1015.00	1015.00 ✓
		Less : 10% by PRO+		1125	750.00 543.70
		<u>PARTS REPLACEMENT-SPECIAL NETT ITEMS</u>			
	1 set	Front bumper clip/ fastener	essential	50.00	30.00 ✓
	1 set	Front fender inner shield clip / fastener o/s <i>X SVC</i>	essential	30.00	20.00 X
	1 set	Front tyre (Nexus : 205/55R16) o/s	serviceable	230.00	Rejected
		<u>LABOUR AND MISC CHARGES:</u>			
1	1 set	To disconnect front wire harness of electrical components to facillitate repairs, reconnect & check functions including to focus headlamps		50.00	30.00 X
2	1 set	To dismantle / install airconditioner condenser & radiator assembly pipes & hoses etc to facillitate repairs & refill with refringerant & coolant respectively		150.00	Rejected
3	1 set	To correct front / wheel geometry including to oscillate equipoise o/s front/ alloy rim / type to specifications		150.00	80.00 ✓
4	1 set	To check diagnostics of vehichle managements / control units, reset memories to specifications etc		120.00	Rejected
5	1 set	To dismantle / renew the front accident damaged portions. To heat, knock-out , reshape , straightened, orientate & align bonnet inner lock front bumper beam front fender inner panel o/s		850.00	500.00 400
Sub - Total				7730.00	5553.30

APPRAISEMENT SCHEDULE

Registration No: SMR1608S

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate	Revised Amount
		<u>LABOUR AND MISC CHARGES:</u>	B/F	7730.00	5553.30
6	1 set	To putty /primer application and spray painting including touch-up affected areas with polyurethane paint.		850.00	⁴⁰⁰⁰ 550.00
7	1 set	To rustproofing & cavities preservation to the replaced and repaired panels.		850.00	550.00 X
Grand - Total				9430.00	6653.30

Note: The repairer has agreed to undertake the repairs at a contract lump sum of \$5400.00 NETT, corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

Pro Plus Automobile Engineers

ERROL TAN

B.A Econ (Hons). UK

Dip. Auto Engr. & Motor Trade Management. UK

Automobile Engineer & Licensed Appraiser

2785
20% = 2200
40 Days.



**PRO
PLUS
AUTOMOBILE
ENGINEERS**

221 Balestier Road #10-01, Rocca Balestier, Singapore 329928
Tel: +65 6707 8932 Fax: +65 6352 6802
Mobile : +65 9673 0595 / +65 9788 9809
E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com
Company Registration No : 40156500M

*Consultants to Motor Industry, Automobile
Engineers, Claims Investigators, Accident
Reconstruction Specialists, Insurance Loss
Assessors / Adjusters, Valuers And
Licensed Appraisers.*

Our Ref: PP/ET/JT.1608.TP.11-20

23rd November 2020

Mr Stanley Soo Wei Lun
c/o 160 Sin Ming Drive
#07-11/07, Autocity @ Sin Ming
Singapore 575722

WITHOUT PREJUDICE

Dear Sirs,

RE: Third Party Claim

Vehicle Registration No. SMR 1608S

We refer to your instruction to appraise the above-mentioned vehicle on 4th November 2020.

A static inspection was carried out and our report is enclosed for your perusal. The estimated repair costs submitted by Messrs JP Conceptz Pte Ltd for S\$11329.78 as per our attached schedule has been rechecked thoroughly by us against the actual damages sustained on the vehicle, and we recommend the replacements and rectifications accordingly.

Our revised quotation for the repair is S\$6081.36. In our opinion, we consider it to be excessive. We, therefore, recommend a contract lump sum repair cost. This is more economical than to have the vehicle repaired on a parts by/for parts basis. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair this vehicle for S\$5400.00 NETT which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirements at the recommended contract lump sum. However, we have not given authorisation and instruction to the repairer to proceed with the repairs.

The entire repair of the damaged vehicle should be completed within a reasonable period of 6 (Six) days, excluding weekends and public holidays.

We are reverting the matter to you for a decision, and enclosed is our invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.


Very truly yours,

PRO PLUS AUTOMOBILE ENGINEERS

Errol Tan

Licensed Appraiser & Automobile Engineers

Ends:



The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosed, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error please, contact us immediately by telephone so that we can arrange for its return.