

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21000960/EVD3E2

Date: 10/02/2021

REFERENCE

Insured/Claimant:	TEO KIAN MIN	Policy No:	1900107744		
Date of Loss:	20/01/2021	Nature of Claim:	OD	Claim No:	5011703874SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGW5809Y		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Engine No:	3A92UHR4490
Reg. Date:	28/06/2019 (Man. Year: 2018)	Chassis No:	MMBSTA13AKH001416
Colour:	Blue	Odometer:	61243 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	KAPSEN 5 mm	Rear Left Side:	KAPSEN 5 mm
Front Right Side:	KAPSEN 5 mm	Rear Right Side:	KAPSEN 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,430.00	3,303.06	2,126.94	39.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,165.00	3,775.00	1,390.00	26.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,595.00	7,078.06	3,516.94	33.19
+ GST 7.00/7.00% (S\$)	741.65	495.46	246.19	33.19
Nett Amount (S\$)	11,336.65	7,573.52	3,763.13	33.19

INSPECTION

Date of Assignment: 20/01/2021

Date Inspected: 20/01/2021 Inspected At:

Estimated Period of Repair: 6.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*FACE, RR BUMPER	Broken	748.00 F	*748.00 FL
4	1		*BRACKET, RR BUMPER, RH	Nor Necessary	28.00 F	*- FL
5	1		*BRACKET, RR BUMPER, LH	Not Necessary	28.00 F	*- FL
6	1		*PANEL, RR END	Dented	425.00 F	*425.00 FL
7	1		*LATCH, TRUNK LID	Not Necessary	218.00 F	*- FL
8	1		*PANEL, TRUNK LID	Dented	791.00 F	*791.00 FL
9	1		*GARNISH, RR END PANEL	Not Necessary	336.00 F	*- FL
10	1		*MARK, THREE-DIA	Necessary	69.00 F	*69.00 FL
11	1		*MARK, ATTRAGE	Necessary	21.00 F	*21.00 FL
12	1		*TRIM, RR END	Not Necessary	66.00 F	*- FL
13	1		*REFLECTOR	Not Necessary	23.00 F	*- FL
14	1		*REFLECTOR	Not Necessary	23.00 F	*- FL
15	1		*LAMP ASSY, COMB, RR RH	Not Necessary	335.00 F	*- FL
16	1		*LAMP ASSY, COMB, RR LH	Not Necessary	335.00 F	*- FL
17	1		*BUZZER, KEYLESS OPERATIO, RR	Not Necessary	91.00 F	*- FL
18	1		*ANT, KEYLESS OPERATION, RR	Not Necessary	96.00 F	*- FL
19	1		*DUCT, RR VENTILATOR	Not Necessary	30.00 F	*- FL
20	1		*COVER, RR VENTILATOR	Not Necessary	40.00 F	*- FL
21	1		*BODY KIT, ATTRAGE, T69	Broken	1,643.00 FS	*1,643.00 FS
22	4		*CLIP,RR END TRIM (Supplementary)	Necessary	12.00 F	*12.00 FL
23	4		*GROMMENT,RR END TRIM (Supplementary)	Necesity	12.00 F	*12.00 FL
					Sub Total (\$\$)	5,430.00 3,781.00
					- List Item Discount on L Items 0.00/23.00% (\$\$)	0.00 477.94
					Total Parts (\$\$)	5,430.00 3,303.06

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR AIRDAM, REAR BUMPER, BOOTLID, REAR END PANEL	New	1,800.00	900.00
2	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
3	SPRAY PAINT FOR REAR BUMPER, REAR AIRDAM, REAR END PANEL, BOOT LID	New	1,400.00	1,050.00
4	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	200.00	120.00
5	REMOVE & INSTALL REAR AIRDAM	New	100.00	80.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	40.00
9	REPLACE REAR END PANEL AND REPAIR REAR FLOOR PANEL (Supplementary)	New	675.00	675.00
10	SPRAY PAINT REAR END PANEL AND REAR FLOOR PANEL (Supplementary)	New	700.00	700.00
Gross Labour Cost (\$\$)			5,165.00	3,775.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >