

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21000965/AVF3Q2

Date: 22/03/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLX6600K

Insured Vehicle No : GBE2977T

Date of Loss: 19/01/2021

Nature of Claim: TP

Claim No: CDMCG21000131

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX6600K

Make & Model: BMW 320I, 2.0 (A)

Engine No: A8010606N20B20B

Reg. Date: 14/03/2014 (Man. Year: 2013)

Chassis No: WBA3B16030NS51471

Colour: Silver

Odometer: 125095 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35R19

Rear Tyre Size: 245/35R19

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,048.60	5,796.10	6,252.50	51.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,170.00	1,710.00	59.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,928.60	6,966.10	7,962.50	53.34
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	14,928.60	5,500.00	9,428.60	63.16

INSPECTION

Date of Assignment: 20/01/2021

Date Inspected: 20/01/2021 Inspected At:

Advance Auto Garage
10 Kaki Bukit Road 2, #01-21 First East Centre
Singapore 417868

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2021)
Parts:	143	BMW 320I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX6600K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER SIDE HOLDER RH	Necessary	92.00 FL	*92.00 FL
2	1	*FRONT BUMPER SPONGE	Cracked	85.00 FL	*85.00 FL
3	1	*FRONT BUMPER REINFORCEMENT	Bent	468.00 FL	*468.00 FL
4	1	*FRONT BUMPER FOG LAMP RH	Cracked	295.00 FL	*295.00 FL
5	1	*FRONT BUMPER FOG LAMP GRILLE RH	Not Necessary	89.00 FL	*- FL
6	1	*FRONT BUMPER NOZZLE COVER RH	Missing	35.00 FL	*35.00 FL
7	1	*FRONT BUMPER NOZZLE PUMP RH	Cracked	249.00 FL	*249.00 FL
8	1	*FRONT BUMPER INNER AIR DUCT RH	Cracked	65.00 FL	*65.00 FL
9	1	*FRONT BUMPER LOGO	Necessary	78.00 FL	*78.00 FL
10	1	*FRONT BUMPER TOP INNER FRAME	Cracked	148.00 FL	*148.00 FL
11	1	*FRONT GRILLE	O/s Cracked	290.00 FL	*145.00 FL
12	1	*HEADLAMP RH	Cracked	2,083.00 FL	*2,083.00 FL
13	1	*BONNET	Repair	1,659.00 FL	*- FL
14	1	*FRONT RH FENDER	Repair	699.00 FL	*- FL
15	1	*FRONT RH FENDER INNER SHIELD	Deformed	186.00 FL	*186.00 FL
16	1	*FRONT RH FENDER INNER SHIELD LOWER COVER	Not Necessary	68.00 FL	*- FL
17	1	*FRONT RH LOWER ARM	Not Necessary	450.00 FL	*- FL
18	1	*FRONT RH UPPER ARM	Not Necessary	488.00 FL	*- FL
19	1	*FRONT RH STAY ARM	Not Necessary	329.00 FL	*- FL
20	1	*FRONT RH KNUCKLE ARM	Not Necessary	899.00 FL	*- FL
21	1	*FRONT RH WHEEL HUB C/W BEARING	Not Necessary	354.00 FL	*- FL
22	1	*FRONT RH SHOCK ABSORBER	Not Necessary	695.00 FL	*- FL
23	1	*FRONT RH WHEEL RIM	Cut	1,125.00 FS	*700.00 FS
24	1	*FRONT BUMPER	Distorted	2,000.00 FS	*1,500.00 FS
25	1	*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
26	1	*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
27	1	*SET FRONT RH FENDER INNER SHIELD LOWER COVER CLIPS	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,029.00	6,189.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	980.40	392.90
Total Parts (\$\$)	12,048.60	5,796.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVE AND REFIT PARTS	New	1,000.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	600.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	40.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
6	TO REMOVE FRONT UNDERCARRIAGE	New	380.00	0.00
7	TO PERFORM DIAGNOSTIC TEST	New	150.00	100.00
Gross Labour Cost (\$\$)			2,880.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >