

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000967/ABA3Q2

Date: 07/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070107877

Claimant
Vehicle No : EZ5671J **Insured Vehicle No :** GBF2645X

Date of Loss: 18/01/2021 Nature of Claim: TP Claim No: 1532178840SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EZ5671J		
Make & Model:	TOYOTA COROLLA AXIO, 1.5 HYBRID (A)	Engine No:	1NZR457603
Reg. Date:	22/03/2017 (Man. Year: 2016)	Chassis No:	NKE1657140274
Colour:	Blue	Odometer:	219071 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,410.90	1,035.82	6,375.08	86.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	1,190.00	3,210.00	72.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	11,810.90	2,225.82	9,585.08	81.15
+ Loss of Use (4.0 x S\$70.00/day) (S\$)		280.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,513.27		
Global Sum Settlement (S\$)		2,500.00		

INSPECTION

Date of Assignment: 20/01/2021

Date Inspected: 20/01/2021 Inspected At:

Auto Bullox Pte Ltd (HQ)
53 UBI AVE 1, #01-25, PAYA UBI
INDUSTRIAL PARK
Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	972.00 FL	*- FL
2	1		*BOOTLID OUTER CHROME GARNISH	Not Necessary	374.45 FL	*- FL
3	2		*BOOTLID HINGE	Not Necessary	110.00 FL	*- FL
4	2		*BOOTLID STOPPER	Not Necessary	60.00 FL	*- FL
5	1		*BOOTLID INSULATOR	Not Necessary	161.70 FL	*- FL
6	1		*BOOTLID EMBLEM -LOGO	Not Necessary	121.25 FL	*- FL
7	1		*BOOTLID EMBLEM -AXIO	Not Necessary	131.35 FL	*- FL
8	1		*BOOTLID EMBLEM -COROLLA	Not Necessary	85.30 FL	*- FL
9	1		*REAR TAILLAMP PANEL RH	Repair	278.45 FL	*- FL
10	1		*REAR FENDER RH	Repair	1,072.40 FL	*- FL
11	1		*REAR FENDER INNER TRIM RH	Not Necessary	561.60 FL	*- FL
12	1		*REAR TAILLAMP RH	Cracked	490.50 FL	*490.50 FL
13	1		*REAR BUMPER	Distorted	1,218.50 FL	*785.00 FL
14	1		*REAR BUMPER RETAINER	N/S Damaged	131.20 FL	*65.60 FL
15	1		*REAR BUMPER REINFORCEMENT	Not Necessary	391.45 FL	*- FL
16	1		*REAR BUMPER REFLECTOR RH	Not Necessary	131.35 FL	*- FL
17	1		*REAR END PANEL	Not Necessary	781.90 FL	*- FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	274.45 FL	*- FL
19	1		*SPARE TYRE TOP BOARD	Not Necessary	581.90 FL	*- FL
20	1		*REAR EXHAUST SILENCER	Not Necessary	781.45 FL	*- FL
21	2		*REAR EXHAUST MOUNTING	Not Necessary	60.00 FL	*- FL
22	1		*REAR WINDSCREEN MOULDING	Not Necessary	190.00 FL	*- FL
23	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
24	1		*SET BOOTLID INNER TRIM CLIP	Not Necessary	20.00 FS	*- FS
25	1		*SET REAR SENSOR	Not Necessary	400.00 FS	*- FS
26	1		*JOINT SELANT	Not Necessary	120.00 FS	*- FS
27	1		*WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,651.20	1,371.10
- List Item Discount on L Items 25.00/25.00% (\$)	2,240.30	335.28
Total Parts (\$)	7,410.90	1,035.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK ALL WIRING AND LIGHTING SYSTEM	New	90.00	30.00
2	REMOVE AND RENEW REAR SENSOR	New	120.00	50.00
3	REMOVE AND RENEW REAR EXHAUST	New	150.00	0.00
4	REMOVE AND REFIT REAR WINDSCREEN	New	120.00	0.00
5	REMOVE ,REFIT TRIM ,LINING AND GARNISH	New	200.00	60.00
6	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	0.00
7	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS	New	1,600.00	400.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	600.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	50.00
Gross Labour Cost (\$\$)			4,400.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >