

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000968/KTF3E2

Date: 30/09/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/20-511629-WTT
Claimant Vehicle No :	YN362K	Insured Vehicle No :	FBQ3196K
Date of Loss:	18/01/2021	Nature of Claim:	TP
		Claim No:	MSC/V/21-000039

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN362K	Engine No:	4JJ1774186
Make & Model:	ISUZU NHR85AUE4A, 3.0 D (M)	Chassis No:	JAANHR85E97100032
Reg. Date:	11/05/2009 (Man. Year: 2009)	Odometer:	406048 km
Colour:	Blue/Red		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8(D)
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 4/4 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,770.70	1,513.02	7,257.68	82.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	855.00	1,795.00	67.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,420.70	2,368.02	9,052.68	79.27
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	11,420.70	1,850.00	9,570.70	83.80
+ GST 7.00/7.00% (S\$)	799.45	129.50	669.95	83.80
Nett Amount (S\$)	12,220.15	1,979.50	10,240.65	83.80

INSPECTION

Date of Assignment:	20/01/2021	
Date Inspected:	26/01/2021 Inspected At:	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Sep 2021)	
Parts:	N/A	ISUZU NHR85AUE4A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN362K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT TYRE 195R 15C - LH	Serviceable	400.00 F	*- F
2	1		*FRONT WHEEL RIM - LH	Repair	780.25 F	*- F
3	1		*FRONT BUMPER	Repair	1,450.85 F	*- FL
4	1		*HEAD LAMP - LH	Serviceable	725.10 F	*- FL
5	1		*FRONT DOOR - LH	Bent	1,782.00 F	*1,120.00 FL
6	1		*FRONT DOOR WEATHERSTRIP - LH	Serviceable	188.00 F	*- FL
7	1		*FRONT DOOR CHECKER - LH	Serviceable	180.00 F	*- FL
8	1		*FRONT DOOR REGULATOR GEAR - LH	Serviceable	267.20 F	*- FL
9	1		*FRONT DOOR REGULATOR GEAR MOTOR - LH	Serviceable	403.00 F	*- FL
10	1		*FRONT DOOR INNER TRIMBOARD - LH	Serviceable	689.60 F	*- FL
11	1		*FRONT STEP PANEL - LH	Repair	380.15 F	*- FL
12	1		*FRONT STEP GARNISH - LH	Cracked	298.50 F	*298.50 FL
13	1		*FRONT DOOR LOCK - LH	Repair	420.15 F	*- FL
14	1		*FRONT DOOR OUTER HANDLE - LH	Serviceable	220.85 F	*- FL
15	1		*FRONT DOOR STICKER - LH	Necessary	400.00 FS	*150.00 FS
16	1		*FRONT DOOR OUTER MOULDING - LH	Cut	185.05 F	*185.05 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,770.70	1,753.55
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	240.53
Total Parts (\$\$)	8,770.70	1,513.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	New	1,200.00	350.00
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,000.00	400.00
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL	New	180.00	30.00
4	TO REMOVE / TRANSFER LH FRONT DOOR MECHANISMS	New	150.00	60.00
5	TO CHECK WIRING FUNCTIONS	New	120.00	15.00
Gross Labour Cost (\$\$)			2,650.00	855.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >