

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000971/GVD3Q2

Date: 01/02/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00124992000
Claimant Vehicle No :	GBJ1019P	Insured Vehicle No :	GBK8487U
Date of Loss:	16/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200325/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ1019P	Engine No:	1KD2833958
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Chassis No:	JTFHT02P200246771
Reg. Date:	02/01/2019 (Man. Year: 2018)	Odometer:	86524 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	785.00	266.10	518.90	66.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	100.00	550.00	84.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,435.00	366.10	1,068.90	74.49
+ GST 7.00/7.00% (\$\$)	100.45	25.63	74.82	74.48
Nett Amount (\$\$)	1,535.45	391.73	1,143.72	74.49

INSPECTION

Date of Assignment:	28/01/2021	
Date Inspected:	25/01/2021 Inspected At:	8 KAKI BUKIT AVE 4# 04-20 PREMIER Repairer: A-Tec Automotive Pte Ltd (HQ)
Estimated Period of Repair:	1.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2021)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ1019P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LEFT TAILLAMP	Cracked	785.00 F	*354.80 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	785.00
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00
					Total Parts (S\$)	785.00
						266.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND INSTALL REAR LEFT TAILAMP	New	250.00	50.00
2	TO CHECK REAR LIGHTING AND WIRING	New	200.00	50.00
3	TO PUTTY AND SPRAY PAINTING REAR LEFT PORTION	New	200.00	0.00
Gross Labour Cost (\$\$)			650.00	100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >