

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000975/NVD3E2

Date: 09/03/2021

REFERENCE

Insured/Claimant:	WONG KOON KIAN	Policy No:	1800141802		
Date of Loss:	29/12/2020	Nature of Claim:	OD	Claim No:	0823057538SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN6789X		
Make & Model:	YAMAHA XABRE, 150cc TFX150	Engine No:	G3G8E0036033
Reg. Date:	24/11/2018 (Man. Year: 2017)	Chassis No:	MH3RG3710HK026854
Colour:	Silver	Odometer:	44998 km
Engine Capacity:	150 cc		
Market Value/New Car Price:	S\$9,200.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	130/70 R17
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,417.40	4,184.90	1,232.50	22.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,090.00	830.00	1,260.00	60.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,507.40	5,014.90	2,492.50	33.20
Approved Total (Overridden) (S\$)		4,000.00		
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	7,207.40	3,700.00	3,507.40	48.66
+ GST 7.00/7.00% (S\$)	504.52	259.00	245.52	48.66
Nett Amount (S\$)	7,711.92	3,959.00	3,752.92	48.66

INSPECTION

Date of Assignment:	20/01/2021		
Date Inspected:	22/01/2021	Inspected At:	Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD Singapore 218216
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked	145.00 FL	*145.00 FL
2	1		*FRONT WHEEL SHAFT	Bent	75.00 FL	*75.00 FL
3	1		*LEFT FRONT FOOT REST	Scratched	75.00 FL	*75.00 FL
4	1		*FRONT LEFT FORK ASSY	Broken	680.00 FL	*500.00 FL
5	1		*SIDE STAND	Serviceable	85.00 FL	*- FL
6	1		*STEERING STEM	Bent	220.00 FL	*150.00 FL
7	1		*STEERING BRIDGE	Scratched	195.00 FL	*195.00 FL
8	2		*STEERING BEARINGS	Necessary	90.00 FL	*90.00 FL
9	1		*SET GEAR PEDAL	Scratched	78.00 FL	*78.00 FL
10	1		*FRONT LEFT SIGNAL	Serviceable	125.00 FL	*- FL
11	1		*LEFT VIEW MIRROR	Scratched	95.00 FL	*95.00 FL
12	1		*IU BRACKET	Bent	45.00 FL	*45.00 FL
13	1		*HANDLE BAR	Bent	175.00 FL	*120.00 FL
14	1		*LLEFT BALANCER	Scratched	48.00 FL	*48.00 FL
15	1		*CLUTCH LEVER	Bent	55.00 FL	*55.00 FL
16	1		*LEFT HANDGRIP	Serviceable	35.00 FL	*- FL
17	1		*FUEL TANK LEFT COVER	Scratched	205.00 FL	*150.00 FL
18	1		*FUEL TANK AMBLEMS	Necessary	75.00 FL	*40.00 FL
19	1		*LEFT REAR SIGNAL	Serviceable	115.00 FL	*- FL
20	1		*LEFT SIDE COVER AMBLEM	Necessary	70.00 FL	*40.00 FL
21	1		*LEFT SIDE COVER	Scratched	175.00 FL	*140.00 FL
22	1		*SPORT RIM FRONT	Grazed	580.00 FS	*450.00 FS
23	1		*FRONT NUMBER PLATE	Bent	20.00 FS	*20.00 FS
24	1		*ERP IU	Scratched	157.00 FS	*157.00 FS
25	1		*RIGHT FORK ASSEMBLY (Supplementary)	Scratched	680.00 FL	*500.00 FL
26	1		*HEADLAMP BRACKET (Supplementary)	Bent	175.00 FL	*120.00 FL
27	1		*LEFT FRONT FOOT REST HOLDER (Supplementary)	Bent	165.00 FL	*165.00 FL
28	1		*LEFT CLUTCH HOLDER (Supplementary)	Bent	75.00 FL	*75.00 FL
29	1		*CLUTCH SWITCH (SIDE STAND) (Supplementary)	Broken	65.00 FL	*65.00 FL
30	1		*TAIL COVER (Supplementary)	Deformed	95.00 FL	*95.00 FL
31	1		*METER ASSEMBLY (Supplementary)	Deformed	395.00 FL	*300.00 FL
32	1		*LEFT SIGNAL SWITCH ASSY (Supplementary)	Broken	195.00 FL	*120.00 FL
33	1		*TOP BOX (Supplementary)	Scratched	220.00 FS	*220.00 FS
34	1		*BOX BRACKET (Supplementary)	Bent	175.00 FS	*175.00 FS
35	1		*REAR NUMBER PLATE (Supplementary)	Dented	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,888.00	4,533.00
- List Item Discount on L Items 10.00/10.00% (S\$)	470.60	348.10
Total Parts (S\$)	5,417.40	4,184.90

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	100.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	800.00	300.00
3	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
4	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	180.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT SPORT RIMS	New	150.00	70.00
6	SPRAY PAINTING	New	280.00	200.00
7	LABOUR FOR REMOVING AND REPLACING SUPPLEMENTARY PARTS (Supplementary)	New	200.00	80.00
Gross Labour Cost (\$\$)			2,090.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >