

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21000978/QPS3Q2
Date: 31/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070053753
Claimant Vehicle No :	SHC4576T	Insured Vehicle No :	GW886G
Date of Loss:	16/01/2021	Nature of Claim:	TP
		Claim No:	4553038248SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4576T		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR6230436
Reg. Date:	10/12/2014 (Man. Year: 2014)	Chassis No:	JTDKN36U305753773
Colour:	Maroon	Odometer:	434301 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,792.54	4,069.63	20,722.91	83.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,820.00	1,840.00	3,980.00	68.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,612.54	5,909.63	24,702.91	80.70
Approved Total (Overridden) (S\$)		5,100.00		

Nett Amount (S\$)	30,612.54	5,100.00	25,512.54	83.34
+ Car Rental (6.0 x S\$133.75/day) (S\$)		802.50		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		5,909.50		
Global Sum Settlement (S\$)		5,900.00		

INSPECTION

Date of Assignment: 18/01/2021

Date Inspected: 18/01/2021

Estimated Period of Repair: 5.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRT (DISC 25%)	Crumpled	482.00 F	*361.50 F
2	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
3	1		*BRACKET ,FR BUMPER (DISC 25%)	Broken	110.40 F	*82.80 F
4	1		*COVER ,FR BUMPER HOLE LH (DISC 25%)	Scratched	18.50 F	*13.88 F
5	1		*COVER ,FR BUMPER HOLE RH (DISC 25%)	Scratched	18.50 F	*13.88 F
6	1		*BUMPER SUPPORT F/LH (DISC 25%)	Broken	76.40 F	*57.30 F
7	1		*BUMPER SUPPORT F/RH (DISC 25%)	Broken	76.40 F	*57.30 F
8	1		*EMBLEM FRONT (DISC 25%)	Necessary	86.50 F	*64.88 F
9	1		*FENDER FRT /LH (DISC 25%)	Crumpled	723.40 F	*542.55 F
10	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
11	1		*FENDER LINER FRT/RH (DISC 25%)	Cut	171.70 F	*128.78 F
12	1		*LOWER ARM FRT/LH (DISC 25%)	Bent	625.90 F	*469.43 F
13	1		*STEERING KNUCKLE LH FRT (DISC 25%)	Bent	580.80 F	*435.60 F
14	1		*HEAD LAMP LH (DISC 10%)	Crumpled	945.20 F	*850.68 F
15	1		*LENS & BODY ,FR TURN RH (DISC 10%)	Scratched	511.80 F	*460.62 F
16	1		*FOG LAMP RH (DISC 10%)	Cracked	295.20 F	*265.68 F
17	1		*NUMBER PLATE (SN)	Scratched	15.00 F	*15.00 F
18	1		*NUMBER PLATE FRAME (SN)	Scratched	12.00 F	*12.00 F
19	1		*TYRE (SN)	Broken	126.74 F	*126.74 F
20	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
21	1		*BUMPER ENERGY ABSORBER FRT	Serviceable	78.80 F	*- F
22	1		*BUMPER REINFORCEMENT FRT	Serviceable	498.40 F	*- F
23	1		*ARM SUB-ASSY ,FR BUMPER LH	Serviceable	250.40 F	*- F
24	1		*ARM SUB-ASSY ,FR BUMPER RH	Serviceable	250.40 F	*- F
25	1		*BUMPER GRILLE SUB-ASSY ,LOWER	Serviceable	311.10 F	*- F
26	1		*FOG LAMP LH	Serviceable	280.10 F	*- F
27	1		*FOG LAMP RH	Serviceable	295.20 F	*- F
28	1		*BRACKET ,FR TURN LOWER RH	Serviceable	26.00 F	*- F
29	1		*BRACKET ,FR TURN UPPER RH	Serviceable	24.40 F	*- F
30	1		*BRACKET ,FR TURN CENTER RH	Serviceable	58.20 F	*- F
31	1		*LENS & BODY ,FR TURN RH	Serviceable	511.80 F	*- F
32	1		*BRACKET ,FR TURN CENTER LH	Serviceable	58.20 F	*- F
33	1		*BRACKET ,FR TURN LOWER LH	Serviceable	26.00 F	*- F
34	1		*BRACKET ,FR TURN UPPER LH	Serviceable	24.40 F	*- F
35	1		*LENS & BODY ,FR TURN LH	Serviceable	511.80 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*GRILLE RADIATOR LOWER NO.2	Serviceable	94.60 F	*- F
37	1		*GRILLE ,RADIATOR	Serviceable	310.60 F	*- F
38	1		*BUMPER LIP FRT	Serviceable	139.60 F	*- F
39	1		*BUMPER FRT ABSORBER LOWER	Serviceable	127.70 F	*- F
40	1		*WIRE ,ENGINE ROOM.NO.3	Serviceable	242.00 F	*- F
41	1		*THERMISTOR ASSY	Serviceable	107.00 F	*- F
42	1		*HOOD HINGE LH	Serviceable	55.90 F	*- F
43	1		*HOOD HINGE RH	Serviceable	55.90 F	*- F
44	1		*HOOD END PANEL SEAL	Serviceable	35.50 F	*- F
45	1		*SUPPORT SUB-ASSY	Serviceable	1,460.40 F	*- F
46	1		*HEAD LAMP RH	Serviceable	945.20 F	*- F
47	1		*WIPER WASHER JAR	Serviceable	180.10 F	*- F
48	1		*FENDER LINER FRT/LH	Serviceable	171.70 F	*- F
49	1		*FENDER LINER PAD ,FR WHEEL ,LH	Serviceable	49.30 F	*- F
50	1		*FENDER PROTECTOR FRT/LH UPPER	Serviceable	46.10 F	*- F
51	1		*PROTECTOR ,FRONT FENDER SIDE PANEL LH	Serviceable	114.50 F	*- F
52	1		*FENDER APRON SUB FRT/LH	Serviceable	637.80 F	*- F
53	1		*TIE ROD END LH	Serviceable	159.30 F	*- F
54	1		*WHEEL HUB FRT	Serviceable	549.70 F	*- F
55	2		*SHOCK ABSORBER BEARING ,FRT LH/RH	Serviceable	34.00 F	*- F
56	1		*SHOCK ABSORBER FRT/LH	Serviceable	394.20 F	*- F
57	2		*SHOCK ABSORBER MOUNTING FRT ,RH/LH	Serviceable	193.80 F	*- F
58	2		*STABILIZER BAR LINK FRT /RH /LH	Serviceable	195.00 F	*- F
59	1		*STEERING KNUCKLE LH FRT	Serviceable	580.80 F	*- F
60	1		*DRIVE SHAFT LH	Serviceable	1,543.80 F	*- F
61	1		*LOWER ARM FRT /LH	Serviceable	625.90 F	*- F
62	1		*JOINT ASSY ,LWR BALL	Serviceable	195.60 F	*- F
63	1		*STEERING RACK ASSY	Serviceable	1,597.50 F	*- F
64	1		*MIRROR ASSY ,LH	Serviceable	1,224.90 F	*- F
65	1		*MIRROR LAMP LH	Serviceable	65.30 F	*- F
66	1		*FENDER FRT/RH	Serviceable	723.40 F	*- F
67	1		*NAME PLATE (HYBRID)	Serviceable	51.90 F	*- F
68	1		*FENDER LINER PAD FR WHEEL RH	Serviceable	49.30 F	*- F
69	1		*HOOD PANEL INSULATOR	Serviceable	390.50 F	*- F
70	1		*HOOD PANEL	Repair	748.10 F	*- F
71	1		*WHEEL DISC FRONT	Repair	1,484.20 F	*- F
72	1		*DOOR FRT/LH	Repair	894.40 F	*- F
73	1		*COVER ,OUTER MIRROR LH	Repair	107.40 F	*- F

F=Franchise part.

Total Parts (S\$)**24,792.54****4,069.63**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	1,264.00	600.00
2	SPRAY PAINT	New	2,970.00	1,010.00
3	TOWING CHARGE	New	56.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
5	TO APPLY RUST PROOFING ON AFFECTED AREA	New	200.00	30.00
6	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
7	TO REMOVE AND REFIX TYRE RIM (SPRAYING PURPOSE)	New	120.00	20.00
8	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	0.00
9	TO REMOVE AND REFIT WIRE HARNESS	New	250.00	0.00
10	TO REMOVE AND REFIX UNDERCARRIAGE	New	250.00	100.00
11	TO REPLACE SUNDRY PARTS	New	100.00	0.00
12	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			5,820.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >