

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III20006910/ETD3E2-1

Date: 22/01/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SKU6131A	Insured Vehicle No :	SHC8871P
Date of Loss:	30/06/2020	Nature of Claim:	TP
		Claim No:	MCT20060364

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU6131A	Engine No:	10296322008086
Make & Model:	MERCEDES-BENZ 200E, 2.0 (A)	Chassis No:	WDB1240212B040056
Reg. Date:	02/10/1989 (Man. Year: 1989)	Odometer:	466259 km
Colour:	Blue		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,185.01	1,361.70	1,823.31	57.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	1,160.00	2,110.00	64.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,455.01	2,521.70	3,933.31	60.93
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	6,455.01	2,000.00	4,455.01	69.02

INSPECTION

Date of Assignment:	20/01/2021	Hup Ley Huat Motor Spray Painting Services (HQ)
Date Inspected:	06/07/2020 Inspected At:	BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
Parts:	143	MERCEDES-BENZ 200E 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU6131A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent / Deformed	855.40 FL	*696.00 FL
2	1		*REAR BUMPER SIDE RETAINER	Bent	90.00 FL	*90.00 FL
3	1		*REAR BUMPER SIDE ATTACHMENT	Serviceable	116.00 FL	*- FL
4	1		*REAR BUMPER SPONGE	Serviceable	162.00 FL	*- FL
5	1		*REAR BUMPER CHROME (CENTER)	Damaged	222.00 FL	*180.00 FL
6	1		*REAR BUMPER CHROME (SIDE)	O/S Deformed/N/SNot Necessary	382.00 FL	*126.00 FL
7	1		*TAIL LAMP	Cracked	565.50 FL	*421.00 FL
8	1		*TAIL LAMP GARNISH	Serviceable	115.00 FL	*- FL
9	1		*TAIL LAMP SEALANT	Serviceable	75.00 FL	*- FL
10	2		*TAIL LAMP CLIPS	Serviceable	40.00 FL	*- FL
11	1		*TAIL LAMP BASE PANEL	Repair	225.00 FL	*- FL
12	1		*REAR END PANEL	Repair	691.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,538.90	1,513.00
- List Item Discount on L Items 10.00/10.00% (\$)	353.89	151.30
Total Parts (\$)	3,185.01	1,361.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK AND RECONNECT SNAP WIRING	New	120.00	30.00
2	TO TUFF COAT AFFECTED AREAS	New	150.00	30.00
3	TO RESPRAY AFFECTED AREAS	New	1,400.00	500.00
4	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR REAR CHASSIS MEMBER, REAR FENDER INNER PANEL, REAR DOOR AND ALIGNED ALL PARTS	New	1,600.00	600.00
Gross Labour Cost (S\$)			3,270.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >