

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000982/ABS3Q2
Date: 03/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLN7837R	Insured Vehicle No :	SLU7328G
Date of Loss:	14/01/2021	Nature of Claim:	TP
		Claim No:	3958438834SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN7837R		
Make & Model:	CHEVROLET CRUZE NB, 1.4 D 6 (A)	Engine No:	B14NET170230011
Reg. Date:	17/05/2017 (Man. Year: 2017)	Chassis No:	KL1JA6989GK354979
Colour:	Black	Odometer:	59836 km
Engine Capacity:	1362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,151.90	10,234.70	8,917.20	46.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	1,910.00	2,390.00	55.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,451.90	12,144.70	11,307.20	48.21
Approved Total (Overridden) (S\$)		9,700.00		

Nett Amount (S\$)	23,451.90	9,700.00	13,751.90	58.64
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,563.45		

INSPECTION

Date of Assignment: 19/01/2021

Date Inspected: 19/01/2021

Estimated Period of Repair: 6.0 days

Inspected At: Xin Hua Workshop Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01
Singapore 415933

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR FENDER RH	Not Necessary	2,196.00 FL	*- FL
2	1		*RR TAILLAMP PANEL RH	Not Necessary	322.00 FL	*- FL
3	1		*RR FENDER LH	Not Necessary	2,196.00 FL	*- FL
4	1		*RR TAILLAMP PANEL LH	Not Necessary	322.00 FL	*- FL
5	1		*RR FENDER INNER SHIELD LH	Not Necessary	193.00 FL	*- FL
6	1		*RR FENDER INNER SHIELD RH	Not Necessary	193.00 FL	*- FL
7	1		*RR FENDER INNER TRIM LH	Not Necessary	388.00 FL	*- FL
8	1		*RR FENDER INNER TRIM LH	Not Necessary	388.00 FL	*- FL
9	1		*RR WINDSCREEN MLDG	Not Necessary	118.00 FL	*- FL
10	1		*RR FENDER QUARTER GARNISH RH	Not Necessary	140.00 FL	*- FL
11	1		*RR FENDER QUARTER GARNISH LH	Not Necessary	140.00 FL	*- FL
12	1		*RR BUMPER	Deformed	1,456.00 FL	*1,291.00 FL
13	1		*RR BUMPER CHROME MLDG RH	Necessary	152.00 FL	*152.00 FL
14	1		*RR BUMPER CHROME MLDG LH	Necessary	152.00 FL	*152.00 FL
15	1		*RR BUMPER CHROME MLDG CENTRE	Cut	205.00 FL	*205.00 FL
16	1		*RR BUMPER REINFORCEMENT	Bent	736.00 FL	*736.00 FL
17	1		*RR BUMPER SIDE RETAINER LH (INNER)	Necessary	116.00 FL	*116.00 FL
18	1		*RR BUMPER SIDE RETAINER LH (OUTER)	Necessary	116.00 FL	*116.00 FL
19	1		*RR BUMPER SIDE RETAINER RH (INNER)	Necessary	116.00 FL	*116.00 FL
20	1		*RR BUMPER SIDE RETAINER RH (OUTER)	Necessary	116.00 FL	*116.00 FL
21	1		*RR BUMPER CENTRE RETAINER	Cracked	130.00 FL	*130.00 FL
22	4		*RR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	860.00 FL	*430.00 FL
23	4		*RR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	52.00 FL	*52.00 FL
24	1		*RR BUMPER REVERSE WIRE HARNESS	Damaged	336.00 FL	*336.00 FL
25	1		*RR BUMPER TOW COVER	Not Necessary	96.00 FL	*- FL
26	1		*RR REVERSE CAMERA	Damaged	361.00 FL	*361.00 FL
27	2		*RR NUMBER PLATE LAMP	Cracked	150.00 FL	*150.00 FL
28	1		*RR BOOTLID	Buckled	1,973.00 FL	*1,705.00 FL
29	1		*RR BOOTLID WEATHERSTRIP	Cut	214.00 FL	*214.00 FL
30	2		*RR BOOTLID STOPED	Not Necessary	24.00 FL	*- FL
31	1		*RR BOOTLID LOGO	Necessary	165.00 FL	*165.00 FL
32	1		*RR BOOTLID EMBLEM CHEVROLET	Necessary	82.00 FL	*82.00 FL
33	1		*RR BOOTLID EMBLEM CRUZE LS	Necessary	80.00 FL	*80.00 FL
34	1		*RR BOOTLID EMBLEM TURBO	Necessary	87.00 FL	*87.00 FL
35	1		*RR BOOTLID LOCK	Damaged	286.00 FL	*286.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*RR BOOTLID LOCK COVER	Not Necessary	38.00 FL	*- FL
37	1		*RR BOOTLID LOCK KEYLESS SENSOR	Cracked	167.00 FL	*167.00 FL
38	1		*RR BOOTLID HINGE RH	Not Necessary	176.00 FL	*- FL
39	1		*RR BOOTLID HINGE LH	Not Necessary	176.00 FL	*- FL
40	1		*RR BOOTLID LAMP RH	Cut	401.00 FL	*401.00 FL
41	1		*RR BOOTLID LAMP LH	Cut	401.00 FL	*401.00 FL
42	1		*RR TAILLAMP LH	Cut	850.00 FL	*725.00 FL
43	1		*RR TAILLAMP RH	Cut	850.00 FL	*725.00 FL
44	1		*RR END PANEL	Dented	996.00 FL	*996.00 FL
45	1		*RR END PANEL TOP GARNISH	Deformed	267.00 FL	*267.00 FL
46	1		*RR SPARE TYRE PANEL	Repair	1,439.00 FL	*- FL
47	1		*RR SPARE TYRE PANEL BOARD	Cracked	473.00 FL	*473.00 FL
48	10		*RR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
49	10		*RR BOOTLID INNER TRIM CLIP	Not Necessary	40.00 FS	*- FS
50	10		*RR FENDER INNER TRIM CLIP	Not Necessary	40.00 FS	*- FS
51	10		*RR FENDER INNER SHIELD CLIP	Not Necessary	40.00 FS	*- FS
52	5		*RR END PANEL TOP GARNISH CLIP	Necessary	20.00 FS	*20.00 FS
53	1		*RR WINDSCREEN SEALANT	Not Necessary	65.00 FS	*- FS
54	1		*RR WINDSCREEN INNER SEAL	Not Necessary	40.00 FS	*- FS
55	1		*RR NUMBER PLATE	Cracked	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	21,241.00	11,358.00
- List Item Discount on L Items 10.00/10.00% (\$)	2,089.10	1,123.30
Total Parts (\$)	19,151.90	10,234.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,600.00	800.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA ,RR BUMPER ,RR BOOTLID ,RR END PANEL ,RR SPARE TYRE PANEL ,RR FENDER LH ,RR FENDER RH	New	1,600.00	800.00
3	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	30.00
4	REMOVE AND REFIX INTERIOR TRIM ,SEAT CUSHION /UPHOLSTERY ,ROOF LINING ,SEATBELT,ETC	New	200.00	60.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	120.00	50.00
6	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	120.00	50.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID	New	180.00	60.00
8	TO REMOVE AND REFIT REAR WINDSCREEN DUE TO REPLACEMENT OF REAR FENDER	New	200.00	0.00
9	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	100.00	60.00
10	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	60.00	0.00
Gross Labour Cost (S\$)			4,300.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >