

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21000984/AVD3E2

**Date:** 16/04/2021

### REFERENCE

Insured/Claimant:	ANG CHU YUN (HONG CHUYUN)	Policy No:	2070013391	
Date of Loss:	16/01/2021	Nature of Claim:	OD	Claim No: 5149828201SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX1811A	Engine No:	CVK086224
Make & Model:	AUDI A4, 2.0 TFSI Limited Edition (A)	Chassis No:	WAUZZZF4XKA104808
Reg. Date:	11/02/2020 (Man. Year: 2019)	Odometer:	9188 km
Colour:	Silver		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$132,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,234.00	8,200.50	11,033.50	57.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,322.00	3,072.00	6,250.00	67.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>28,556.00</b>	<b>11,272.50</b>	<b>17,283.50</b>	<b>60.52</b>
<b>- Excess (S\$)</b>	<b>550.00</b>	<b>550.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>28,006.00</b>	<b>10,722.50</b>	<b>17,283.50</b>	<b>61.71</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,960.42</b>	<b>750.58</b>	<b>1,209.84</b>	<b>61.71</b>
<b>Nett Amount (S\$)</b>	<b>29,966.42</b>	<b>11,473.08</b>	<b>18,493.34</b>	<b>61.71</b>

### INSPECTION

Date of Assignment:	21/01/2021		
Date Inspected:	20/01/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Cracked	71.00 FS	*28.16 FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	210.00 FS	*167.60 FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Cracked	63.00 FS	*50.08 FS
7	1		*RADIATOR GRILLE	Not Necessary	1,332.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cracked	804.00 FS	*85.30 FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	124.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	38.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
15	1		*LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
16	2		*LOCK CARRIER BRACKET SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
17	1		*HORN - RH LOW TONE	Not Necessary	126.00 FS	*- FS
18	1		*SPRING SHACKLE - RH	Not Necessary	29.00 FS	*- FS
19	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Cut	484.00 FS	*193.60 FS
20	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
21	1		*FRONT FENDER - RH	Repair	767.00 FS	*- FS
22	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
23	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	72.00 FS	*- FS
24	1		*FRONT FENDER BRACKET - RH	Not Necessary	35.00 FS	*- FS
25	1		*FRONT FENDER BRACE - RH	Not Necessary	118.00 FS	*- FS
26	1		*WHEEL HOUSING LINER - RH	Not Necessary	241.00 FS	*- FS
27	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	233.00 FS	*- FS
28	1		*WHEEL SPOILER - RH	Cracked	73.00 FS	*58.40 FS
29	1		*WHEEL SPOILER TRIM - RH	Missing	36.00 FS	*28.56 FS
30	1		*STONE CHIP GUARD - RH	Not Necessary	51.00 FS	*- FS
31	1		*TOP FENDER LEDGE COVER - UPPER	Not Necessary	31.00 FS	*- FS
32	1		*TOP FENDER LEDGE COVER - LOWER	Not Necessary	23.00 FS	*- FS
33	1		*BONNET IMPACT PROTECTION - CENTRE	Not Necessary	28.00 FS	*- FS
34	1		*BONNET IMPACT PROTECTION - LH	Not Necessary	28.00 FS	*- FS
35	1		*BONNET IMPACT PROTECTION - RH	Not Necessary	28.00 FS	*- FS
36	1		*LED HEADLIGHT - RH	Cut	7,693.00 FS	*6,154.40 FS
37	1		*LIFT CYLINDER - RH	Not Necessary	210.00 FS	*- FS
38	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	93.00 FS	*- FS
39	1		*LOCK CARRIER	Not Necessary	1,016.00 FS	*- FS
40	1		*COOLANT REGULATOR SUPPORT	Not Necessary	38.00 FS	*- FS
41	1		*READY MIX COOLANT	Not Necessary	179.00 FS	*- FS
42	1		*RADIATOR AIR GUIDE - OUTER	Not Necessary	28.00 FS	*- FS
43	1		*RADIATOR AIR GUIDE - INNER	Not Necessary	12.00 FS	*- FS
44	1		*FRONT BUMPER BRACKET - RH	Not Necessary	228.00 FS	*- FS
45	1		*PRESSURE HOSE - RH	Not Necessary	357.00 FS	*- FS
46	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
47	1		*SUNDRIES	Necessary	300.00 FS	*4.80 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **19,234.00**    **8,200.50**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	0.00
3	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	500.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET	New	2,900.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,322.00</b>	<b>3,072.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >