

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21000985/AQD3E2

Date: 12/05/2021

REFERENCE

Insured/Claimant:	ACW HOLDINGS PTE LTD	Policy No:	2070149996	
Date of Loss:	16/01/2021	Nature of Claim:	OD	Claim No: 8036013145SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV9077A	Engine No:	DAX061683
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Chassis No:	WAUZZZFYL2005422
Reg. Date:	27/10/2020 (Man. Year: 2019)	Odometer:	6523 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$215,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,457.00	3,844.32	25,612.68	86.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,892.00	4,082.00	7,810.00	65.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,349.00	7,926.32	33,422.68	80.83
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	40,349.00	6,926.32	33,422.68	82.83
+ GST 7.00/7.00% (S\$)	2,824.43	484.84	2,339.59	82.83
Nett Amount (S\$)	43,173.43	7,411.16	35,762.27	82.83

INSPECTION

Date of Assignment:	21/01/2021		
Date Inspected:	20/01/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,929.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	293.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP - LH	Not Necessary	38.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	113.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	173.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	39.00 FS	*30.48 FS
7	1		*FRONT FENDER - LH	Dented	1,427.00 FS	*1,141.60 FS
8	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
9	1		*FRONT FENDER BRACE - LH	Bent	225.00 FS	*179.60 FS
10	1		*FRONT FENDER BRACKET - LH	Not Necessary	18.00 FS	*- FS
11	1		*TOP FENDER LEDGE COVER - INNER	Cracked	31.00 FS	*24.64 FS
12	1		*TOP FENDER LEDGE COVER - OUTER	Not Necessary	40.00 FS	*- FS
13	1		*WHEEL HOUSING LINER - LH	Not Necessary	278.00 FS	*- FS
14	1		*WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	38.00 FS	*- FS
15	1		*JOINTED SHAFT COVER - LH	Not Necessary	37.00 FS	*- FS
16	1		*WHEEL SPOILER - LH	Not Necessary	162.00 FS	*- FS
17	2		*FRONT WHEEL COVER - LH / RH	N/S Deformed / O/S Necessary	1,264.00 FS	*1,011.20 FS
18	1		*FRONT DOOR - LH	Repair	4,085.00 FS	*- FS
19	1		*FRONT DOOR OUTER SEAL - LH	Not Necessary	205.00 FS	*- FS
20	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
21	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
22	1		*FRONT DOOR CATCH	Not Necessary	146.00 FS	*- FS
23	1		*FRONT DOOR COVER - LH	Not Necessary	790.00 FS	*- FS
24	1		*HEADLIGHT MOUNTING - LH	Not Necessary	118.00 FS	*- FS
25	1		*LED HEADLIGHT - LH	Not Necessary	8,191.00 FS	*- FS
26	1		*FRONT ALUMINIUM RIM - LH	Cut	1,821.00 FS	*1,456.80 FS
27	1		*FRONT WISHBONE LINK - LH	Not Necessary	539.00 FS	*- FS
28	1		*SUSPENSION GUIDE	Not Necessary	943.00 FS	*- FS
29	2		*UPPER GUIDE - LH FRONT / REAR	Not Necessary	720.00 FS	*- FS
30	1		*WHEEL BEARING HOUSING - LH	Not Necessary	1,136.00 FS	*- FS
31	1		*SWIVEL JOINT	Not Necessary	193.00 FS	*- FS
32	1		*WHEEL HUB	Not Necessary	479.00 FS	*- FS
33	1		*DOUBLE ANGLED BALL BEARING	Not Necessary	246.00 FS	*- FS
34	1		*SUSPENSION FORKS - LH	Not Necessary	366.00 FS	*- FS
35	1		*COUPLING ROD	Not Necessary	127.00 FS	*- FS
36	1		*GAS SHOCK ABSORBER	Not Necessary	1,483.00 FS	*- FS
37	1		*TIE ROD END - LH	Not Necessary	197.00 FS	*- FS
38	3		*BONNET IMPACT PROTECTION - LH / RH / CENTRE	Not Necessary	84.00 FS	*- FS
39	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 29,457.00 3,844.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
4	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY	New	1,800.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,000.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR, DOOR COVER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS	New	5,100.00	2,050.00
7	TO RENEW LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT	New	520.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			11,892.00	4,082.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >