

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III20010078/GTF3E2-1

Date: 28/01/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015		
Claimant Vehicle No :	SKV2830L	Insured Vehicle No :	SHB6235U		
Date of Loss:	12/09/2020	Nature of Claim:	TP	Claim No:	MCT20090216

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV2830L		
Make & Model:	TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG 2WD (A)	Engine No:	3ZRB608262
Reg. Date:	09/09/2015 (Man. Year: 2015)	Chassis No:	ZSU600052118
Colour:	White	Odometer:	75619 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,411.75	2,196.47	3,215.28	59.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,767.60	1,140.00	627.60	35.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,179.35	3,336.47	3,842.88	53.53
Approved Total (Overridden) (S\$)		2,650.00		
Nett Amount (S\$)	7,179.35	2,650.00	4,529.35	63.09

INSPECTION

Date of Assignment:	21/01/2021		
Date Inspected:	30/11/2020	Inspected At:	No 68 Kaki Bukit Ave 6 #04-11 @KB Repairer : Triple-t Automobile (HQ)
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jan 2021)	
Parts:	N/A	TOYOTA HARRIER 2.0 2.0 PREMIUM AT AIRBAG 2WD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV2830L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (ORIGINAL)	Deformed / Cut	1,024.50 FL	*1,024.50 FL
2	1		*REAR END PANEL	Repair	758.90 FL	*- FL
3	1		*REAR EXHAUST PIPE	Rebuild	1,425.50 FL	*- FL
4	1		*REAR BUMPER SPONGE	Damaged	112.50 FL	*112.50 FL
5	2		*REAR EXHAUST PIPE HEADSEAL	Grazed	370.00 FL	*278.30 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	55.00 FS	*35.00 FS
7	1		*REAR BUMPER LOWER (BODYKIT)	Damaged	677.40 FS	*400.00 FS
8	1		*REAR BUMPER LOWER LID (BODYKIT)	Holder Torn	785.00 FS	*500.00 FS
9	1		*REAR BUMPER DIFFUSER (BODYKIT)	Serviceable	845.80 FS	*- FS
10	1		*REVERSE SENSOR	Malfunction	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,334.60	2,550.30
- List Item Discount on L Items 25.00/25.00% (S\$)	922.85	353.83
Total Parts (S\$)	5,411.75	2,196.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	672.00	500.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL. (FRONT DOOR, SIDE SKIRT, BONNET, FRONT BUMPER / LOWER LID, FRONT FENDER)	New	700.00	600.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	0.00
4	REMOVE AND REBUILD EXHAUST SYSTEM	New	90.00	0.00
5	REMOVE AND REPLACE REAR REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	81.60	40.00
6	SPECIALIST CHARGES - DIGNOSTIC FAULT CODE / RESET	New	150.00	0.00
7	WIRING AND BULB CHECKING	New	24.00	0.00
Gross Labour Cost (\$\$)			1,767.60	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >