

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Oct 2020 16:54 Edit Reg		21 Jan 2021 00:00 Edit Adj Rpt	S\$1,300.00 Edit Estimates	S\$1,300.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	MOHAMED IQBAL HAIDER ALI , ID: S1668498H		
Main Claimant:	MUHAMMAD FAZIL BIN ZAILANI		
Vehicle Reg. No.:	SJF7884U	Date of Loss:	23/09/2020 12:00 - :59 [147 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MPC2020D0001843	Policy/Cover Note No.:	D20MPC0000804
Vehicle Reg. No. (Insured):	SKG1132D	Policy No. (Claimant):	MT/00646812/01
		Excess:	
Repairer:	Garage 13 Pte. Ltd. (HQ) 8 Kaki Bukit Avenue 4, #03-46 Premier, 415875 Kaki Bukit - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 25/01/2021]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*SJF7884U (MPC2020D0001843)
[SKG1132D]
TP
MUHAMMAD FAZIL BIN ZAILANI
Sep 23 2020 12:00PM
[MOHAMED IQBAL HAIDER ALI]
Garage 13 Pte. Ltd.

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/10/20 21:44	General View	 Load JPG	
2	13/10/20 21:44	General View	 Load JPG	
3	13/10/20 21:44	General View	 Load JPG	
4	13/10/20 21:44	Odometer Reading	 Load JPG	
5	13/10/20 21:44	Chassis Number	 Load JPG	
6	13/10/20 21:44	General View	 Load JPG	
7	13/10/20 21:44	General View	 Load JPG	
8	13/10/20 21:44	General View	 Load JPG	
9	13/10/20 21:44	General View	 Load JPG	
10	13/10/20 21:44	General View	 Load JPG	
11	13/10/20 21:44	General View	 Load JPG	
12	13/10/20 21:44	General View	 Load JPG	
13	13/10/20 21:44	General View	 Load JPG	
14	13/10/20 21:44	General View	 Load JPG	
15	13/10/20 21:44	General View	 Load JPG	
16	13/10/20 21:44	General View	 Load JPG	
17	13/10/20 21:44	General View	 Load JPG	
18	13/10/20 21:44	General View	 Load JPG	
19	13/10/20 21:44	General View	 Load JPG	
20	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
21	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
22	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
23	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
24	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
25	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
26	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
27	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
28	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
29	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
30	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
31	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
32	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
33	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
34	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	
35	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
37	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
38	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
39	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
40	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
41	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
42	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
43	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
44	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
45	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
46	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
47	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
48	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
49	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
50	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
51	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
52	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
53	13/10/20 21:45	Photographs of Damaged Parts	 Load JPG	☒
54	13/10/20 21:45	Photo After Spray	 Load JPG	☒
55	13/10/20 21:45	Photo After Spray	 Load JPG	☒
56	13/10/20 21:45	Photo After Spray	 Load JPG	☒
57	13/10/20 21:45	Photo After Spray	 Load JPG	☒
58	13/10/20 21:45	Photo After Spray	 Load JPG	☒
59	13/10/20 21:45	Photo After Spray	 Load JPG	☒
60	13/10/20 21:45	Photo After Spray	 Load JPG	☒
61	13/10/20 21:45	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/10/20 15:44	ACKNOWLEDGEMENT EMAIL TO III DD 02.10.2020	 Load PDF	
2	02/10/20 15:44	TP GIA REPORT	 Load PDF	
3	05/10/20 09:19	Status of Driving Licence DD 05.10.2020	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/10/20 08:30	Singapore Accident Statement	 Load PDF	
2	21/01/21 09:19	Letter of Demand from Third Party TPD LOD FROM GARAGE 13 PTE LTD (SJF7884U)	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III20010600/ETF3S2-1**Date:** 08/02/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0000804
Claimant Vehicle No :	SJF7884U	Insured Vehicle No :	SKG1132D
Date of Loss:	23/09/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0001843

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF7884U	Engine No:	L15A26801447
Make & Model:	HONDA CITY, 1.5 CVT (A)	Chassis No:	MRHGD86908P010114
Reg. Date:	11/06/2008 (Man. Year: 2007)	Odometer:	132057 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,869.16	663.52	3,205.64	82.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.50	960.00	820.50	46.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,649.66	1,623.52	4,026.14	71.26
Approved Total (Overridden) (\$\$)		1,300.00		
(\$\$)	5,649.66	1,300.00	4,349.66	76.99
+ GST 7.00/7.00% (\$\$)	395.48	91.00	304.48	76.99
Nett Amount (\$\$)	6,045.14	1,391.00	4,654.14	76.99

INSPECTION

Date of Assignment:	21/01/2021		
Date Inspected:	08/10/2020	Inspected At:	Garage 13 Pte. Ltd 8 Kaki Bukit Avenue 4, #03-46 Premier Singapore 415875
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2021)
Parts:	143	HONDA CITY 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF7884U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	458.50 FL	*- FL
2	1		*BOOT LID TOP LOCK	Serviceable	63.80 FL	*- FL
3	1		*BOOT LID WEATHERSTRIP	Refix	87.90 FL	*- FL
4	1		*BOOT LID LOWER LOCK	Serviceable	12.70 FL	*- FL
5	2		*BOOT LID HINGE	Refix	86.40 FL	*- FL
6	1		*BOOT LID LOGO	Serviceable	28.50 FL	*- FL
7	1		*BOOT LID EMBLEM CITY	Serviceable	32.00 FL	*- FL
8	1		*BOOT LID EMBLEM I-DSI	Serviceable	31.00 FL	*- FL
9	2		*BOOT LID REFLECTOR	Intact	370.00 FL	*- FL
10	1		*REAR EXHAUST PIPE	Rebuild	558.70 FL	*- FL
11	1		*REAR BUMPER	Deformed	598.40 FL	*372.00 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	45.40 FL	*45.40 FL
13	2		*REAR TAIL LAMP	Serviceable	509.60 FL	*- FL
14	2		*REAR TAIL LAMP PANEL	Repair	118.80 FL	*- FL
15	2		*REAR TAIL LAMP LOWER METAL BRACKET	Serviceable	59.40 FL	*- FL
16	1		*REAR END PANEL	Repair	419.60 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Cracked	112.00 FL	*112.00 FL
18	1		*REVERSE SENSOR	Malfunction	280.00 FS	*200.00 FS
19	1		*REAR BUMPER LOWER LID	Not Necessary	650.00 FS	*- FS
20	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	15.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,587.70	769.40
- List Item Discount on L Items 20.00/20.00% (\$)	718.54	105.88
Total Parts (\$)	3,869.16	663.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS.	New	855.00	400.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.	New	700.00	500.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS.	New	50.00	30.00
4	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY.)	New	22.50	0.00
5	REMOVE AND REBUILD REAR EXHAUST SYSTEM.	New	76.50	0.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING.	New	76.50	30.00
Gross Labour Cost (\$\$)			1,780.50	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >